

ASS. REC. BY:

REF: CS/AIG 20003923/ AS-Bed Special Instruction:

SUSIAJOL: Chao Qiang ASSIGNMENT (Office)From (Person): Eric Tuo Wei Hong of AIG Date/Time: 12.3.2020 2.57p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 6725R Insured: GBJ 14692at Workshop m/s 833 motorSPORTS Tel: 8332 2833of 160 Sin Ming Drive #02-09 sin ming ParkwayPolicy No: _____ Claim No: 886506641084003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.3.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS upDate/Time: 12.3.2020 2.57p.m H.O.D. Endorsement: _____Person Contacted: 34 Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJM 6725R - CCL / AIG 1007432 / UQ 24 EN Don - 12/04/2020</u>
	<u>GBJ 14692 - X</u>

PRS

ASS. REC. BY:

REF:

A1G

PR5

ASSIGNMENT

C-2024)

From:

Date:

12.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJM 6725R

at Workshop m/s 833 Motorsports

of 160 Sin Ming Drive #02-09 Botany

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$25K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJM 6725R

Regn:

13 Jan 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Passenger Station Wagon

Make:

Fiat Doblo

1.4 c.c

1368

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

228177

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA 2230000 5587249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 06-03-20

D.O.I. 12-03-20

Survey held at

W/S

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S TA

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COT: 978

RECEIVED 16 MAR 2020

Date/Time, File Pass to?

16/03/20

1) Typist

Date/Time, File Return to?

2)

Rep. Format: PRS

Lump Sum / L.B.J. (F)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

180

11

191

PRE-REPAIR INSPECTION REQUEST – SJM6725R vs GBJ1469Z (OI) on D.O.A.: 06/03/2020

From: Teo, Ericweihong
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Subramaniam, Divyashni
Sent: Thursday, 12 March, 2020 2:52:33 PM

Hi,

Please refer to the enclosed request from **Advance Law LLC**.

Claim no : 8865066410SG003
Case Owner : BERNARD LER JI QIAN

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Xing Guo Qiang** as Single Joint Expert as requested.*

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II
Singapore– Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: jiayun.lee@advlawllc.com <jiayun.lee@advlawllc.com>
Sent: Thursday, March 12, 2020 9:35 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>; max@advlawllc.com; elton.tan@advlawllc.com; eldred@833motorsports.com; jiayun.lee@advlawllc.com
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ1469Z AND SJM6725R ON 06/03/2020

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above.

We would like to request Xing Guo Qiang from LKK Auto Consultants Pte Ltd being the surveyor.

Kindly let us hear from you within the next 2 days as per the NIMA protocol, failing which we will proceed with the necessary.

Best Regards

J Y

From: Hor, Yinrul
Sent: Wed, 11 Mar 2020 08:29:49 +0000
To: 'jiayun.lee@advlawllc.com'

Gc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Subramaniam, Divyashni, Teo,
 Ericweihong.max@advlawllc.com, elton.tan@advlawllc.com, eldred@833motorsports.com
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ1469Z AND SJM6725R
 ON 06/03/2020

Without Prejudice

Your Reference : FT/smc/101902/PD (833)
 Our Reference : GBJ1469Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster |

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: Jy [mailto:jayun.lee@advlawllc.com]

Sent: Wednesday, March 11, 2020 4:12 PM

To: AIG SGP, Claims-Survey

Cc: max@advlawllc.com; elton.tan@advlawllc.com; eldred@833motorsports.com

Subject: [EXTERNAL] Our Ref: FT/smc/101902/PD (833) SJM6725R, YOUR INSURED CAR: GBJ1469Z

This message is from an external sender; be cautious with links and attachments.

Dear Sir/ Ms,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURUSANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES.

We act for who has been instructed with motorcar no. **SJM6725R** with instructions to repair the same.

Accident on : 06/03/2020 @ 17:00 HRS, ALONG PIE TOWARDS CHANGI NEAR EXIT 34

Please be informed that the said vehicle can be inspected at:-

Venue : 833 MOTORSPORTS
160 SIN MING DRIVE
#02-09 SIN MING AUTOCITY
SINGAPORE 575722

PIC : ELDRED

Contact No : 8332 2833

Thank you.

Best Regards

JY

ADVANCE
ADVANCE LAW LLC

430 Lorong 6 Toa Payoh #11-01 OrangeTee Building Singapore 319402
Tel: (65)6323 5488 | Fax: (65)6258 5521

****WARNING:** Computer viruses can and/or may be transmitted via email. Kindly check and ensure that all emails received from our firm ends with the domain @advlawllc.com before acting on them. When and/or if unsure, please contact us to verify. Please note that the company accepts no liability for any damage caused by any virus transmitted by this email.

STRICTLY CONFIDENTIAL

This message, its contents and any files transmitted with it are intended SOLELY for the addressee(s) and may be legally privileged and/or confidential. Access by any other party is unauthorised without the express written permission of the sender. If you have received this message in error, you may not copy or use the contents, attachments or information in any way. Please destroy it and contact us immediately via e-mail return. This message has been prepared using information believed by the author to be reliable and accurate; we make no warranty as to its accuracy or completeness. We do not accept responsibility for changes made to this message after it was sent.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information	
Owner ID Type:	Singapore NRIC
Owner ID:	353B
Vehicle Details	
Vehicle No.:	SJM6725R
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2020
Vehicle Make:	FIAT
Vehicle Model:	DOBLO PANORAMA 1.4 M ACTIVE
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	350A10004157449
Chassis No.:	ZFA22300005587249
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$15,231.00
Original Registration Date:	13 Jan 2009
First Registration Date:	13 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$3,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2024
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$9,978.00
Total Rebate Amount:	\$9,978.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Mar 2020

OK

**Best Car Repair Workshops in Singapore**

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

SEARCH Price Range Depreciation > 10 yrs Vehicle Type

Home > Used Cars > Classic Credit Pte Ltd > Fiat Doblo Panorama 1.4M Active (COE till 01/2023)

Fiat Doblo Panorama 1.4M Active (COE till 01/2023)

[Overview](#)[Financial](#)[Insurance](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**CLASSIC CREDIT**SAGARMART'S PREMIUM DEALER
2013 / 2014 / 2015 / 2016 / 2017

Price	\$20,800		
Depreciation	\$7,210 /yr	Reg Date	31-Jan-2008 (2yrs 10mths 17days COE left)
Mileage	N.A.	Manufactured	2007
Road Tax	\$730 /yr	Transmission	Manual
Dereg Value	\$12,397 as of today (change)	OMV	\$15,761
COE	\$21,485	ARF	\$17,338
Engine Cap	1,368 cc	Power	57.0 kW (76 bhp)
Curb Weight	1,230 kg	No. of Owners	2

Type of Vehicle MPV

Description

Normal Passenger Unit. Normal Plate Usage. Good For Pte Hire. 5 Seater With Huge Boot Space. Up To 100% Flexible Loan Available. Very Good Condition. Selling Cheap! Hurry! View Now. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Meet Our Friendly Consultant For An Non-Obligation Advised.

Category

COE Car

Status

Available

Resources**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

Posted on: 27-Feb-2020 | Last Updated on: 12-Mar-2020

Upfront Payment[more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$6,240 (change)	Maximum 70% Loan
1st Instalment	\$474	Based on 3.75% interest rate
Insurance	\$1,069 onwards (Get a quote)	
Compare	Extra 15% Off for MINDEF, MHA & POGIS policyholders	



Shortlist Compare Add note
 Report Error More Actions

Seller Information**Classic Credit Pte Ltd**

58 vehicles for sale, 21 sold in past 3 mths

61 Ubi Avenue 2 #03-11, #03-18, #04-06
Automobile Megamart
Tel: 68412076 / 68481203 / 68414849
Search cars nearby

Mike 96365270
Roland 97479331
Mr Chen 90044461

[Contact Seller](#)


Why Classic Credit?
Simple, Premium & Hassle-Free

- Flexible Loan
- High Value for Trade In Vehicle
- Friendly and Professional Service
- Provide Lowest Interest Rate in Town
- Wide Range of Quality Pre-Owned Cars
- 100% Deposit Refund for Unapproved Loan
- Package With Unrivalled Warranty Complete with Certificate and Test Report

USED CAR LIST COMPANY INFO CUSTOMER TESTIMONIALS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2020 13:15
Date Of Accident	06/03/2020 17:00
Exact Location Of Accident	ALONG PIE TOWARDS CHANGI NEAR EXIT 34
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM6725R
Insured/Policyholder	
Name Of Registered Owner	KAMIDAH BINTE KASIMUN
NRIC No	SXXXX353B
Email Address	MD_ASRUL@HOTMAIL.SG
Mobile Phone No	(LOCAL) +65-94240669
Alternative Phone No	OFFICE-94240669

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO PANORAMA-1.4 ACTIVE (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00589107/01
Cover Note Number	

Driver

Name of Driver	MOHAMED ASRUL BIN ABU BAKAR
NRIC No	SXXXX886J
Date Of Birth	18/08/1990
Occupation	INDOOR
Date Of Driving Pass	20/04/2016
Driving Experience	3 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94240667
Fax Number	
Contact Number	
Email Address	MD_ASRUL@HOTMAIL.SG

Address	APT BLK 285B TOH GUAN ROAD #02-94
Postcode	602285
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO POLICE REPORT NO: T/20200307/2061 *I WISH TO STATE THAT ON THE 7TH MARCH 2020, I WENT TO THE ACCIDENT REPORTING CENTER BUT DUE TO MY PREFERRED WORKSHOP BEING CLOSED, I COULD NOT PRODUCE THE PICTURES OF THE DAMAGES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ1469Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GOVINDASAMY SATHISHKUMAR
NRIC/Passport Number	
Contact Number	91361889
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MOHAMED ASRUL BIN ABU BAKAR

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to Police Report No T/20200307/2061

* I wish to state that on the 7th March 2020, I went to the accident reporting centre but due to my preferred workshop being closed, I could not produce the pictures of the damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200307/2081

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

1 of 3

Report No. T/20200307/2081

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/03/2020 14:28		Vide Report No.:		Station Diary No.: 63	
Informant's Particulars					
Name of Informant: MOHAMED ASRUL BIN ABLI BAKAR		Address: APT BLK 285B TOH GUAN ROAD #02-94 SINGAPORE 602285			
ID Type / ID No. NRIC NO / S9028885J		Contact No. Home/Office:		Mobile: 94240567	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 29	Date of Birth: 18/08/1990	Type of Informant: Driver		
Race: Malay		Language:		Institution / School Name:	
Occupation: technician		Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/03/2020 17:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Right before Hong Kah Flyover along PIE towards Changi before Corporation exit				
Weather: Clear	Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	


Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBJ1469Z	Lorry	TOYOTA		Silver	Seriously Damaged	0
SJM6725R	Car	FIAT		Grey	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200307/2061

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

2 of 3

Report No. T/20200307/2061

CONTINUATION OF REPORT

Driver			
Name	MOHAMED ASRUL BIN ABU BAKAR	ID No.	S9029886J
Related Vehicle	SJM6725R (Car)	Contact No.	94240667
Hospital/Clinic	FOO AND ONG FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 2B,2A,2.3 Date of Expiry: NIL
Date Treatment	06/03/2020	Date Discharge	06/03/2020
No. of Days granted Medical Leave	04	Degree of Injury	Serious

Brief Details.

On the 06/03/2020 at about 1700hrs, I was travelling along HongKah flyover PIE towards Changi before corporation exit on the 1st lane. I was travelling straight ahead in my car (SJM6725R).

Suddenly, a lorry driver (GBJ1469Z) turned right into my lane as he was trying to avoid a trailer which was turning into his lane from the 3rd lane. As a result, my car front left side was damaged seriously and his lorry front right was also damaged. The lorry driver is namely Govindasamy Sathishkumar, HP:91361889).

Subsequently, the EMAS crew came and tow my vehicle away and my friend came and sent me back. Later that night at about 2400hrs, I felt pain in my neck, shoulder and back and I went to a clinic to consult doctor and was given 4 days MC.

I wish to state that my car has footage of how the accident occurred.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200307/2061

Police Station Of Origin:
Jurong East N.P.C.
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

3 of 3

Report No. T/20200307/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 TAN WEE JIAN

[Signature]

Signature Of Informant:

[Signature]

Signature Of Interpreter:

Not applicable

Date/Time

07/03/2020 14:28

Officer in Charge Of Case:

TP / AEIT /

SI ANG YLTING STEPHANIE

Control No. 65476414

Authentication Stamp

NP168

[Signature]

Classification Of Case:

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	cut		
1005	992341	Frt Bumper Clips	dec		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	ph	2	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	CRA		
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT		
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Headlamp Garnish	CRA		
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BT		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SIM6725R

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box	Re		
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	buc		
1097	995072	Frt LH Fender Inner Panel	Repair		
1098	995147	Frt LH Fender Lamp	CRA		
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	Re		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	W/S		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre	W/S		
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(01)Hole (02)Dented (03)Distorted (04)Cracked (05)Cut (06)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber	BT	/	
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	BT	/	
1376	995199	Frt LH Knuckle Arm Bearing	BT	/	
1377	995178	Frt LH Lower Arm	BT	/	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod	BT	/	
1380	995143	Frt LH Drive Shaft	BT	/	
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion	BT	/	
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame	BT	/	
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

Vehicle No: STM 6725R

[illegible]

No of Items: _____ Assessor: _____

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2020 Edit Reg		12 Mar 2020 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	YUAN LI ELECTRICAL ENGINEERING PTE LTD, Co. Reg. No.: 201215194D								
Main Claimant:	KAMIDAH BINTE KASIMUN								
Vehicle Reg. No.:	SJM6725R	Date of Loss:	06/03/2020 17:00 - :59 [133 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8865066410SG	Policy/Cover Note No.:	2070009683 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBJ1469Z	Policy No. (Claimant):							
		Excess:							
Repairer:	833 Motorsports Pte Ltd () 160 SIN MING DR #02-09,SIN MING AUTOCITY, 575722 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/03/2020]								
Claimant's Solicitor:	ADVANCE LAW LLC - Tel: 63235488								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJM6725R (8865066410SG)
[GBJ1469Z]**

TP

KAMIDAH BINTE KASIMUN

Mar 6 2020 5:00PM

**[YUAN LI ELECTRICAL ENGINEERING PTE LTD]
833 Motorsports Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	16/03/20 12:00	General View														Load JPG	☒			
2	16/03/20 12:00	General View														Load JPG	☒			
3	16/03/20 12:00	General View														Load JPG	☒			
4	16/03/20 12:00	General View														Load JPG	☒			
5	16/03/20 12:00	General View														Load JPG	☒			
6	16/03/20 12:00	General View														Load JPG	☒			
7	16/03/20 12:00	General View														Load JPG	☒			
8	16/03/20 12:00	General View														Load JPG	☒			
9	16/03/20 12:00	General View														Load JPG	☒			
10	16/03/20 12:00	General View														Load JPG	☒			
11	16/03/20 12:00	General View														Load JPG	☒			
12	16/03/20 12:00	General View														Load JPG	☒			
13	16/03/20 12:00	General View														Load JPG	☒			
14	16/03/20 12:00	General View														Load JPG	☒			
15	16/03/20 12:00	General View														Load JPG	☒			
16	16/03/20 12:00	General View														Load JPG	☒			
17	16/03/20 12:00	General View														Load JPG	☒			
18	16/03/20 12:00	General View														Load JPG	☒			
19	16/03/20 12:00	General View														Load JPG	☒			
20	16/03/20 12:00	General View														Load JPG	☒			
21	16/03/20 12:00	General View														Load JPG	☒			
22	16/03/20 12:00	General View														Load JPG	☒			
23	16/03/20 12:00	General View														Load JPG	☒			
24	16/03/20 12:00	General View														Load JPG	☒			
25	16/03/20 12:00	General View														Load JPG	☒			
26	16/03/20 12:00	General View														Load JPG	☒			
27	16/03/20 12:00	General View														Load JPG	☒			
28	16/03/20 12:00	General View														Load JPG	☒			
29	16/03/20 12:00	General View														Load JPG	☒			
30	16/03/20 12:00	General View														Load JPG	☒			
31	16/03/20 12:00	General View														Load JPG	☒			
32	16/03/20 12:00	General View														Load JPG	☒			
33	16/03/20 12:00	General View														Load JPG	☒			
34	16/03/20 12:00	General View														Load JPG	☒			
35	16/03/20 12:00	General View														Load JPG	☒			
36	16/03/20 12:00	General View														Load JPG	☒			
37	16/03/20 12:00	General View														Load JPG	☒			

Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	16/03/20 12:00	General View	1	Load JPG	☒
39	16/03/20 12:00	General View	1	Load JPG	☒
40	16/03/20 12:00	General View	1	Load JPG	☒
41	16/03/20 12:00	General View	1	Load JPG	☒
42	16/03/20 12:00	General View	1	Load JPG	☒
43	16/03/20 12:00	General View	1	Load JPG	☒
44	16/03/20 12:00	General View	1	Load JPG	☒
45	16/03/20 12:00	General View	1	Load JPG	☒
46	16/03/20 12:00	General View	1	Load JPG	☒
47	16/03/20 12:00	General View	1	Load JPG	☒
48	16/03/20 12:00	General View	1	Load JPG	☒
49	16/03/20 12:00	General View	1	Load JPG	☒
50	16/03/20 12:00	General View	1	Load JPG	☒
51	16/03/20 12:00	General View	1	Load JPG	☒
52	16/03/20 12:00	General View	1	Load JPG	☒
53	16/03/20 12:00	General View	1	Load JPG	☒
54	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
55	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
56	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
57	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
58	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
59	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
60	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
61	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
62	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
63	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
64	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
65	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
66	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
67	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
68	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
69	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
70	17/03/20 16:19	Dismantled Parts	1	Load JPG	☒
71	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
72	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
73	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
74	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
75	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
76	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
77	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
78	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
79	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
80	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
81	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
82	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
83	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
84	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
85	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
86	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒
87	17/03/20 16:20	Dismantled Parts	1	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
89	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
90	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
91	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
92	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
93	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
94	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
95	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
96	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
97	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
98	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
99	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
100	17/03/20 16:20	Dismantled Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/20 11:58	TP GIA REPORT.pdf	 Load PDF	
2	16/03/20 11:58	POLICE REPORT.pdf	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/03/20 12:31	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20003923/GSF3E2

Date: 19/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070009683
Claimant Vehicle No : SJM6725R **Insured Vehicle No :** GBJ1469Z
 Date of Loss: 06/03/2020 Nature of Claim: TP Claim No: 8865066410SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM6725R**
 Make & Model: FIAT DOBLO PANORAMA, 1.4 Active (M) Engine No: 350A10004157449
 Reg. Date: 13/01/2009 (Man. Year: 2008) Chassis No: ZFA22300005587249
 Colour: Grey Odometer: 228177 km
 Engine Capacity: 1368 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/03/2020
 Date Inspected: 12/03/2020 Inspected At: 833 Motorsports Pte Ltd
 160 SIN MING DR #02-09, SIN MING
 AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*-F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*-F
4	1		*FRT LH BUMPER FOG LAMP	Cracked	0.00 F	*-F
5	1		*FRT SUPPORT PANEL	Bent	0.00 F	*-F
6	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*-F
7	1		*FRT LH HEADLAMP GARNISH	Cracked	0.00 F	*-F
8	1		*BONNET	Bent	0.00 F	*-F
9	1		*FUSE BOX	Deformed	0.00 F	*-F
10	1		*FRT LH FENDER	Buckled	0.00 F	*-F
11	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*-F
12	1		*FRT LH FENDER LAMP	Cracked	0.00 F	*-F
13	1		*FRT LH FENDER INNER SHIELD	Deformed	0.00 F	*-F
14	1		*FRT LH WHEEL RIM	Distorted	0.00 F	*-F
15	1		*FRT LH TYRE	Punctured	0.00 F	*-F
16	1		*FRT LH DOOR	Repair	0.00 F	*-F
17	1		*FRT LH DOOR PROTECTOR	Scratched	0.00 F	*-F
18	1		*FRT LH DOOR WING MIRROR	Distorted	0.00 F	*-F
19	1		*FRT LH DOOR GLASS	Scratched	0.00 F	*-F
20	1		*FRT LH DOOR OUTER PILLAR	Buckled	0.00 F	*-F
21	1		*ROCKER PANEL LH	Repair	0.00 F	*-F
22	1		*FRT LH SHOCK ABSORBER	Bent	0.00 F	*-F
23	1		*FRT LH KNUCKLE ARM	Bent	0.00 F	*-F
24	1		*FRT LH KNUCKLE ARM BEARING	Bent	0.00 F	*-F
25	1		*FRT LH LOWER ARM	Bent	0.00 F	*-F
26	1		*FRT LH TIE ROD	Bent	0.00 F	*-F
27	1		*FRT LH DRIVE SHAFT	Bent	0.00 F	*-F
28	1		*STEERING RACK & PINION	Bent	0.00 F	*-F
29	1		*FRT SUB FRAME	Bent	0.00 F	*-F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >