



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SLV9429EMake & Model : VOLKSWAGEN TIGUANYear of Manufacture : 2014Chassis No. : WVGZZZ5NZFW053419Engine No. : CCZ470803

Policy No. : _____

Ins Company : _____

Excess : _____

Date of Accident : 19/01/2020Time of Accident : 08.35

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Contact No : _____

68485725 - JOHARI

Parts (a) Cost / List Price Items \$ 3,546.00Plus/Less 10% \$ 354.60Total of Cost / List \$ 3,191.40(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,191.40Labour (Appendix B) \$ 1,400.00Total Repair Cost \$ 4,591.40*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SLV9429E Case Owner : JOHARI - UBI

Make & Model : VOLKSWAGEN TIGUAN Year Manufacture : 2014

Chassis No : WVGZZZ5NZFW053419 Engine No : CCZ470803

HV : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHF BUMPER ARCH	1		\$ 594.00	Scr ✓		
2	LHF FENDER ARCH	1		\$ 1,776.00	Xm		
3	LHF FENDER	1		\$ 1,176.00	x(R)		
4	SPORT RIM ORIGINAL	1			Scr ✓		
5	TYRE (255/48R18)	4			Xm		
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____						
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

Tel: 68438723/68438736 FAX : 67436072

Vehicle No. : SLV9429E
Make & Model : VOLKSWAGEN TIGUAN

Case Owner : _____
Year of Manufacture : 2014

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (L/R)

23/03/2020 1530

Ram (L/R) @ L/R

88622778

2 repair days

L/S

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.