

ABS. REC. BY: Surveyor: Lim REF: CS3/A1419021202/Bq03-1<sup>02</sup>

From (Person) Meunier Bernard Ler ASSIGNMENT (Office) of A14 Date/Time: 12/03/2020

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ☒ WS/TP RES / OD RES / EVA / INV / MV / CT To Inspect Vehicle No: SLT 48E2Y Insured: SMD 6099B

at Workshop in/s of Eng Shing Mechanical Tel: 6453 7380

160 Sin Ming Drive # 06-21

Policy No: \_\_\_\_\_ Claim No: 376213646159

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 30/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 206pm 2/12/19 Person Contacted: Mr. Tan H.O.D. Endorsement: \_\_\_\_\_

Vehicle IN/OUT ☒

Date/Time	Action/Instruction
	1-31mm (X)
	SLT 48E2Y-X
	SMD 6099B-X
	Dismantle return - 05/12/19
	After patrol - 10/12/19
23/12/19	Submit PAR.
18/1/20	Submit LS \$3300, 5 days (Red \$3950, 54%.)

RECEIVED 19 MAR 2020

ALG

PRS

# ASSIGNMENT

Form

Date

4/12/19

Estimated Cost

GD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle At:

SLT 4882Y

at Workshop mis

Eng Shing Mechanical

of 160 Sin Ming Drive # 06-21

Insured

Policy No.

Claims No.

Sum Insured


Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value

65,000/2

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repair:

4

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Date

Person Contacted

Vehicle: IN / OUT

Veh No

SLT 4882Y

or Rego:

30/10/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

BAV

Colour

White

Sp Reading

47719

Eng No:

36079358537D5A

C No:

WBAIV72070V249858

Gen. Cond: Good (Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6 mm

R/Bal

6 mm

L/Bal

6 mm

L/Bal

6 mm

D.O.A

30/11/19

D.O.I

4/12/19

Survey held at

Eng Shing Mechanical

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED

AV 65,000/2

PV 42,571/2

NV 19,429/2

TOTAL LIN

6/12/19

Draw/Note File Photo(s)



Preli. Report

73/12/19



Final Report

Draw/Note File Photo(s)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp 15



Interview 15



Tech. Insp 15



Photostat 15

Survey Fee:

Transportation

2 x 15 = 30

Phone

Other

Total

191

120

11

191

Report Formed:

002

Temp. Date / P.E. / C.

## Nivitha (LKK Auto)

---

**From:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>  
**Sent:** Thursday, 12 March 2020 9:32 AM  
**To:** Admin A; Admin-D (LKKAuto)  
**Subject:** Paper Adjustment for 3762136461SG-003  
**Attachments:** 3762136461SG.pdf; 3762136461SG\_02\_03\_2020  
\_RULINGS\_JUDGMENTS\_SENTENCES\_J07729 -001.pdf

Dear LKK,

Please assist to complete paper adjustment for the above case.

Relevant documents are in Merimen.

Do let me know if further documents are required.

Thanks!

**Best Regards,**

**Bernard Ler**  
**AIG**  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

[Bernard-JQ.Ler@aig.com](mailto:Bernard-JQ.Ler@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7596

Email: absolute.app.svcs@gmail.com

**Vehicle Inspection Report**

To: Eng Jiat Cheng  
C/o: 160 Sin Ming Drive #06-21  
Sin Ming AutoCity (S) 575722

Date of report: 15.01.2020  
Date of request: 04.12.2019  
Date of inspection: 04.12.2019  
Date of accident: 30.11.2019  
Claim type: Third Party Claim

Report No: AAS/2019/587

**Particulars of affected vehicle:**

Registration no: SLT4882Y  
Make/Model: BMW 116d (A)  
Year of registration: 2015  
Colour: Pearl White

Odometer: 49719 km  
Engine Capacity: 1496 cc  
Engine no: 36079358B37D15A  
Chassis no: WBA1V72070V249858

**Condition of tires:**

Front Left: 6mm  
Make: Goodyear  
Rear Left: 6mm  
Make: Goodyear

Front Right: 6mm  
Make: Goodyear  
Rear Right: 6mm  
Make: Goodyear

Type of road wheel: Alloy [The above represent the remaining life of the tire thread]

**Pre-accident condition (Static tests only)**

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

**The Assignment**

The inspection was conducted at M/s. Eng Shing Mechanical Works  
160 Sin Ming Drive #06-21  
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

**Assessment**

Repairer's estimate:	\$ 12,122.00
Revised estimate:	\$ 9,032.00
Recommended reserve:	\$ 7,250.00 (Lump sum)

Estimated normal duration of repairs : 6 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
Mobile: 9688-0413 Fax: 6266-7596  
Email: absolute.app.svcs@gmail.com

Vehicle No: SLT4882Y

Report No: AAS/2019/587

W/O PREJUDICE

Point of impact

At the RHR portion. The RHR road wheel was also affected.

General description of damages

The rear bumper, RHR fender, RHR door, RHR road wheel, RHR undercarriages, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Eng Shing Mechanical Works as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$9,032.00

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$7,250.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 64 photographs.

Your Faithfully  
Absolute Appraisal Services Pte Ltd



Nicky Seah  
Automobile Appraiser  
MSAAA / MSMCTA



# ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SLT4882Y

Appraisal Schedule

Report No: AAS/2019/587

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est	
1	Rr bumper	1	Dented/Deformed	\$ 1,037.00	✓ \$ 1,037.00	BR ✓
2	Rr fender RH	1	Dented/Repair	\$ 1,490.00		
3	Rr door RH	1	Dented/Distorted	\$ 1,208.00	<sup>1200</sup> <del>\$ 1,208.00</del>	DD ✓
4	RH side skirt	1	Dented/Deformed	\$ 373.00	✓ \$ 373.00	WT ✓
5	Rr alloy rim (654) RH	1	Dented/Defaced	\$ 832.00	<sup>200</sup> <del>\$ 832.00</del>	R ✓
6	Rr shock absorber RH	1	Bent/Jammed	\$ 286.00	\$ 286.00	NDX
7	Rr wheel hub RH	1	Warped/Distorted	\$ 190.00	\$ 190.00	
8	Rr wheel bearing RH	1	Distorted/Necessary	\$ 161.00	\$ 161.00	NDX
9	Rr brake disc RH	1	Refit	\$ 411.00		
10	Rr wheel carrier RH	1	Bent/Distorted	\$ 1,226.00	\$ 1,226.00	NDX
11	Rr trailing arm RH	1	Bent	\$ 120.00	\$ 120.00	
12	Rr guide link RH	1	Bent	\$ 298.00	\$ 298.00	
13	Rr control arm RH	1	Bent	\$ 334.00	\$ 334.00	
14	Rr track strut RH	1	Bent	\$ 147.00	\$ 147.00	
15	Rr lower arm RH	1	Bent	\$ 360.00	\$ 360.00	
16	Rr stabilizer link RH	1	Refit	\$ 89.00		
List total:				\$ 8,562.00	\$ 6,572.00	2819.00
1	Rr tyre RH	1	Cut	80% \$ 300.00	<sup>50</sup> <del>\$ 240.00</del>	140.00 NDX
Special nett total:				\$ 300.00	\$ 240.00	
Parts Total:				\$ 8,862.00	\$ 6,812.00	2672.00



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**  
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722  
 Mobile: 9688-0413 Fax: 6266-7396  
 Email: absolute.app.svcs@gmail.com

Vehicle No: SLT4882Y

S/N Labour Description

Report No: AAS/2019/587

Repairer's Est Revised Est  
 \$ 80.00 \$ 50.00 *NNA*

1	Check lightings & wiring	\$ 80.00	\$ 50.00	<i>NNA</i>
2	To remove and reinstall rear interior trims for necessary repairs.	\$ 120.00	\$ 100.00	<i>50.00</i>
3	To transfer RHR door fittings.	\$ 120.00	\$ 120.00	<i>50.00</i>
4	To remove, check & replace RHR undercarriage parts.	\$ 300.00	\$ 220.00	<i>80.00</i>
5	Wheel alignment. 2x	\$ 150.00	\$ 120.00	<i>60.00</i>
6	To renew damaged parts. Repair, reform, realign all damaged area.	\$ 1,200.00	\$ 750.00	<i>600.00</i>
7	To conduct spray painting on replacement & affected area.	\$ 1,200.00	\$ 800.00	<i>600.00</i>
8	Anti rust.	\$ 90.00	\$ 60.00	<i>30.00</i>

Labour Total: \$ 3,260.00 \$ 2,220.00

The final adjusted lump sum amount is \$7,250.00

Grand Total: \$ 12,122.00 \$ 9,032.00

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

64 Photographs were taken at the time of inspection.

*Repair days 5*

*17/3/2020*

*L/S 3,300/-*

*Parts 2677.00*  
*SN —*  
*Labour 1470.00*  
*@20% 4147.00*  
*829.40*  
*3317.60*  
*TOTUM Lin*  
*17/3/2020*

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.

1. 2000年10月1日起，凡在我国境内销售货物的单位和个人，均应按销售额的一定比例缴纳增值税。

Source: <http://www.fishbase.org>.

Cover: Group 998, 10/10/2012

## SUMMARY

1084 I. V. Ivanov et al.

BANCALAT EMBROID.

10 Aug 2015

29 Apr 2020

1000

in order to work his/her permission.

in accordance with the licensing or other laws or regulations to drive or be disqualified by order of a Court of Law as a result of any  
 one Motor Vehicle

in connection with the Policyholder's business or profession.

© 2004 Wiley

connection:

Table 1.

Motor Vehicle (Third Party Risk and Compensation)

Act, 1967 (Malaysia), are not to be included under these

---

ASIANI PTE. LTD. 000000728431

26 Apr 2019 17:21 hrs

100

**Authorized Officer**

### Chart Exercise



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2019 15:46
Date Of Accident	30/11/2019 19:15
Exact Location Of Accident	ALONG UPPER THOMSON ROAD NEAR OUTSIDE THOMSON CC
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4882Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ENG JIAT CHENG
NRIC No	S1164260H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94756701
Alternative Phone No	OFFICE-94756701

### Vehicle Particulars

Manufacturer	BMW
Model	116 D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096192563-01
Cover Note Number	

### Driver

Name of Driver	TAN YU SHENG
NRIC No	S8524894D
Date Of Birth	02/09/1982
Occupation	INDOOR
Date Of Driving Pass	13/10/2004
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94756701
Fax Number	
Contact Number	

Address	BLK 453 SIN MING AVENUE #16-563 SINGAPORE
Postcode	570453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE YAN LIN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD6099B
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED
Vehicle Category	PRIVATE CAR
Name of Driver	ONG TENG KHOON
NRIC/Passport Number	S0178139A
Contact Number	96649359
Address	
Postcode	
Insurance Company Name	

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 02/12/19  
09:11

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(near outside Thomson CC)

I was driving along Upper Thomson Road, towards Novena, on 30/11/2019, about 1915hrs. I was on left most lane, going straight. A car on my right, SMD6099B, cut into my lane, I sounded the horn <sup>but he continued</sup> & he knocked into the right passenger door of my car and scraped all the way to the right back bumper.

We stopped at the side of the road to exchange contacts and take photo. The driver of SMD6099B said that he was turning to Marymount MRT to pick his wife. Hence, he would needed to take the left lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 02/12/19  
9.12

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/12/2019 12:55
Date Of Accident	30/11/2019 19:10
Exact Location Of Accident	UPPER THOMPSON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6099B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG TENG KHOON
NRIC No	S0178139A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97402827
Alternative Phone No	Others-97402827

### Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800102391-01
Cover Note Number	

### Driver

Name of Driver	ONG TENG KHOON
NRIC No	S0178139A
Date Of Birth	10/07/1952
Occupation	INDOOR
Date Of Driving Pass	17/06/1976

Driving Experience	43 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97402827
Fax Number	
Contact Number	OTHERS-97402827
EMail Address	NOEMAIL
Address	80 SPRINGSIDE AVENUE
Postcode	786575
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER THE ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT4882Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	TAN YU SENG
NRIC/Passport Number	
Contact Number	94756701
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

Vehicle No: SMD 6097B

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: SMD 6099B

Accident Location: Upper Thomson Road			
Accident Date: 30/11/2019		Time: 07:10 am / pm	
- Brief Details Of Accident -			
<p>I was driving along Upper Thomson Road <del>on</del> on the 3rd lane at the speed of 40 km. Weather is clear, road is clear, no traffic jam. A white color BMW No: SLT4882Y driven by Mr Tan Yu Seng NRIC: S8524894D was speeding driving close to me hit the left side of tyre rim and brush the left side of the car. BMW SLT4882Y after hitting me the car go some distance before <sup>his far</sup> stop.</p> <p>I check my car left side got scratches, tyre rim was brushed too.</p>			
- Other Vehicle Involve Details -			
(B)	Veh No: SLT4882Y	Hp: 94756701	Pax: Driver Name: TAN YU SENG
(C)	Veh No:	Hp:	Pax: Driver Name:

## DECLARATION

(We declare the foregoing particulars are true in every respect.)

  
 Policyholder's Signature  
 Date & Time:

Ong Teng Khoo  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 2/12/19  
 12:11 pm

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PIN No.:



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19021202/Bqd3e2-1		
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120		Date : 19-03-2020		
ATTN : BERNARD LER		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMD 6099B	Veh. Inspected	SLT 4882Y	
Policy No.	1800102391-01	Coverage (\$)	0.00	
Claim No.	3762136461SG	Excess (\$)	0.00	
Assign From	BERNARD LER	Assign Date	12/03/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA1V72070V249858	Colour	WHITE	
Odometer	49719	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/11/2019	Inspection Date	04/12/2019	
Survey held at	160 SIN MING DRIVE# 06-21			
Repairer	ENG SHING MECHANICAL WORKS			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4882Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RR BUMPER	BROKEN	1,037.00	1,037.00
1	RR FENDER RH	TO REPAIR SEE LABOUR	1,490.00	-
1	RR DOOR RH	DENTED	1,208.00	1,208.00
1	RH SIDE SKIRT	CUT	373.00	373.00
1	RR SHOCK ABSORBER RH	NOT DAMAGED	286.00	-
1	RR WHEEL HUB RH	NOT DAMAGED	190.00	-
1	RR WHEEL BEARING RH	NOT DAMAGED	161.00	-
1	RR BRAKE DISC RH	REFIT	411.00	-
1	RR WHEEL CARRIER RH	NOT DAMAGED	1,226.00	-
1	RR TRAILING ARM RH	NOT DAMAGED	120.00	-
1	RR GUIDE LINK RH	NOT DAMAGED	298.00	-
1	RR CONTROL ARM RH	NOT DAMAGED	334.00	-
1	RR TRACK STRUT RH	NOT DAMAGED	147.00	-
1	RR LOWER ARM RH	NOT DAMAGED	360.00	-
1	RR STABILIZER LINK RH	REFIT	89.00	-
	LESS 5% DISCOUNT		-	-130.90
			7,730.00	2,487.10
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RR ALLOY RIM (654) RH (SN) (LOCAL REPAIR)	DENTED / DEFACED	832.00	200.00
1	RR TYRE RH (SN)	NOT DAMAGED	300.00	-
			1,132.00	200.00
<b><u>LABOUR</u></b>				
	CHECK LIGHTINGS & WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS FOR NECESSARY REPAIRS.		120.00	50.00
	TO TRANSFER RHR DOOR FITTINGS.		120.00	50.00
	TO REMOVE, CHECK & REPLACE RHR UNDERCARRIAGE PARTS.		300.00	80.00
	WHEEL ALIGNMENT. 2X		150.00	60.00

Report Ref No. CS3/AIG19021202/Bqd3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RENEW DAMAGED PARTS. REPAIR, REFORM, REALIGN ALL DAMAGED AREA INCLUSIVE OF THE REPAIR RR FENDER RH.		1,200.00	600.00
	TO CONDUCT SPRAY PAINTING ON REPLACEMENT & AFFECTED AREA.		1,200.00	600.00
	ANTI RUST.		90.00	30.00
			3,260.00	1,470.00
GRAND TOTAL			12,122.00	4,157.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CS3/AIG19021202/Bqd3e2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.