ESTIMATED ACCIDENT REPAIR COST



	BLIS DEGISTRATION		
16:00HRS	NUMBER	SBS336	59T
6-Mar-20	BUS TYPE (SD/DD)	DD	
MOHAMMED YAHYA BIN ZAINAL AZMAN	BUS ROUTE NUMBER		
AIG INSURANCE	BUS ADVERTS (Y/N)	N	
& CONSUMABLE ITEMS (MATERIAL COST)			
Part or Item Descriptio	n	Quantity	Total Cost
O/S/F DEFLECTOR		1	\$160.00
O/S/F CORNER BUMPER W		1	
O/S/F LIGHT BEZEL			
	14 12 1 12 1 1	7% GST	\$51.80
		PARTS TOTAL COST	\$791.80
SMENT / REPAIR / SPRAY PAINT (LABOUR COST)			
LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR	SPRAY PAINT)		TOTAL COST
REPLACE DAMAGED PARTS			1300 \$2,600.00
			\$1,920.00
		7% GST	\$316.40
		LABOUR TOTAL COST	\$4,836.40
	MOHAMMED YAHYA BIN ZAINAL AZMAN AIG INSURANCE R. CONSUMABLE ITEMS (MATERIAL COST) Part or Item Description O/S/F DEFLECTOR O/S/F CORNER BUMPER O/S/F LIGHT BEZEL SMENT / REPAIR / SPRAY PAINT (LABOUR COST) LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR	MOHAMMED YAHYA BIN ZAINAL AZMAN AIG INSURANCE BUS ROUTE NUMBER BUS ADVERTS (Y/N) Part or Item Description O/S/F DEFLECTOR O/S/F CORNER BUMPER O/S/F LIGHT BEZEL MENT / REPAIR / SPRAY PAINT (LABOUR COST) LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	AIG INSURANCE BUS ROUTE NUMBER AIG INSURANCE BUS ADVERTS (Y/N) N CONSUMABLE ITEMS (MATERIAL COST) Part or Item Description O/S/F DEFLECTOR O/S/F CORNER BUMPER O/S/F LIGHT BEZEL TWA TWA THE PARTS TOTAL COST LABOUR ITEM (LABOUR COST) LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT) EPLACE DAMAGED PARTS

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING	COST		

SECTION 4: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	6/3/2020
	DATE & TIME SURVEY	
	DATE OUT	
DD	TOTAL NUMBER OF DAYS	5 d. 1
SS OF USE COST		\$2,000,00

BUS TYPE (SD / DD) LOSS

SUMMARY		
SECTION NO.	COST	
1	\$791.80	
2	\$4,836.40	
3 -		
4	\$2,000.00	
GRAND TOTAL	\$7,628.20	

Rosul

40 90010068

3 days

12/03/2020@1030

Rosurvey after repair

PAGE 2