

20/03/2020

ASS. REC. BY:

REF:

CS/CTI/20003955/Kvd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tay of CTIDate/Time: 12/3/2020 @ 5:26pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 9148D

Insured:

SLR 8977Sat Workshop m/s EM SolutionTel: 6456 0226of 160 Sin Ming Drive #03-18/19

Policy No: _____

Claim No: SNM20D201212/SLR8977S/IRENE

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 09/03/2020

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement: _____

Date/Time: 10:29am @ 13/3/2020

Person Contacted:

BernardVehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SMC 9148D-X	✓
	SLR 8977S	

ASS. REC. BY:

REF: CTZ/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP 12/29 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMC 9148D Yr Regn: 01, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Wish c.g. 1987Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 128816 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20W 20 5001505Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: Nexen 225/45ZR17R: Westlake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

R/Bal: 7 mm RearL/Bal: 7 mm R/Bal: 8 mmD.O.A. 9/13/20 L/Bal: 8 mmD.O.I. 13/3/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

F. & S.

Others

TOTAL

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 12 March 2020 5:26 PM
To: assignments; 甯琨 ©; Sally Chong
Subject: FW: OUR REF: SNM20D201212/ SLR8977S/IRENE - YOUR REF.: E21.113088.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

Importance: High

Dear Sir,

We refer to the above matter.

Please get your surveyor to liaise with EM SOLUTION to conduct survey.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sally Chong [mailto:sallychong@visionlawllc.com]

Sent: Thursday, March 12, 2020 5:01 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; 'Judy Soh'

<judysoh@visionlawllc.com>; Tanvin13@yahoo.com.sg

Subject: OUR REF: SNM20D201212/ SLR8977S/IRENE - YOUR REF.: E21.113088.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

Importance: High

URGENT

Dear Irene,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO
PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: SENTOSA LIMOUSINE**

ACCIDENT INVOLVING SMC 9148D & SLR 8977S ON 9 MAR 2020 ALONG BLK 808, WOODLANDS STREET 81 CARPARK AT ABOUT 18:20 HRS

We refer to your email of even date below and your list of surveyors therein.

Our client now confirms the appointment of KENNETH KONG- LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue : E M SOLUTION PTE LTD
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: Irene Tay [mailto:irene.tay@sg.cntaiping.com]

Sent: Thursday, 12 March, 2020 3:50 PM

To: Sally Chong; Claims Dept of CTI

Cc: 'EM Solution Pte Ltd'; derekkeh@singnet.com.sg; 'Judy Soh'

Subject: RE: OUR REF: SNM20D201212/ SLR8977S/IRENE - YOUR REF.: E21.MISC.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA
ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG

SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]
Sent: Wednesday, March 11, 2020 9:45 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>
Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; 'Judy Soh' <judysoh@visionlawllc.com>
Subject: RE: OUR REF: SNM20D201212/ SLR8977S/IRENE - YOUR REF.: E21.MISC.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

URGENT-REMINDER

Dear Irene,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: SENTOSA LIMOUSINE
ACCIDENT INVOLVING SMC 9148D & SLR 8977S ON 9 MAR 2020 ALONG BLK 808, WOODLANDS STREET 81 CARPARK AT ABOUT 18:20 HRS

We are instructed by **SENTOSA LIMOUSINE** to notify you of a road traffic accident **ON 9 MAR 2020 ALONG BLK 808, WOODLANDS STREET 81 CARPARK AT ABOUT 18:20 HRS** involving our client's vehicle registration number **SMC 9148D** and vehicle registration number **SLR 8977S** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

From: Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

Sent: Tuesday, 10 March, 2020 5:07 PM

To: Sally Chong; Irene Tay

Cc: 'EM Solution Pte Ltd'; derekkeh@singnet.com.sg; 'Judy Soh'; Claims Dept of CTI

Subject: OUR REF: SNM20D201212/ SLR8977S/IRENE - YOUR REF.: E21.MISC.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

Dear Irene,

Please conduct PRS for SMC9148D.

Note : officer in charge – Irene Tay 63896192.

***** Kindly quote our reference number when replying.**

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sally Chong <sallychong@visionlawllc.com>

Sent: Tuesday, March 10, 2020 3:47 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; 'Lucas Lee' <lucas.lee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; derekkeh@singnet.com.sg; 'Judy Soh' <judysoh@visionlawllc.com>

Subject: OUR REF.: E21.MISC.20 (SMC 9148D @09/03/2020) // CHINA TAIPING REF NO : SLR 8977S

URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO
PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: SENTOSA LIMOUSINE

ACCIDENT INVOLVING SMC 9148D & SLR 8977S ON 9 MAR 2020 ALONG BLK 808, WOODLANDS STREET
81 CARPARK AT ABOUT 18:20 HRS

We are instructed by SENTOSA LIMOUSINE to notify you of a road traffic accident ON 9 MAR 2020 ALONG
BLK 808, WOODLANDS STREET 81 CARPARK AT ABOUT 18:20 HRS involving our client's vehicle registration
number SMC 9148D and vehicle registration number SLR 8977S driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged
vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would
like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated
timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: VEHICLE OWNER OF SLR 8977S

LEI HUICHUN

807, Woodlands Street 81,

#09-201,

Singapore 730807

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the
recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	233X
Vehicle Details	
Vehicle No.:	SMC9148D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 2.0 AUTO
Primary Colour:	Green
Manufacturing Year:	2009
Engine No.:	3ZRA417557
Chassis No.:	JTDGJ20W205001505
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,003.00
Original Registration Date:	04 Jan 2010
First Registration Date:	04 Jan 2010
Transfer Count:	4
Actual ARF Paid:	\$22,003.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$39,313.00
COE Rebate Amount:	\$38,488.00
Total Rebate Amount:	\$38,488.00

The information contained herein is correct as at 16 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2020 15:18
Date Of Accident	09/03/2020 18:20
Exact Location Of Accident	BLK 808 WOODLANDS STREET 81 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC9148D
Insured/Policyholder	
Name Of Registered Owner	SENTOSA LIMOUSINE
Co Reg No	5XXXX233X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91884948

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5111217081
Cover Note Number	

Driver

Name of Driver	MOHAMMAD HANIZAM BIN HASSAN
NRIC No	SXXXX878J
Date Of Birth	25/01/1982
Occupation	OUTDOOR
Date Of Driving Pass	29/09/2014
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87520640
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 999B BUANGKOK CRESCENT #05-757 SINGAPORE
Postcode	532999
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8977S
Vehicle Make/Model/Colour	RED/HONDA
Details Of Properties	REFER ATTACHED AND POLICE REPORT
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHAMMAD HANIZAM BIN HASSAN
Approximate Age	
Injuries Sustain	REFER ATTACHED AND POLICE REPORT
Injured person in which vehicle?	SMC9148D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20200310/2114

1 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200310/2114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/03/2020 16:49		Vide Report No.:		Station Diary No.: 74	
Informant's Particulars					
Name of Informant: MOHAMMAD HANIZAM BIN HASSAN			Address: APT BLK 999B BUANGKOK CRESCENT #05-757 SINGAPORE 532999		
ID Type / ID No.: NRIC NO / S8200878J			Contact No.: Home/Office: Mobile: 87520640		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 25/01/1982	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/03/2020 18:20	Type of Location: Car Park
Location: Along Road 1 WOODLANDS STREET 81 Blk 808 Woodlands St 81				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLR8977S	Car					1
SMC9148D	Car					0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20200310/2114

2 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200310/2114

CONTINUATION OF REPORT

Driver			
Name	MOHAMMAD HANIZAM BIN HASSAN	ID No.	S8200878J
Related Vehicle	SMC9148D (Car)	Contact No.	87520840
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3A Date of Expiry: NIL
Date Treatment	10/03/2020	Date Discharge	NIL
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 09/03/2020 at about 1820hrs, I was traveling (SMC9148D) along the OSCP of Blk 808 Woodlands St 81.

Suddenly, one vehicle (SLR8977S) which was in the lot came out and hit onto my vehicle's right front bumper area. I alighted from my vehicle to make a check. No police or ambulance was activated. No one was injured the point of time. I did exchange particulars with the driver. My vehicle has an in-car camera however, it is spoilt.

After the accident, I felt pain on shoulder and neck area. I went to see a doctor and gotten 4 days of medical certificate.

Particulars of the driver:
Lei Huichun, S7384018Z
HP: 81236678

Common Statement Pg. 1



SINGAPORE
POLICE FORCE



T/20200310/2114

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

3 of 3

Report No: T/20200310/2114

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
Sgt 2 LIM HWEE JIE, SAMUEL

Signature Of Informant.

Signature Of Interpreter:
Not applicable

Date/Time:
10/03/2020 16:49

Officer In Charge Of Case:
TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 85476404

Classification Of Case:

SN 061

Authentication Stamp
NF100

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

11.03.2020

Sentosa Limousine

Not Notified
1/1/2020 @ 7
Recovery After Paint *3 days*

REPAIR ESTIMATE FOR TOYOTA WISH - SMC 9148 D

1 pc	RH headlamp assy		CAT	1,475.80	—
1 pc	front bumper		CAT	1,068.40	—
1 pc	RH front bumper fog lamp		h	284.30	X
1 pc	RH front bumper fog lamp grille			68.95	?
1 pc	front bumper inner sponge			148.20	?
1 pc	front bumper reinforcement			375.50	?
2 pcs	front bumper reinforcement brackets	68.50	n	137.00	X
2 pcs	front bumper side retainers	72.80		145.60	X
1 pc	front grille		h	185.60	X
1 pc	RH front fender		n	761.40	X
1 pc	RH front fender inner shield		h	141.80	X
1 pc	RH front fender lamp		h	56.20	X
				4,848.75	
Less 25%				1,212.19	
				3,636.56	

1 set	front bumper clips		h	45.00	SN —
1 set	RH front fender inner shield clips		h	35.00	SN X
1)	Check electrical wirings.			60.00	201
2)	Repair accident damages and renew above parts.			880.00	3001
3)	Spray paint on accident affected portions.			880.00	4001
4)	Rust proofing on accident affected portions.		h	50.00	X
				\$ 5,586.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: