

ASS. REC. BY: H ANN

REF: SMO

W

**ASSIGNMENT**

From: PPS Date: 13/03/2020

Estimated Cost: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMQ 2359J

at Workshop m/s ECO Automobile

of 13 karki Bukit Road 4 #03-29

Insured: Bartley Biz

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SMQ 2359J Yr Regn: 21/01/2020

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Make: Audi Q5 Quattro c.c. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 122637 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ8RZ3AA043437


Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: \_\_\_\_\_ R: 235/45/R18



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 45 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front 6 mm Dun Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/3/20 D.O.I. 13/3/20

Survey held at ECO Automobile 0221PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>range → 6-7K</u>
	<u>upr days → 5 day</u>
	<u>18/3/2020</u>
	<u>mv - 68000</u>
	<u>pv - 38847</u>
	<u>nv - 29120</u>

RECEIVED 18 MAR 2020

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? 18/3 - typist

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:	<u>100</u>
Transportation:	<u>60</u>
S + RS. SI	
Photos	
Others	
TOTAL	<u>160</u>