

ASS. REC. BY:

REF:

MSIG CS/MSG20004021/Gsf3

ASSIGNMENT

From: _____ Date: 16.3.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 8603B

at Workshop m/s Focus Auto

of 1 Kari Butta M/L 702-48

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$72K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMJ 8603B Yr Regn: 06 Mar 2017

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan

Colour: white

Sp. Reading: 67448

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. _____

Survey held at W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CofG: 49891

11/01/2021 @ 14:02 PM AIDA CALL IN SAY STILL PENDING LIABILITY FROM MSIG, VEHICLE NOT YET REPAIR.

Date/Time, File Pass to?

11/01/2021

1) TYPIST

Date/Time, File Return to?

2) _____

Rep. Format: PRELI

Lump Sum / L.B. (\$) _____



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL