

All diagnosis code

TEL:

FAX:

Employee. in charge:

E-mail:

Date and time: 4/6/2020 9:01:25 am

Vehicle: Forester

VIN: JF1SJ5KC5GG075359

Model: 16MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Past	U0164	Lost Communication With HVAC Control Module	00000	0	ommo		
Past	U0231	Lost Communication With Rain Sensing Module	00000	0	ommo		

<Airbag : 3 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Past	B1906	Open in Front P/T LH	04799	3600	ommo		
Past	B1826	Open in Side Airbag LH	04799	3600	ommo		

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Past	B1836	Open in Curtain Airbag LH Squib Circuit	04799	3600	ommo		

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<Combination Meter : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Past	U0164	Lost Communication With HVAC Control Module	00050	2900	ommo		
Past	U0151	Lost Communication With Restraints Control Module	04798	1400	ommo		

<Multi-function Display : 0 piece>

<Headlight / Foglight : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04850	131100	Current		
Past	B2905	LED Head Light Circuit LH	04753	20136100	ommo		**
Past	B2911	Steering Responsive Headlight Communication LH	04753	46350500	ommo		

All diagnosis code

TEL:

FAX:

Employee, in charge:

E-mail:

Date and time: 4/6/2020 9:03:24 am

Vehicle: Forester

VIN: JF1SJ5KC5GG075359

Model: 16MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			04851	17500	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<Combination Meter : 0 piece>

<Multi-function Display : 0 piece>

<Headlight / Foglight : 0 piece>