

REF: CS3/A2G19022274/71v430 -1

ASSIGNMENT (Office)

From Person: Loh Chee Heng at ALG Date/Time: 13/03/2020 5:31pm

Estimated Cost: Bill to:

OD / TP / VN / TP RES / OD RES / EVA / INV / MY / CS

To inspect Vehicle No: SLB 5748R

Insured: SMD 4663K

at Workshop no: Super modern

Tel: 62567830

25 Kaki Bukit Rd 4 #01-21 Synergy

Policy No:

Claim No: 9590628878 SG

Insured Name:

Driver:

Make of Vehicle: DOA 14.12.2019

CA / REV / REP / REV 24 HRS

Date/Time: 18.12.19 1:40pm

Person Conducted: madam Teoh

Vehicle Endorsement

Value: IN OUT

Date/Time: Action/Restriction: ☒ ☐ ☐ ☐

19/12/19 @ 238pm Mdm Teoh said no est
21/1/2020 Submit DAR report

URGENT

18/3/2020

4/5 \$3900, 6 days

190

23/3/20 Submit LS \$3900 (Recd 2450, 39%), 6 days


RECEIVED 23 MAR 2020

Tupke

414

ASSIGNMENT

Event:
 Date:
 Time:
 Location:
 Type:
 Make:
 Model:
 Year:
 Color:
 VIN:
 License:
 Title:
 Insurance:
 Policy No:
 Claims No:
 Sum Insured:
 (Client's Record)
 Make of Veh:
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:
 IDAC Accident Report:
 Consistent? Yes or No
 G/A: PR Seen:
 Consistent? Yes or No
 Est. Repair:
 days: Res: Yes or No
 Loss Sub:
 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Vehicle No: **SLB 5748R**
 Type: **Car** / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **Honda Vozel**
 Color: **Blue**
 Sp Reading: **51483**
 Eng No:
 C/N: **R411115261**
 Gett Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / TS/Rim / STD A/Rim or
 Tyre Size: **F: 215/60R16**
R: 215/60R16

BS / **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front:
 R/Bal: **6** mm
 L/Bal: **6** mm
 D.O.A:
 Survey held at: **Super Modern**
 Des. of Damages: **Frt / Rew / O/S / N/S / UIC / Roothop** or

Rear:
 R/Bal: **6** mm
 L/Bal: **6** mm
 D.O.A: **18/12/19 4:10pm**

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: **11/12/19**
 Action / Instruction: **N: G/A. - 6 days**
25 KB R4 #01-21

RECEIVED 2020

How many days for:
☐ : Prel Report
☐ : Final Report

Days Of Repair: **6**
 Resurvey No. of Trip: **1**

How many days for:
11 - typist

What For:
☐ Site trip
☐ Interview
☐ Drawing
☐ Other

Survey Fee: **180**
 Insurance: **11**
191

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

000Z

Vehicle Details

Vehicle No.:

SLB5748R

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Dec 2019

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X CVT ABS D/AIRBAG 2WD

Primary Colour:

Blue

Manufacturing Year:

2016

Engine No.:

L15B4035267

Chassis No.:

RU11115261

Maximum Power Output:

96.0 kW (128 bhp)

Open Market Value:

\$20,980.00

Original Registration Date:

14 Apr 2016

First Registration Date:

14 Apr 2016

Transfer Count:

0

Actual ARF Paid:

\$11,372.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

13 Apr 2026

PARF Rebate Amount:

\$8,529.00

Intended COE Rebate Details

COE Expiry Date:

13 Apr 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$46,009.00

COE Rebate Amount:

\$29,070.00

Total Rebate Amount:

\$37,599.00

The information contained herein is correct as at 19 Dec 2019

OK

MOTORCAR (Rear)

Rear Portion

Vehicle No: SLB5748R

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper side RH			
1143	993017	Rear Bumper side LH			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items:

Assessor:

31/12/2019

Nivitha (LKK Auto)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Friday, 13 March 2020 5:31 PM
To: assignments
Subject: 9590628878SG-003, paper resurvey for SLB5748R - Urgent
Attachments: TP survey.pdf; PRI photos.pdf

Dear Sir/Mdm,

Kindly assist paper resurvey for SLB5748R and let us have the report soonest. If possible, by the next 7 days as this case is in litigation stage in Court.

PRI is conducted by your surveyors. Attached TP survey report and PRI photos. Both parties report will be sent in an encrypted email shortly.

Thank you.

Best regards,
Loh Chee Heng
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 14:17
Date Of Accident	14/12/2019 08:10
Exact Location Of Accident	CAUSEWAY TWRDS JOHOR BAHRU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5748R
Insured/Policyholder	
Name Of Registered Owner	LUM YEW KUAN
NRIC No	S0009000Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96333351
Alternative Phone No	OFFICE-96333351

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5079182330-03
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	LUM NAM CHUIN
NRIC No	S8927393E
Date Of Birth	09/08/1989
Occupation	INDOOR
Date Of Driving Pass	09/01/2009
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97597584
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 107 #10-340 TOWNER ROAD
Postcode	321107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LUM YEW KUAN GENDER: : MALE
Passenger 2	NAME: : TAN NGAK TEOW GENDER: : FEMALE
Passenger 3	NAME: : TIEW YEN FONG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD4663K
Vehicle Make/Model/Colour	TOYOTA / PRIUS AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG CHANG KIT(HUANG ZHENJIE)
NRIC/Passport Number	S8229026E
Contact Number	97969497

Address

298D COMPASSVALE ST
#08-82

Postcode

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 16/12/19
2.27pm

GIA/ACC Sketch Plan Form v3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/12/19
2.29pm


IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vacbk@vacom.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: 16 DEC 2019

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/12/19 at 8.10am, my car was stationary at the Causeway towards Johor Bahru when I suddenly felt a loud bang at the rear of my vehicle. When I got down of my car to see, I saw that motor vehicle SMD4663K has hit the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 14/12/19 2.27pm

UASAC (Kaki Bukit) v. 1.1

Driver's Signature
(If driver is not the policyholder)
Date & Time: 14/12/19 2.27pm

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No: 6 DEC 2019

Accident Photo



Accident Photo



Driving License



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: _____ Vehicle Registration No: 8UB574R
Name (as shown in NRIC): Lum Yana Chuan NRIC/FIN/Passport No: S 8427393E
(*Vehicle Driver / Vehicle Owner) [*] Please delete as appropriate
Address: _____ Singapore ()
Contact (Tel): _____ Mobile No.: _____
Email Address: _____
Date of Accident: 14-12-2019 Time of Accident: 0810
Place of Accident: Causeway Twox John Bahru
Insurance Company: LINE

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Update gender passenger and driver name.

Policyholder / Driver's Signature: _____
Date: _____

IDAC KAKI BUKIT (VAC)
Reporting Centre: 23 Kaki Bukit Ave 4
Name: Singapore 415933
Tel: 67416697 Fax: 67492305
Date: _____ Email: yockb@singnet.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2019 15:57
Date Of Accident	14/12/2019 08:00
Exact Location Of Accident	WOODLANDS CROSSING BORDER BRIDGE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4663K
Insured/Policyholder	
Name Of Registered Owner	KINETIC ALLIANCE PTE LTD
Co Reg No	201613074E
Email Address	SUPPORT@KINETIC-ALLIANCE.COM
Mobile Phone No	
Alternative Phone No	Office-62642231

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994109
Cover Note Number	

Driver

Name of Driver	WONG CHANG KIT (HUANG ZHENJIE)
NRIC No	S8229026E
Date Of Birth	06/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2007
Driving Experience	12 YEARS AND 5 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-97969597
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 298D COMPASSVALE STREET #08-62
Postcode	544298
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : TANG YEE HAW Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB5748R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver
NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 16 DEC 2019


Driver's Signature
(If driver is not the policyholder)
Date & Time: 16 DEC 2019


Reporting Centre Personnel's Signature
Name: Pnh Kwee Choo
NRIC/FI

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am the driver of car B, I hit car A while car A was stationary, Due to I release brake unintentionally.

Location: Woodlands cross border bridge


Date: 14/12/2019 (SAT)

Time: Around 8am

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date: 16 DEC 2019


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 16/12/19
 1550


 Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.:

CERTIFICATE OF INSURANCE



HOTLINE TEL: (65) 6419-3000

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 186)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1967 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

N.L.A.00

COMPREHENSIVE
CERTIFICATE NO.
POLICY NO.

COMMERCIAL MOTOR
SMD4663K
999994199

(The below excess is subject to GST)
POLICY EXCESS S\$1500.00 (Sect 1 & 2)
WINDSCREEN EXCESS S\$100.00

SUM INSURED Market Value
INSURING WITH COE/PAIF YES

SMD4663K

Kinetic Alliance Pte Ltd

06 June 2019

07 June 2020

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Insured's order or with their permission.

S\$1,500.00 Section 1 & S\$1,500.00 Section 2 Excess is applicable for driver who is between 23 years to 60 years old with minimum 2 years driving experience in Singapore.

An additional section 2 excess of \$1,000.00 per accident is applicable in the event of an accident occurring outside Singapore.

Accident repair has to be carried out at AIG appointed list of workshop or Manufacturer workshop within 3 years warranty.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

- 1) Use for social, domestic, pleasure purposes and business purposes of Insured
- 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.
- 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.

LOSS OF USE Not Included

HIRE PURCHASE COMPANY NA

*Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 186) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 186) and Part IV of the Road Transport Act, 1967 (Malaysia).

Issued in Singapore 07 Jun 2019

AIG Asia Pacific Insurance Pte. Ltd.

101630-000
SC Alliance Pte Ltd
78 Sea Breeze Avenue
Singapore 487582



AUTHORIZED REPRESENTATIVE

SSPOEC

ORIGINAL

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



CHASSIS NUMBER

TOYOTA MOTOR CORPORATION			
JTDKN33U5G5074314			
1	RO	KG	6/7R
1	80	KG	200/FA10
1	100	KG	A/TM
1	100	KG	CLAP410
1	98	KG	PLANT
MODEL 2VWJ0R AHAEH			
545			

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No: 53138015K

Automobile Inspection Report

To: Lum Yew Kuan c/o 25 Kaki Bukit Road 4 #01-26 Synergy@KB Singapore 417800	Date : 27/12/2019 Reference No : CAS/19-12/041																				
<u>General Information</u> Registration No. : SLB 5748R Accident Date : 14/12/2019																					
<u>Particulars of Damaged Vehicle</u> Colour : Blue Engine Capacity : 1496 cc Mileage (KM) : 051483 Chassis No. : RU11115261 Registration Date : 14/04/2016 Make & Model : Honda Vezel Pre-Accident Condition : Good Engine No. : L15B4035267 Steering : In Order Brake : In Order																					
<u>Tyre Condition</u> <table><thead><tr><th></th><th>Size</th><th>Make</th><th>Balance</th></tr></thead><tbody><tr><td>R/H Front Tyre</td><td>215/60R16</td><td>DUNLOP</td><td>80%</td></tr><tr><td>L/H Front Tyre</td><td>215/60R16</td><td>DUNLOP</td><td>80%</td></tr><tr><td>R/H Rear Tyre</td><td>215/60R16</td><td>DUNLOP</td><td>80%</td></tr><tr><td>L/H Rear Tyre</td><td>215/60R16</td><td>DUNLOP</td><td>80%</td></tr></tbody></table>			Size	Make	Balance	R/H Front Tyre	215/60R16	DUNLOP	80%	L/H Front Tyre	215/60R16	DUNLOP	80%	R/H Rear Tyre	215/60R16	DUNLOP	80%	L/H Rear Tyre	215/60R16	DUNLOP	80%
	Size	Make	Balance																		
R/H Front Tyre	215/60R16	DUNLOP	80%																		
L/H Front Tyre	215/60R16	DUNLOP	80%																		
R/H Rear Tyre	215/60R16	DUNLOP	80%																		
L/H Rear Tyre	215/60R16	DUNLOP	80%																		
<u>Inspection</u> Repairer : Super Modern Services Pte Ltd 25 Kaki Bukit Road 4, #01-26 Synergy@KB, Singapore 417800																					
<u>Adjustment And Recommendation Cost Of Repair</u> Repairer's Estimate : \$10,381.96 Revised Amount : \$6,350.00 Less Excess : - Nett Total : \$6,350.00																					
<u>Remarks</u> (A) Survey was done on 17/12/2019 (B) Re-survey was done on 20/12/2019 (C) Re-survey after repair was done on 24/12/2019 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.																					

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SLB 5748R

Our ref : CAS/19-12/041

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Tailgate	Dented/Buckled	1,275.60	1,275.60 ^{1/00}
2	1pc	Tailgate glass moulding	Necessary	120.60	120.60
3	1pc	Tailgate emblem 'H'	Necessary	32.70	32.70
4	1pc	Tailgate outer garnish	Broken	260.80	260.80
5	1pc	Tailgate emblem 'Vezel'	Necessary	48.80	48.80
6	2pcs	Tailgate lamp @ \$310.60	O/S Cracked/Broken	621.20	310.60
7	1pc	Tailgate inner lock	Bent/Jammed	280.90	280.90
8	1pc	Tailgate inner trim board	Serviceable	431.80	-
9	1pc	Tailgate weatherstrip	Distorted	241.60	241.60
10	2pcs	Tailgate stopper @ \$12.60	Necessary	25.20	25.20
11	2pcs	Taillamp @ \$381.90	Serviceable	763.80	762.40
12	1pc	Rear bumper	Dented/Deformed	891.60	891.60
13	2pcs	Rear bumper reflector @ \$89.90	Cracked/Broken	179.80	179.80 ^{LH-XND R Rera ✓ 29.90}
14	2pcs	Rear bumper side @ \$281.60	Repair	563.20	-
15	2pcs	Rear bumper side retainer @ \$48.60	Necessary	97.20	97.20
16	1pc	Rear end panel	Dented/Warped	641.60	641.60 ^{Rp}
17	1pc	Rear end panel trim	Deformed	182.90	182.90
18	1pc	Rear exhaust silencer	Dented/Bent	614.60	614.60 ^{Rp}
19	2pcs	Rear exhaust mounting @ \$28.20	Distorted	56.40	56.40 ^{x pin}
20	1pc	Rear smart keyless antenna	Damaged	180.90	180.90 ^{XND Z}
21	1pc	Rear smart keyless buzzer	Damaged	190.60	190.60 ^{XND Δ}
22	1pc	Rear wiper motor	Damaged/Jammed	481.90	481.90 ^{XND}
				8,183.70	6,114.30 ³⁵⁵³
		Less 20%		(1,636.74)	(1,222.86) ²⁸⁴³¹⁷
		Sub total		6,546.96	4,891.44
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1set	Tailgate glass sealant	Necessary	80.00	50.00
2	1set	Tailgate glass foam tape	Necessary	65.00	45.00
3	1pc	Reverse camera	Damaged	350.00	350.00 ^{X 516}
4	1set	Reverse sensor	Damaged	280.00	220.00 ²⁰⁰
		Sub total		7,321.96	5,556.44 ²¹⁵

Constant Appraiser Services

Vehicle No : SLB 5748R

Our ref : CAS/19-12/041

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES</u>			
1		To remove, refix tailgate glass		140.00	120.00
2		To remove, refix rear interior trim to assist repair		100.00	80.00 ⁶⁰
3		To check rear electrical wiring		40.00	20.00
4		Transfer & reinstall tailgate electrical & mechanical to new tailgate		100.00	70.00 ⁶⁰
5		To remove, refix exhaust silencer		100.00	80.00 ⁶⁰
6		To remove, refix reverse sensor / camera		80.00	60.00 ³⁰
7		To respray undercoating		100.00	60.00 ³⁰
8		To respray painting & etc		1,200.00	1,000.00 ⁷⁰⁰
9		Panel beating, cut, weld, remove & replacing above parts		1,200.00	900.00 ⁷⁰⁰
Grand total				10,381.96	7,946.44
Recommended cost of lump sum repair (To its pre-accident condition)					6,350.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,350.00** on a contractual basis. Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Yours faithfully,

Constant Appraiser Services


Lim Yong Tian (Sebastian)
 Licensed Appraiser
 Adv. Dip. In Mechanical Engineering (AUS)
 MSAAA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG19022274/T1vf3e2-1		
78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120		Date : 23-03-2020		
ATTN : LOH CHEE HENG		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 4663K	Veh. Inspected	SLB 5748R
	Policy No.	999994109	Coverage (\$)	0.00
	Claim No.	9590628878SG	Excess (\$)	0.00
	Assign From	LOH CHEE HENG	Assign Date	13/03/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11115261	Colour	BLUE
	Odometer	51483	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	14/12/2019	Inspection Date	18/12/2019
	Survey held at	SUPER MODERN SERVICES 25 KAKI BUKIT ROAD 4 #01-26 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5748R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED / BUCKLED	1,275.60	1,100.00
1	TAILGATE GLASS MOULDING	NECESSARY	120.60	120.60
1	TAILGATE EMBLEM 'H'	NECESSARY	32.70	32.70
1	TAILGATE OUTER GARNISH	BROKEN	260.80	260.80
1	TAILGATE EMBLEM 'VEZEL'	NECESSARY	48.80	48.80
2	TAILGATE LAMP @\$310.60	O/S CRACKED / BROKEN	621.20	310.60
1	TAILGATE INNER LOCK	BENT / JAMMED	280.90	280.90
1	TAILGATE INNER TRIM BOARD	SERVICEABLE	431.80	-
1	TAILGATE WEATHERSTRIP	DISTORTED	241.60	241.60
2	TAILGATE STOPPER @\$12.60	NECESSARY	25.20	25.20
2	TAILLAMP @\$381.90	SERVICEABLE	763.80	-
1	REAR BUMPER	DENTED / DEFORMED	891.60	762.70
2	REAR BUMPER REFLECTOR @\$89.90	N/S NOT DAMAGED / O/S CRACKED	179.80	89.90
2	REAR BUMPER SIDE @\$281.60	TO REPAIR SEE LABOUR	563.20	-
2	REAR BUMPER SIDE RETAINER @\$48.60	NECESSARY	97.20	97.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	641.60	-
1	REAR END PANEL TRIM	DEFORMED	182.90	182.90
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	614.60	-
2	REAR EXHAUST MOUNTING @\$28.20	NOT NECESSARY	56.40	-
1	REAR SMART KEYLESS ANTENNA	NOT DAMAGED	180.90	-
1	REAR SMART KEYLESS BUZZEL	NOT DAMAGED	190.60	-
1	REAR WIPER MOTOR	NOT DAMAGED	481.90	-
	LESS 20% DISCOUNT		-1,636.74	-710.78
			6,546.96	2,843.12

Report Ref No. CS3/AIG19022274/T1vf3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	50.00
1	SET TAILGATE GLASS FOAM TAPE (SN)	NECESSARY	65.00	45.00
1	REVERSE CAMERA (SN)	SERVICEABLE	350.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			775.00	295.00
	<u>LABOUR</u>			
	TO REMOVE, REFIX TAILGATE GLASS.		140.00	120.00
	TO REMOVE, REFIX REAR INTERIOR TRIM TO ASSIST REPAIR.		100.00	60.00
	TO CHECK REAR ELECTRICAL WIRING.		40.00	20.00
	TRANSFER & REINSTALL TAILGATE ELECTRICAL & MECHANICAL TO NEW TAILGATE.		100.00	60.00
	TO REMOVE, REFIX EXHAUST SILENCER.	NOT NECESSARY	100.00	-
	TO REMOVE, REFIX REVERSE SENSOR / CAMERA.		80.00	30.00
	TO RESPRAY UNDERCOATING.		100.00	30.00
	TO RESPRAY PAINTING & ETC.		1,200.00	700.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE, REAR END PANEL AND REAR EXHAUST SILENCER.		1,200.00	700.00
			3,060.00	1,720.00
GRAND TOTAL			10,381.96	4,858.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS3/AIG19022274/T1vf3e2-1

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.