

ACS. REC. BY:

REF: C71

ASSIGNMENT

From:

Date: 17.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBA 1830K

at Workshop m/s

Ace Autolukon

of

13 Kaki Bukit Road 4 #03-29 Bony Biz Centre

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

7BA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBA1830K

Yr Regn: 2007 / March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Fiat Doblo

c.c 1248

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

331129

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA22300005499950

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Goodrich

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/03/20

Survey held at

Ace Autolukon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP (Chin)

COE Expiry: 26/03/22
Lump Sum \$1000 - Cred: 3724.79 (78%)

MV: 11K

PV: 9.9K

Nett: 1.1K

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Rep. Format:

Lump Sum / L.B.I. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL