From (Person	is avail teo		MENT (Office)		te/Time:	6/03/206	4
Estimated Co			Bill to:				
To Inspect Ve	STIP RES / OD RES /	EVA/INV/MV EU 9330K	7 /-CS	Insured:	SENT	1885	
at Workshop	m/s_ Eve	ROAWN		Tel:	639511	171 WER	L. Ta
of	cary	BRUCT @	Premier	500016			
Policy No:					CMTOO	1521100	apl
Sum Insured:			Excess:				
Make of Veh				100	- 0.0	121-0	
Climit's Record				D.	0.A(4	13/20	
Client's Recerv	REP / DEVI 24 TEN	Person Contacts	st: (vene		O.R.		_
Client's Recervice / REV	3)	Person Contacts Estimate (X)			O.R.		_
Client's Recervice / REV	Action/Instruction	Person Contacts Estimate (X)		tan Veb	H.O.D. Endorseme	oni:	_
Client's Recerv	Action/Instruction	Person Contacts Eshmoth (X)	6555/A1-3.	tan Veb	H.O.D. Endorseme	oni:	

SS. REC. BY: H- ANIV- REF: 5M	ASSIGNMENT	
PRS		12/12/10
rom: Date: 12/3/20	70 Veh No: 524 7330/2 YrRe	
slimated Cost.	Type: M.Cap/ M.Cycle / Bus / Van / Lorry / Taxi	Prime Mover /
TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No: SW 9330 L	Make: Hymsi Marla	- cc /57/
Workshop m/s Evendawn Pruto	Colour Begg A/C:	Insured / Std / NI / NA
8 Kerles mulest tre 4 401-02 Pl	LEMEL Sp. Reading /5540 L. T/Radio	; Insured / Std / NI / NA
nsured: @ KANEL BRUKET.	Eng/No:	
Policy No.	CMO: KMHO84/CV	- JU593601
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt	
Q 31 TO 12 15 15 15 15 15 15 15 15 15 15 15 15 15	Steering Inorder / Jammed / Leaked / Burnt or	
Juli Historia	Brake: (norder/ Jammed / Leaked / Burnt or	
(Client's Record)	Modi: NII / \$/Rim/ / STD A/Rim or	
Make of Veh:	Tyre Size: F: 125/0	5/115
	Tyre size: P:	-
(Policy Condition) N/S N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OF	ITSU / PIR / SUMI /
Remark: The veh had commenced its N/S repair at the time of Inspection.	TOYO / YOKO or	1. WW. 1. 1. 113. T. W. 197. T.
repair at the time of mapeonon.	14/1	
Bal. or Market Value.	Front NEXEN Rear	2 -NE
IDAC Accident Rport: Consistent? : Yes or No	7	7
GIA / PR Seen: Consistent? : Yes or No		7.7
Est. Repairs: days Res.: Yes or No	D.O.A. 14/3/20 D.O.	
Lum Sum: % 3 Val.: Yes or No	72.77	n Ave. 0)
CA I REV I REP. I 24 HRS	Des. of Damages : Frt. / Rear / O/S / N/S /	U/C / Rooftop or
Vehicle	IN/OUT	re affected due to collision
Date:Person Contacted:	The U/C / Chassis frame / Body Structu	HE BROADE GOO TO COMBION
Date / Time Action / Instruction		
Submit PRS Report	PRS Ca	2-4
SHAMILL LES FEMAL	f -	
MV - 57000	RECEIVED 2 5 MAR 2020	
pv- 45200		
NV- 13806	i.	
Data/Time, File Pass tu7 : Preli. Report	Days Of Repair:	
		vey Fee: 100
1) : Final Report		reportation: 60
USANTAN PROBLEM NO	passeng	5+RS_SI
2)		otos
	and the same of th	hers
Reperformer:	Control of the Contro	
Lump Sum / LB.I: / F)	: Weel and (8	
	The state of the s	OTAL 160

Summer Lee (LKK Auto)

From:

Teo, Grace <grace.teo@sompo.com.sg>

Sent:

Monday, 16 March, 2020 4:34 PM

To:

Irene; Gnoh, Pau Loong; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com';

sur@lkkauto.com

Cc:

candy@iaconsultingsg.com; sile@iaconsultingsg.com

Subject:

CMTD2001157/GPL - PRI(LKK)/ SFN288S(NR) & SLU9330K ACC ON 14.03.20 SIMS

AVE / PAYA LEBAR ROAD ON 14.03.2020

Attachments:

doc00899120200316115126.pdf

Our Reference: CMTD2001157/GPL

Your Reference: SLU9330K

Date: 16/03/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S EVERDAWN AUTO SERVICE

Vener Ton 16/2/2004. Gam 16/2/2004. Gam

Dear Irene.

ACCIDENT INVOLVING SFN288S & SLU9330K ON 14.03.2020

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, LKK AUTO to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to LKK AUTO.

Please make the arrangement to survey for SLU9330K on a without prejudice and any admission of liability basis.

Please be informed that Mr. Gnoh Pau Loong is the handler of this case who can be contacted at 63295 217/ PauLoong.Gnoh@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now a





For Travel, Personal Accident & Home Insurance | For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Irene <motor@iaconsultingsg.com>
Sent: Monday, March 16, 2020 4:26 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Cc: candy@iaconsultingsg.com; sile@iaconsultingsg.com

Subject: RE: CMTD2001157/GPL - PRI/ SFN288S(NR) & SLU9330K ACC ON 14.03.20 SIMS AVE /

PAYA LEBAR ROAD ON 14.03.2020

Dear Grace.

We refer to your email below.

We regret to inform you that our client will not appoint any of the surveyors from your list provided in your email dated today.

However, we are pleased to provide below a list of ten surveyors for your consideration.

Gilbert Leow	Impact Analysis Consultant	
Andy Ho	Impact Analysis Consultant	
Shandy Loh	Impact Analysis Consultant	
Michael Yap	Mccoy Pte Ltd	
Joshua Ong	Delta-V Consultant	
James Ong	Delta-V Consultant	
Nick Ng	Delta-V Consultant	
Loo Yee Khang	Cozon Engineers	
Alex Teo	Cozon Engineers	
Denise Yap	Pal's Appraiser Pte Ltd	

Kindly let us know if you agree or disagree to appointing any of the above surveyors within the timeline stipulated under the NIMA protocol.

Thank you.

Regards, For and on behalf of Everdawn Auto Service Irene Tan

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Monday, 16 March 2020 4:07 PM

To: Irene; Gnoh, Pau Loong

Cc: candy@iaconsultingsg.com; sile@iaconsultingsg.com

Subject: CMTD2001157/GPL - PRI/ SFN288S(NR) & SLU9330K ACC ON 14.03.20 SIMS AVE / PAYA LEBAR ROAD ON

14.03.2020

Our Reference: CMTD2001157/GPL

Your Reference: SLU9330K

Date: 16/03/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S EVERDAWN AUTO SERVICE

Dear Irene,

ACCIDENT INVOLVING SFN288S & SLU9330K ON 14.03.2020

We refer to your Notice of Accident dated 16/03/2020.

Please be informed that Mr. Gnoh Pau Loong is the handler of this case who can be contacted at 63295 217/ PauLoong, Gnoh@sompo.com.sg .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2 LKK Auto Consultants	LKK Auto Consultants	Kenneth Kong (North area)	
	Marcus Chua (East area)		
	Mohd Rasul (West area)		
		Mohd Taufikh (West area)	
3 Priority	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Irene <motor@iaconsultingsg.com>
Sent: Monday, March 16, 2020 12:02 PM

To: Claims - Motor Survey < MotorSurvey@sompo.com.sg > Cc: candy@iaconsultingsg.com; sile@iaconsultingsg.com

Subject: ACCIDENT INVOLVING SIMS AVE / PAYA LEBAR ROAD ON 14.03.2020

Dear Sir.

attached herewith the Notification Of Accident for your reference.

Kindly let us have a list of your ten surveyors as your nominated SJE for our consideration within the stipulated timeline under the NIMA Protocol.

Best Regards, Irene Tan For and on behalf of Everdawn Auto Service Tel: 6385 1171

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

/ehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: /ehicle Details	893A
/ehicle No.:	SLU9330K
/ehicle to be Exported:	No
ntended Deregistration Date:	17 Mar 2020
/ehicle Make:	HYUNDAI
/ehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Beige
Manufacturing Year:	2017
ingine No.:	G4FGHU837182
Chassis No.:	KMHD841CMJU593601
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,900.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Fransfer Count:	0
Actual ARF Paid: ntended PARF Rebate Details	\$11,900.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2027
PARF Rebate Amount: ntended COE Rebate Details	\$8,925.00
COE Expiry Date:	18 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$36,275.00
Total Rebate Amount:	\$45,200.00

The information contained herein is correct as at 17 Mar 2020

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum









hyundai elantra

Price Range

* Depreciation

▼ Year Reg

▼ Vehicle Type

Photos

Map

Home = Used Cars = Taxis = Hyundai Elantra 1.6A GLS S

Hyundai Elantra 1.6A GLS S

Overview Financial Insurance Accessories Similar

Price

\$61,800

9000

Depreciation

\$7,500 /yr

Reg Date

04-Aug-2017

View models with similar depre-

29,855 km (11.4k /yr)

Manufactured

(7yrs 4mths 17days COE left)

Research

Mileage Road Tax

\$738 /yr

Transmission

2017 Auto

Dereg Value

\$42,166 as of today (change)

OMV

\$12,903

COE

\$44,002

ARF

Power

\$12,903

93.8 kW (125 bhp)

Engine Cap

1,591 cc 1,345 kg

No. of Owners



Type of Vehicle

Curb Weight

Mid-Sized Sedan

Features

Rear A/C, Rear Armrest With Cup Holders, 6speed Gearbox With New Refined Engine Means This Car Performs Quietly And Efficiently. View specs of the Hyundai Elantra (2016-2018)

Accessories

Daytime Running Lights, Touchscreen Audio, Apple Carplay With Bluetooth, Proximity Keyless Entry, Convenient Entry Lights At Side Mirrors Etc.

Description

100% Full Loan Available, 1 Owner, Interior Is Super Well Kept, New Car Smell Hits You When U Open The Door! Full Komoco Records, Averaging 13.5 Km/L. View This Superbly Kept Car Today!

Category

PARF Car

Status Available

Resources


ket value of your existing car for free, Get started











Shortlist Add oc Compare Report Error More Actions

Seller Information

1axis

53 vehicles for sale, 66 sold in past 3 mms.

O 5 Yishun Industrial Street 1 #01-18

MVA320032477 / VAC - Kirki Bukii ENTRY DATE & TIME: 14/03/2025 13/27 BUBMITTED BY: Normains Bits Abdul Masid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- fit. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	CMT	CTAT	44.0	ENT
ACCID			7	

Date Of Report 14/03/2020 13:27
Date Of Accident 14/03/2020 11:40

Exact Location Of Accident SIMS AVENUE / PAYA LEBAR ROAD

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU9330K

Insured/Policyholder

 Name Of Registered Owner
 YEO WEE KIM

 NRIC No
 SXXXX893A

 Email Address
 NOEMAIL

Mobile Phone No (LOCAL) +65-98783441

Alternative Phone No OFFICE-98763441

Vehicle Particulars

Manufacturer HYUNDAI

Model ELANTRA AD 1.6 GLS AT

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number D18MPC0003321_01 (COMP)

Cover Note Number

Driver

 Name of Driver
 YEO WEE KIM

 NRIC No
 SXXXX893A

 Date Of Birth
 22/12/1963

 Occupation
 INDOOR

 Date Of Driving Pass
 07/11/1981

Driving Experience 38 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98783441

Fax Number

Contact Number OFFICE-98783441

EMail Address NOEMAIL

Address

BLK 6 MARINE TERRACE #06-212

Postcode

440006

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

2

involved in the accident Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH OWNER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFN288S

Vehicle Make/Model/Colour

BMW 6401 GRAN COUPE 4DR SR LED DSC NAV HUD

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- I. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- fi. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that

- [4] My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (Rr) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/air permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and.
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their thint party service provides or agents/including their lawyers/law firms), which may be uted outside of Singapore, for one or more of the above Purposes.
- [d] my Personal information will also be collected and used to compile claims history for the purpose of fraud detection. Investigation and management in present and all future claims.
- (#) the information so collected under (d) above may be shared / disclosed.
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

late & Time:

1435

Driver's Signature

(if driver is not the policyhilder)

Date & Time:

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Singapore 415933 Tel: 67416697 Fax: 67492305

Email: vacktr@vicom.com.sq

Reporting Centre Personnel's Signature

NRICITIN No.

Sketch Plan #2

PLA	1	
SKETCH PLAN	Raga lebor Rel	
	sam I di sins Ave	toward to change Rel
Gren light white	Behind Car (BANWSF	H2885 Black Enloy) hit
DECLARATION (/We declare the foregoing particul		IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 #02-02 Singapora 415933 Tel: 67416697 Fax: 67492305 Email: vackb@vicom.com.eg
Date & Time 14/3 3010 13/55	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRXC/FIN No.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 8258 3581 FAX: 6258 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL C53/SMO20004070/Htf3e2 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND Date: 25-03-2020 TOWERSINGAPORE 048623 Code: SMO Policy Particulars :- (THIRD PARTY CLAIM) SFN 288S SLU 9330K Insured Veh. Veh. Inspected Policy No. Coverage (\$) 0.00 CMTD2001157/GPL 0.00 Claim No. Excess (\$) Assign From GRACE TEO Assign Date 16/03/2020 Vehicle Particulars & Condition Make & Model HYUNDAI ELANTRA 1591 C.C HIDDEN 2017 Engine No. Year of Reg. Chassis No. KMHD841CMJU593601 BEIGE Colour 15540 KM IN ORDER Odometer Steering IN ORDER SPORTS RIM Brakes Modification GOOD General Conditions of Tyres Size Make Balance 195/65 R15 NEXEN 7 mm R/H Front Tyre 195/65 R15 NEXEN L/H Front Tyre 7 mm NEXEN 7 mm R/H Rear Tyre 195/65 R15 195/65 R15 NEXEN 7 mm L/H Rear Tyre **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. General Information Inspect Date / Time 14/03/2020 17/03/2020 (02:02 PM) Accident Date **EVERDAWN AUTO SERVICE** Survey held at 8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500 5b. Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/SMO20004070/Htf3e2

Inspected By

LEE HOCK ANN

بصالا

LEE HOCK ANN

Asst. Automotive Assessor

Tu

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No. liability of responsibility whatsoever, in posted or bort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does no at his or her own risk.