

000

200. +  
200. +  
296.88 +  
120. +  
816.88

x  
80. %  
653.504 \*

## Section A - Accident Details

Registration Number	SHB459E
Case Reference Number	TAX/03/20/2039
Registration Date	4/2/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	GOH BOON HENG ANDY (WU WENXING)
Type of Accident	Head to Rear
Accident Date and Time	13/3/2020 4:25 PM
Accident Reported Date and Time	14/3/2020 11:59 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106159
Special Instruction to ARC, if any	TP / DROVE IN/ NTUC - LKK
Prepared Date and Time	16/3/2020 2:26 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$2,171.39	\$120.00
Total Other Cost	\$656.88	\$130.00
TOTAL COST	\$3,724.27 <b>4297.38</b>	\$650.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	16/03/2020 5:10 PM	16/03/2020 4:55 PM
Signature		
Remarks		Lump Sum Repair, After paint photo.