

22/03/2002

ASS. REC. BY:

REF:

CS3
ESTCT1 20004172 / Psf32k

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Adeline chng Ai Wen

of CTI

Date/Time: 18.3.2020 11.09.11

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 64334

Insured:

GBG 2695

at Workshop m/s

Provident Automobile

Tel:

94505599

of 11 KAT Bukit Road 1 1103-09

Policy No: DMICVSR 30800519033

Claim No:

SNM 201720130002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10.3.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 18.3.2020 11.20.00

Person Contacted:

Malcolm

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJY 64334 - NA / MC17019937/24 PCA - 17/10/2017
	GBG 2695 - NA / CT1 K015564129 PCA - 02/09/2019
3/03/20	@ 16:38 pm checked with Malcolm, no estimate.

Meningan

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SSV 64330at Workshop m/s BKTH Providence Automobileof 11 Kaki Bukit Road 1 #03-08

Insured:

Policy No.:

Claims No.:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SSV 64330Yr Regn: 20/9/2010Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish 2.0c.c. 1987

Colour:

GreyA/C: Insured / Std / NI / NA

Sp. Reading:

140675T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTIGJ20W8C5003243Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215 / 60 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

10/03/2020

D.O.I.

18/03/2020

Survey held at

Providence automobileDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$8000 - \$10000/-
	Repair days: <u>12</u> days
	<u>3/3/2020</u>
	MV: <u>\$17000 - \$21,000</u>
	PV: <u>\$13146</u>
	NV: <u>\$7854/-</u>

Date/Time, File Pass to?

01/04/20

1)

Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 12Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

PRS

Lump Sum / L&A: \$

190190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Mar 2020		18 Mar 2020 11:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	S.A ASIA INTERNATIONAL PTE. LTD., Co. Reg. No.: 201608987E		
Vehicle Reg. No.:	SJY6433U	Date of Loss:	10/03/2020 18:00 - :59
Claim Type:	TP / SNM20D201300C02	Policy/Cover Note No.:	DMCVSN30800519033
Vehicle Reg. No. (Insured):	GBE269S	Policy No. (Claimant):	5115868404 TPFT
		Excess:	S\$0.00
Repairer:	Providence Automobile Pte Ltd (HQ) 11 KAKI BUKIT ROAD 1 #03-08 EUNOS TECHNOLINK, 415939 Kaki Bukit - Tel: 94505599		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pel Wen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/03/2020]		
Adj Asg. Remarks:	survey revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Wednesday, 18 March, 2020 10:56 AM
To: Izhar; assignments
Cc: pva.ins@hotmail.com
Subject: RE: OUR REF: SNM20D201300 /GBE269S/ADELINE - ACCIDENT INVOLVING MOTOR VEHICLES SJY 6433 U AND GBE 269 S ALONG CTE ON 10 MARCH 2020

Dear Sirs

We refer to your email of even date.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK AUTO CONSULTANTS PTE LTD to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6225 5879

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Izhar [mailto:izhar@chiaarul.com]
Sent: Wednesday, 18 March 2020 10:38 AM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>
Cc: pva.ins@hotmail.com
Subject: RE: OUR REF: SNM20D201300 /GBE269S/ADELINE - ACCIDENT INVOLVING MOTOR VEHICLES SJY 6433 U AND GBE 269 S ALONG CTE ON 10 MARCH 2020
Importance: High

Dear Adeline,

We refer to the above matter and your email of even date.

We are not agreeable to your proposed surveyors therein.

In the premises, we propose the surveyor, Mr Tommie from Vicom as the Single Joint Expert.

Kindly revert on the same soonest hereof.

Regards,

Mr Izhar

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Adeline Chng [<mailto:adeline.chng@sg.cntaiping.com>]

Sent: Wednesday, March 18, 2020 1:03 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Izhar <izhar@chiaarul.com>

Cc: pva.ins@hotmail.com

Subject: RE: OUR REF: SNM20D201300 /GBE269S/ADELINE - ACCIDENT INVOLVING MOTOR VEHICLES SJY 6433 U AND GBE 269 S ALONG CTE ON 10 MARCH 2020

Our reference: SNM20D201300C02/ GBE269S/Chngpw

Your reference: SJY6433U

Dear Sirs

ACCIDENT INVOLVING GBE269S & SJY6433U ON 10/03/2020

We refer to your email of 17/03/2020

Kindly note the following:-

1. We would like to conduct pre-repair survey of the vehicle at the appointed workshop.
2. We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE

4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

3. If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.
4. As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.
5. As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact Adeline Chng at 63896155 and email us at claimsdept@sg.cntaiping.com

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, 17 March 2020 11:19 PM

To: Izhar <izhar@chiaarul.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>

Cc: pva.ins@hotmail.com; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201300 /GBE269S/ADELINE - ACCIDENT INVOLVING MOTOR VEHICLES SJY 6433 U AND GBE 269 S ALONG CTE ON 10 MARCH 2020

Dear Adeline,

Please conduct PRS for SJY6433U.

Note : officer in charge – Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Izhar <izhar@chiaarul.com>

Sent: Tuesday, March 17, 2020 5:43 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: pva.ins@hotmail.com

Subject: ACCIDENT INVOLVING MOTOR VEHICLES SJY 6433 U AND GBE 269 S ALONG CTE ON 10 MARCH 2020

Dear Sirs,

We act for S.A Asia International Pte Ltd, the owner of motor vehicle SJY 6433 U which have appointed us to act on their behalf to claim against your insured's vehicle no. GBE 269 S in regards to the road traffic accident on 10 March 2020.

Please be informed that the said motor vehicle can be inspected at:-

**Providence Automobile Pte Ltd
Blk 11 Eunost Technolink
Kaki Bukit Road 1 #03-08
Singapore 415939**

Kindly contact Mr Malcolm at 9450 5599 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,

Mr Izhar

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	987E
Vehicle Details	
Vehicle No.:	SJY6433U
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 2.0 AUTO
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	3ZRA518126
Chassis No.:	JTDGJ20W805003243
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,003.00
Original Registration Date:	20 Sep 2010
First Registration Date:	20 Sep 2010
Transfer Count:	3
Actual ARF Paid:	\$22,003.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2020
PARF Rebate Amount:	\$11,001.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$42,901.00
COE Rebate Amount:	\$2,145.00
Total Rebate Amount:	\$13,146.00

The information contained herein is correct as at 19 Mar 2020

OK

63



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



TOYOTA WISH 2.0

Price Range

Depreciation

2010

Vehicle Type

Advanced Search

Home » Used Cars » Direct Owners » Toyota Wish 2.0A

Toyota Wish 2.0A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price \$17,900

Depreciation N.A. Reg Date 24-Mar-2010 (4days COE left)

Mileage 125,000 km (12.5k /yr) Manufactured 2010

Road Tax \$1,198 /yr Transmission Auto

Dereg Value \$11,028 as of today (change) OMV \$22,003

COE \$23,889 ARF \$22,003

Engine Cap 1,987 cc Power 106.0 kW (142 bhp)

Curb Weight 1,380 kg No. of Owners 2

Type of Vehicle MPV

GET YOUR
COE
RENEWAL
LOAN

Shortlist

Compare

Add note

Report Error

More Actions

Features

Great Condition, Will Include Interior And Exterior Grooming For The Deal. New Engine Mounting, Perfect Interior. Newly Replaced Steering Wheel. View specs of the Toyota Wish (2009-2018)

Accessories

With New 5 Or 10 Years COE Added It's Still The Cheapest.

Description

Will Trade With Other Car. Loan Available.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Seller Information

Contact Person(s) Ben

Contact No. 96355515

Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» Ownership Transfer

GET HELP WITH
PAPERWORKsgCARMART
CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers & Sellers

Posted on: 09-Mar-2020 | Last Updated on: 09-Mar-2020

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment N.A. (change)

Maximum 70% Loan

1st Instalment N.A.

Based on 2.98% interest rate

Insura

\$657 onwards (Get a quote)

Compare

Extra 15% Off for MINDEF, MHA & POGIS policyholders

Powered by

AVIVA

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/03/2020 12:24
 Date Of Accident 10/03/2020 18:50
 Exact Location Of Accident CTE TOWARDS AYE (TUAS) BEFORE BUKIT TIMAH EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJY6433U
Insured/Policyholder
 Name Of Registered Owner S.A ASIA INTERNATIONAL PTE. LTD.
 Co Reg No 2XXXXX987E
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No Office-81330068
Vehicle Particulars
 Manufacturer TOYOTA
 Model WISH 2.0 AUTO
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number 5115868404 TPFT
 Cover Note Number
Driver
 Name of Driver HABIB MOHAMED BIN OMAR KHATHA
 NRIC No SXXXX064B
 Date Of Birth 14/07/1973
 Occupation OUTDOOR
 Date Of Driving Pass 21/01/1994
 Driving Experience 26 YEARS AND 1 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-81383595

Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 863B TAMPINES STREET 83 #03-462
Postcode	522863
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : HABIB MOHAMED BIN OMAR KHATHA Gender: : Male
Passenger 2	Name: : NOOR SARMILA BEGAM BTE ARIFF OMAR Gender: : Female
Passenger 3	Name: : MOHAMED MIKHAIL SIRHAN BIN HABIB MOHAMED Gender: : Male
Passenger 4	Name: : MOHAMED QAISER SIRHAN BIN HABIB MOHAMED Gender: : Male

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE269S

Vehicle Make/Model/Colour

HYUNDAI / H1 STAREX 2.5 CRDI MT ABS AIRBAG 2WD

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

HABIB MOHAMED BIN OMAR KHATHA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJY6433U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

NOOR SARMILA BEGAM BTE ARIFF OMAR

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJY6433U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

MOHAMED MIKHAIL SIRHAN BIN HABIB MOHAMED

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJY6433U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 4

Name

MOHAMED QAISER SIRHAN BIN HABIB MOHAMED

Approximate Age

Injuries Sustain

3/19/2020

E-FILE

Injured person in which vehicle?

SJY6433U

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAN DUNIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
m.com.sg
Reporting Centre Personnel's Signature
Name:
NRUC/FIN No.:

14 MAR 2020

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for describing the circumstances of the accident. A diagonal line is drawn across the middle, and the text 'Please See Attached' is written diagonally across it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IOAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Reporting Centre Personnel's Signature
Name: vankh@vicom.com.sg
NRUC/FIN No.:

14 MAR 2020

Sketch Plan #3

On 10/03/2020 @ about 1845hrs I was driving my vehicle, SJY6433U, along CTE towards AYE(Tuas). At the location before Bt Timah Rd Exit, the front traffic was slowing down. I also slowed down my vehicle.

All of a sudden, I heard a very loud bang and felt impact coming from the rear of my vehicle. I then realised that one vehicle, GBE269S had hit on to the rear part of my vehicle. The rear part of my vehicle were damage.


I, my wife and my son was conveyed to the Tan Tock Seng Hospital. My another one son was conveyed to KK Hospital.

That's all.

HABIB MOHAMMED
87327064B

F. SJY6433U

B. GBE269S



HABIB MOHAMMED
87327064B

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20200313/7020

1 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20200313/7020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/03/2020 16:24		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: HABIB MOHAMED BIN OMAR KHATHA			Address: APT BLK 863B TAMPINES STREET 83 #03-462 SINGAPORE 522863		
ID Type / ID No.: NRIC NO / S7327064B			Contact No.: Home/Office:		Mobile: 81383595
Nationality: SINGAPORE CITIZEN			Email: pva.ins@hotmail.com		
Sex: Male	Age: 46	Date of Birth: 14/07/1973	Type of Informant: Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: Driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/03/2020 18:50	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJY6433U	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20200313/7020

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200313/7020

CONTINUATION OF REPORT

Driver			
Name	HABIB MOHAMED BIN OMAR KHATHA	ID No.	S7327064B
Related Vehicle	SJY6433U (Car)	Contact No.	81383595
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	10/03/2020	Date Discharge	10/03/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Son			
Name	MOHAMED QAISER SIRHAN BIN HABIB MOHAMED	ID No.	T0121628C
Related Vehicle	SJY6433U (Car)	Contact No.	91079858
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Son			
Name	MOHAMED MIKHAIL SIRHAN BIN HABIB MOHAMED	ID No.	T0606944J
Related Vehicle	SJY6433U (Car)	Contact No.	91079858
Hospital/Clinic	KK WOMEN'S AND CHILDREN'S HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/03/2020	Date Discharge	10/03/2020
No. of Days granted Medical Leave	06	Degree of Injury	Slight
Wife			
Name	NOOR SARMILA BEGAM BINTE ARIFF OMAR	ID No.	S7332765B
Related Vehicle	SJY6433U (Car)	Contact No.	91079858
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/03/2020	Date Discharge	10/03/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Individual Statement



SINGAPORE
POLICE FORCE



T/20200313/7020

3 of 4

Police Station Of Origin
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20200313/7020

CONTINUATION OF REPORT

Brief Details.

On 10/03/2020 @ about 1845hrs I was driving my vehicle, SJY6433U, along CTE towards AYE(Tuas). At the location before Bt Timah Rd Exit, the front traffic was slowing down. I also slowed down my vehicle.

All of a sudden, I heard a very loud bang and felt impact coming from the rear of my vehicle. I then realised that one vehicle, GBE269S had hit on to the rear part of my vehicle. The rear part of my vehicle were damage.

I, my wife and my son was conveyed to the Tan Tock Seng Hospital. My another one son was conveyed to KK Hospital.
That's all.

Individual Statement



SINGAPORE
POLICE FORCE



T/20200313/7020

4 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408855
Tel No: 65470000

Report No: T/20200313/7020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/03/2020 16:24
Officer In Charge Of Case: TP / TPHQ / ONG CHEE HIEN Contact No.: 65476437	Classification Of Case:
Authentication Stamp NP168	

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2020		18 Mar 2020 11:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: S.A ASIA INTERNATIONAL PTE. LTD., Co. Reg. No.: 201608987E									
Vehicle Reg. No.: SJY6433U		Date of Loss: 10/03/2020 18:00 - :59 [113 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D201300C02		Policy/Cover Note No.: DMCVSN30800519033							
Vehicle Reg. No. (Insured): GBE269S		Policy No. (Claimant): 5115868404 TPFT							
		Excess: S\$0.00							
Repairer: Providence Automobile Pte Ltd (HQ) 11 KAKI BUKIT ROAD 1 #03-08 EUNOS TECHNOLINK, 415939 Kaki Bukit - Tel: 94505599									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 27/03/2020]									
Adj Asg. Remarks: survey revert									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY6433U (SNM20D201300C02)
[GBE2695]
TP
S.A ASIA INTERNATIONAL PTE. LTD.
Mar 10 2020 6:00PM
[-]
Providence Automobile Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
2	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
3	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
4	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
5	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
6	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
7	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
8	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
9	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
10	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
11	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
12	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
13	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
14	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
15	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
16	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
17	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
18	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
19	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
20	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
21	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
22	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
23	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
24	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
25	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
26	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
27	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
28	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
29	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
30	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
31	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
32	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
33	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
34	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
35	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
36	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	
37	26/03/20 11:00	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
56	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
57	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
58	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
59	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
60	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
61	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
62	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
63	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
64	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
65	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
66	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
67	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
68	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
69	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
70	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
71	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
72	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
73	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
74	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
75	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
76	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
77	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
78	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
79	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
80	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
81	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
82	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
83	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
84	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
85	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
86	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
87	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
89	26/03/20 11:00	General View	 Load JPG	<input checked="" type="checkbox"/>
90	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
117	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
118	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
119	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
120	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
121	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
122	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
123	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
124	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
125	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
126	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
127	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
128	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
129	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
130	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
131	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
132	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
133	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
134	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
135	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
136	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
137	26/03/20 11:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
139	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
140	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
141	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
142	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
143	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
144	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
145	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
146	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
147	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
148	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
149	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
150	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
151	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
152	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
153	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
154	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
155	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
156	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
157	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>
158	26/03/20 11:01	Dismantled Parts	1 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	14/03/20 12:33	Accident Statement	1 Load HTM	
Photos/Images			3 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
2	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
3	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
4	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
5	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
6	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
7	14/03/20 12:31	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	14/03/20 12:32	Sketch Plan	1 Load JPG	<input checked="" type="checkbox"/>
2	14/03/20 12:32	Sketch Plan #2	1 Load JPG	<input checked="" type="checkbox"/>
3	14/03/20 12:32	Sketch Plan #3	1 Load JPG	<input checked="" type="checkbox"/>
4	14/03/20 12:32	Individual Statement	1 Load JPG	<input checked="" type="checkbox"/>
5	14/03/20 12:32	Individual Statement	1 Load JPG	<input checked="" type="checkbox"/>
6	14/03/20 12:32	Individual Statement	1 Load JPG	<input checked="" type="checkbox"/>
7	14/03/20 12:32	Individual Statement	1 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20004172/FSF3E2
Date: 03/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30800519033
Claimant Vehicle No :	SJY6433U	Insured Vehicle No :	GBE269S
Date of Loss:	10/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201300C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6433U	Engine No:	3ZRA518126
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20W805003243
Reg. Date:	20/09/2010 (Man. Year: 2010)	Odometer:	140675 km
Colour:	Grey		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	West Lake 8 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 8 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/03/2020	
Date Inspected:	18/03/2020 Inspected At:	Providence Automobile Pte Ltd (HQ) 11 KAKI BUKIT ROAD 1 #03-08 EUNOS TECHNOLINK Singapore 415939
Estimated Period of Repair:	12.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	M1-MPV	TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY6433U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >