

ASS. REC. BY:

REF:

es / AIG 20004176 / Eyd3

Special Instruction:

Surveyor: Steve

Mentmen

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

18/3/2020 12:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GV 657 G

Insured:

GW 5402L

at Workshop m/s

My car consultant

Tel:

8866 8832

of

53 ubi Avenue # 01-33

Policy No:

Claim No:

654191364356

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

06/03/2020

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement:

Date/Time:

12:29pm 18/3/2020

Person Contacted:

Hui Qin

Vehicle

IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	GV 657 G - NA / CTI 17000-131 / r3	D.O.A. 7/1/2017
	GW 5402L - X	

ASS. REC. BY:

Steve

REF:

AIG CS3 / AIG 20004176 / Eyd3

PRS

ASSIGNMENT

From:

Date:

18.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GV 657G

at Workshop m/s

my car consultant

of

53 Ubi Ave / #01-33 Baya Ubi Industrial

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GV 657G

Yr Regn:

30/10/91

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi L300

c.c 2477

Colour

Belge

A/C:

Insured / Std / NI / NA

Sp. Reading

385265

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMAJN PIS VYA-001512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185R14C

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

6/3/20

D.O.I.

18/3/20

Survey held at

My Car Consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-6500

Total loss - Beyond Economical Repair

PV-5252

NV-1248

6/4

Submit extensive total loss report.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

6/4/20 Typist

Days Of Repair:

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ = RS. \$1

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / L.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: 'assignments', Nivitha (LKK Auto)
Cc: Lim, Kok-Chong
Sent: 3/18/2020 12:22:52 PM
Attachments:  [GV657G GIA REPORT.PDF.PDF](#)

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: My Car Consultant [<mailto:admin@mycar.sg>]
Sent: Tuesday, March 17, 2020 2:06 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] OUR REF: GV657G YOUR REF: GW5402L PRE-REPAIR INSPECTION FOR GV657G

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

OUR REF: GV657G
YOUR REF: GW5402L

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR GV657G
ACCIDENT INVOLVING GV657G AND GW5402L

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Best Regards,

Huiqin
Claims | My Car Consultant Pte Ltd

+65 88668832

Error! Admin@mycar.sg

Filename

not

specified.

Error!

Filename

not Mycar.sg

specified.

Error!

Filename

not 53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

specified.

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 221C

Vehicle Details

Vehicle No.: GV657G

Vehicle to be Exported: No

Intended Deregistration Date: 18 Mar 2020

Vehicle Make: MITSUBISHI

Vehicle Model: L300 P/VAN

Primary Colour: Beige

Manufacturing Year: 2001

Engine No.: 4D56KG1306

Chassis No.: JMAJNP15VYA001512

Maximum Power Output:

-

Open Market Value: \$13,888.00

Original Registration Date: 30 Oct 2001

First Registration Date: 30 Oct 2001

Transfer Count: 0

Actual ARF Paid: \$695.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$32,564.00

COE Rebate Amount: \$5,252.00

Total Rebate Amount: \$5,252.00

The information contained herein is correct as at 18 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2020 11:07
Date Of Accident	06/03/2020 11:40
Exact Location Of Accident	SUNGEI KADUT STREET 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GV657G
Insured/Policyholder	
Name Of Registered Owner	FOO KEE SENG
NRIC No	SXXXX221C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97397316
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	L300
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMCG19010552
Cover Note Number	

Driver

Name of Driver	NG KIM HUAT
NRIC No	SXXXX245J
Date Of Birth	17/03/1948
Occupation	OUTDOOR
Date Of Driving Pass	27/03/1968
Driving Experience	51 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97397316
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 269 TAMPINES STREET 21 #09-193
Postcode	1852
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT REF NO: T/20200309/2038

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW5402C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG KIM HUAT

Approximate Age

Injuries Sustain

Injured person in which vehicle? GV657G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as or the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITY AUTO PTE LTD
818 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 4233 Fax: 6453 7944
(Claims Section)


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Sketch Plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

City Auto Pte Ltd

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 4234 Fax: 6453 7944
(Claims Section)

Police report



SINGAPORE
POLICE FORCE



T/20200306/2038

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529552
Tel No: 1800-5371909

Page 3
Report No: T/20200306/2038

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/03/2020 12:07	Vide Report No.: L/20200306/0080	Station Diary No.: 16
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: NG KIM HUAT			Address: APT BLK 269 TAMPINES STREET 21 #09-193 SINGAPORE 520269	
ID Type / ID No.: NRIC NO / S0970245J			Contact No.: Home/Office: Mobile: 97397316	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 71	Date of Birth: 17/03/1948	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 06/03/2020 11:40	Type of Location: Straight Road
Location: Along Road 1 SUNGEI KADUT STREET 1 SUNGEI KADUT DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GV657G	Van				Slightly Damaged	0
GW5402L	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

Police report



**SINGAPORE
POLICE FORCE**



T/20200309/2038

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20200309/2038

CONTINUATION OF REPORT

Driver			
Name	NG KIM HUAT	ID No.	S0976245J
Related Vehicle	GV657G (Van)	Contact No.	97397316
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	06/03/2020	Date Discharge	07/03/2020
No. of Days granted Medical Leave	10	Degree of Injury	Slight
Driver			
Name	LOW SENG HUAT	ID No.	S0220587D
Related Vehicle	GW5402L (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 6/3/2020 at about 1140hrs, I was driving my van bearing GV657G along Sungai Kadut Street 1. As I was heading towards Sungai Kadut Drive, suddenly there was a lorry bearing GW5402L that had exited from 62 Sungai Kadut Street 1 and cut across my lane. As a result, I braked but could not avoid and ended up hitting into the left rear portion of the lorry.

Ambulance came and conveyed me to Ng Teng Fong General Hospital where I was warded for 1 day till 7/3/2020. I was given hospitalization leave from 6/3/2020 till 15/3/2020. I had right arm numbness and pain in my right chest as the steering wheel hit my right chest.

As such, I am lodging a traffic accident report.

Police report



SINGAPORE
POLICE FORCE



TZ0200309/2038

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No: TZ0200309/2038

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 NURHIDAYAH BINTE IADIL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 09/03/2020 12:07
Officer In Charge Of Case: TP / GIT / Staff Sgt TAN JUN YAN Contact No.: 65476311	Classification Of Case:
Authentication Stamp NP166	

Front Portion

10 repair dys

CON AC DY

MAC	INC	Item	CON	AC	DY
1001	991236	Fit Bumper Plate			
1002	991237	Fit Bumper Plate Edge			
1003	991239	Fit Bumper Plate Garnish			
1004	991240	Fit Bumper	BR	✓	
1005	992141	Fit Bumper Clip			
1006	991242	Fit Bumper Bracket			
1007	991462	Fit Bumper Side Retainer			
1008	991433	Fit Bumper Reinforcement	DO	✓	
1009	991318	Fit Bumper Beam			
1010	991468	Fit Bumper Sponge			
1011	991427	Fit Bumper Protector			
1012	991420	Fit Bumper Pad			
1013	991363	Fit Bumper Grille			
1014	991301	Fit Bumper Moulding			
1015	991402	Fit Bumper Lower Spoiler			
1016	991438	Fit Bumper Sensor			
1017	995100	Fit LH Bumper Fog Lamp Cover			
1018	991355	Fit RH Bumper Fog Lamp Cover			
1019	995079	Fit LH Bumper Fog Lamp			
1020	995080	Fit RH Bumper Fog Lamp			
1021	991293	Fit Grille			
1022	991328	Fit Grille Emblem	NR	✓	
1023	991299	Fit Grille Chrome Moulding			
1024	991222	Fit Apron Panel			
1025	992013	Fit Support Panel	DO	✓	
1026	992025	Fit Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fit Brace Panel			
1029	995153	Fit LH Headlamp Assy			
1030	991821	Fit RH Headlamp Assy	BR	✓	
1031	995088	Fit LH Side Lamp			
1032	995089	Fit RH Side Lamp	BR	✓	
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990105	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990129	Air Con Liquid Pipe			
1049	990160	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	990394	Air Con Belt			
1052	990474	Radiator			
1053	990738	Radiator Covering			
1054	990712	Radiator Fan Assy			
1055	990745	Radiator Fan Clutch			
1056	990758	Radiator Hose Top			
1057	990757	Radiator Hose Bottom			
1058	990741	Radiator Expansion Tank			
1059	990111	Air Filter			
1060	990474	Air Cleaner Assy			
1061	990476	Air Cleaner Hose			
1062	990479	Air Cleaner Resistor			
1063	990712	Fit Exhaust Muffler			
1064	990711	Fit Exhaust Muffler Cover			
1065	990714	Fit Exhaust Muffler Support Bracket			
1066	990711	Exhaust Muffler Pipe			
1067	990719	Exhaust Pipe			
1068	990719	Exhaust Pipe			

front RH Door

front RH Door trim

front RH pillar

DO ✓

TAI ✓

DO ✓

CON AC DY

MAC	INC	Item	CON	AC	DY
1071	992295	Purge Valve			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990910	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Pin			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Pin			
1091	991234	Gear Box Mounting			
1092	991520	Fit LH Chassis Member			
1093	991520	Fit RH Chassis Member			
1094	990728	Fit Vertical Cross Member			
1095	991863	Fit Lower Cross Member			
1096	995070	Fit LH Fender			
1097	995072	Fit LH Fender Inner Panel			
1098	995147	Fit LH Fender Lamp			
1099	995148	Fit LH Fender Protector			
1100	991740	Fit LH Fender Inner Shield			
1101	995179	Fit LH Mudflap			
1102	995170	Fit LH Wheel Rim			
1103	994025	Fit LH Rim Cover			
1104	995065	Fit LH Tyre			
1105	995071	Fit RH Fender	DO	✓	
1106	991719	Fit RH Fender Inner Panel			
1107	991744	Fit RH Fender Lamp			
1108	991752	Fit RH Fender Protector			
1109	991740	Fit RH Fender Inner Shield			
1110	991334	Fit RH Mudflap			
1111	992087	Fit RH Wheel Rim			
1112	994025	Fit RH Rim Cover			
1113	995065	Fit RH Tyre			
1114	992091	Fit Windscreen Filler	BR	✓	
1115	992117	Fit Windscreen Rubber			
1116	995102	Fit Windscreen Moulding			
1117	995096	Fit Windscreen Sealant			
1118	991049	FFP Bracket	NR	✓	
1119	991030	FFP Unit			
1120	995140	Fit Wiper Arm			
1121	995142	Fit Wiper Blade			
1122	995085	Wiper Panel Garnish			
1123	991126	Front Wall Panel			
1124	990733	Dashboard Assy	CRU	✓	
1125	990732	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	991483	Steering Wheel Anchor			
1128	994485	Steering Wheel Airbag Sensor			
1129	994749	Dashboard Airbag			
1130	990740	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990364	Fit Driver Seat			
1133	991927	Fit RH Seat Belt Assy			
1134	991929	Fit Passenger Seat			
1135	995143	Fit LH Seat Belt			
1136	990711	Anchor			

front RH Headlamp garnish

front RH wheelarch panel

BR ✓

DO ✓