

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3350D
 MAKE :
 MODEL I-40

DATE 16/03/2020
 CHIANG/NTUC

L KEE
CREMANA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER <i>repair</i>			\$1,052.20
1	FRT BUMPERBUMPER BRACKET SIDE LH <i>X</i>			\$24.60
1	FRONT BUMPER RETAINER MTG LH <i>X</i>			\$22.40
1	FRT FENDER SHIELD LH <i>X</i>			\$174.90
1	WHEEL HUB -CAP LH <i>X old damage</i>			\$107.10
1	LH REAR WING MIRROR <i>scr</i>			\$670.00
1	FRT LH FENDER <i>st</i>			\$663.00
1	LH HEADLAMP ASSY <i>scr</i>			\$1,388.00
	SUB TOTAL			\$4,102.20
	20.00%			\$820.44
	DISCOUNTED TOTAL			\$3,281.76
	Labour Charge			
	Panel Beating		380 500	\$500.00
	Spray Painting Charge		500 600	\$600.00
	Tuff Kote		40	\$60.00
	Check Lighting		30	\$60.00
	TOTAL LABOUR			\$1,220.00
	ESTIMATE TOTAL			\$4,501.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Rasul
Hp 90010068
3 days
4/5
17/03/2020 @ 1200 hrs
Resing after repair

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
15 Panke Road Singapore 200886
320 Ubi Road Singapore 408549

24 Senoko Loop Singapore 758156
7 Sungai Kadut Way Singapore 728791
50 Behun Industrial Estate Singapore 68873

Date/Time: 16.03.2020 16:36 Page: 1


A member of COMFORTDELGRO

<p>Team: ARC Repair TP (CLSO)</p> <p>Customer: COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755</p> <p>(R) (O) (P)</p> <p>COUNT CARD NO.</p>	<p>JOB CARD</p>	<p>Sales Order: 305387829</p> <p>JC NO.: 305387829</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>REGN NO.: SHD3350D</td> <td>MILEAGE</td> </tr> <tr> <td>MAKE: HYUNDAI</td> <td>FUEL</td> </tr> <tr> <td>MODEL: I-40</td> <td>E: 1/2 F: 1/2 DATE/TIME IN: 16.03.2020 13:25</td> </tr> <tr> <td>YR OF MANU.: 21.07.2016</td> <td>TARGET DATE</td> </tr> <tr> <td>CHASSIS CODE: KMHLB41UMGU092192</td> <td>COMPLETION DATE/TIME:</td> </tr> </table>	REGN NO.: SHD3350D	MILEAGE	MAKE: HYUNDAI	FUEL	MODEL: I-40	E: 1/2 F: 1/2 DATE/TIME IN: 16.03.2020 13:25	YR OF MANU.: 21.07.2016	TARGET DATE	CHASSIS CODE: KMHLB41UMGU092192	COMPLETION DATE/TIME:
REGN NO.: SHD3350D	MILEAGE											
MAKE: HYUNDAI	FUEL											
MODEL: I-40	E: 1/2 F: 1/2 DATE/TIME IN: 16.03.2020 13:25											
YR OF MANU.: 21.07.2016	TARGET DATE											
CHASSIS CODE: KMHLB41UMGU092192	COMPLETION DATE/TIME:											

Accident Date: 16.03.2020
ATTURE: 3P 16.03.2020

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

Wedge Slip

Vehicle No.: SHD3350D CHIANG

Signature/Date

of Service Advisor

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SHD3350D

Name of Service Advisor

Date

To be kept by Security Guard