

PERSONAL

ASS. REC. BY:

REF: CS3/AIG 20004203/Eqd301

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Teo Eric wei hong

of AIG

Date/Time: 18/3/2020 10:06am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX10024

Insured:

SKM 96054

at Workshop m/s

Teamwork Garage

Tel:

68442475

of

53 Ubi Avenue 1 #01-24

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/03/2020

CA / REV / REP. / REV 24 HRS

(up)

Date/Time: 10:17am 18/3/2020

Person Contacted:

James

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

SLX10024 - NA / AIG 20004085/24

DVA: 15/03/2020

SKM 96054 - NA / AIG 20004085/24

DOA: 15/03/2020

18/3/20

Submit DR

RECEIVED 18 MAR 2020

ASS. REC. BY:

Steve

REF:

AIG CS3 / AIG 20004203 / Egd3

PRS

ASSIGNMENT

From:

Date:

18.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 1002 U

at Workshop m/s TEAMWORK

of 53 Ubi Ave 1 #01-24

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

'up'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX 1002 U

Yr Regn:

16/3/18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato K3

c.c.

1591

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

47856

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNA F2411 MJS 76741

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

c1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

15/3/20

D.O.I.

18/3/20

Survey held at

Teamwork

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK- 62K

Date/Time, File Pass to?

☐

: Preli. Report

1) 19/3 14:30

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

180

11

191

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

MER-DAR

Lump Sum / I.B.J. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	439Z
Vehicle Details	
Vehicle No.:	SLX1002U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2020
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4FGHH691700
Chassis No.:	KNAFZ411MJ5761741
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$15,188.00
Original Registration Date:	16 Mar 2018
First Registration Date:	16 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$15,188.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2028
PARF Rebate Amount:	\$11,391.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$29,406.00
Total Rebate Amount:	\$40,797.00

The information contained herein is correct as at 18 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2020 19:41
Date Of Accident	15/03/2020 16:25
Exact Location Of Accident	EUNOS LINK TWDS HOUGANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX1002U
Insured/Policyholder	
Name Of Registered Owner	CHAN HUA ENG
NRIC No	SXXXX439Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91993968
Alternative Phone No	OFFICE-91993968

Vehicle Particulars

Manufacturer	KIA
Model	CERATO K3 1.6A SUNROOF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023811
Cover Note Number	

Driver

Name of Driver	CHAN YI QIN TIFFANY
NRIC No	SXXXX472A
Date Of Birth	28/09/1995
Occupation	INDOOR
Date Of Driving Pass	17/05/2017
Driving Experience	2 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93390318
Fax Number	
Contact Number	OFFICE-93390318
Email Address	NOEMAIL

Address	6 HOUGANG STREET 92 #02-01
Postcode	538685
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200315/7012.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM9605Y
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHAN YI QIN TIFFANY

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? SLX1002U

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


- 1) Please report **correctly** on the details of the accident to speed up the claims process.
- 2) This form must **be completed by the policy holder and/or the authorised driver.**
- 3) Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) **Any false reporting may be referred to the police for investigation.**
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.


Policy holder's signature
Date / time:


Driver's signature
(if driver is not policy holder)
Date / time:


reporting centre personnel's Signature
Date / time:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature
Date & time:

Driver's signature
(if driver is not policy holder)
Date & time:

reporting centre personnel's Signature
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20200315/7012

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200315/7012

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/03/2020 18:45		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: CHAN YI QIN TIFFANY			Address: 6 HOUGANG STREET 92 #02-01 SINGAPORE 538685		
ID Type / ID No.: NRIC NO / S9536472A			Contact No.: Home/Office: Mobile: 93390318		
Nationality: SINGAPORE CITIZEN			Email: find.tiffanychan@gmail.com		
Sex: Female	Age: 24	Date of Birth: 28/09/1995	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Marketing and sales representative (technical)			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/03/2020 18:30	Type of Location: X-Junction
Location: EUNOS LINK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLX1002U	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20200315/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No: T/20200315/7012

CONTINUATION OF REPORT

Driver			
Name	CHAN YI QIN TIFFANY	ID No.	S9536472A
Related Vehicle	SLX1002U (Car)	Contact No.	93390318
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details

At 15/03/2020 at about 1630hrs, I was traveling straight on Eunos link towards Hougang in my car (SLX1002U). The traffic light turned amber and I stepped on my brakes. Suddenly I felt a very huge impact from my rear. My car propelled 1 meter forward. Then I realised I was hit by (SKM9605Y). I went to Mount Alvernia to see a doctor and was awarded 5 days of medical leave.

Police Report



**SINGAPORE
POLICE FORCE**



T/20200315/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

5 of 3

Report No: T/20200315/7012

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65476219

Authentication Stamp
NP166

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
15/03/2020 18:45

Classification Of Case:

MOTORCAR (Rear)

Rear Portion

Vehicle No: SLX 10024

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	NO	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NR	✓	2
1149	993045	Rear Bumper Reinforcement	NR	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CM	✓	
1157	993023	Rear Bumper Lower Spoiler	NR	✓	
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	NR	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CM	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	CM	R	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

18/3/2020

5 days

Third-party vehicle survey by Adrian

3/18/2020

Report: LKK Auto Consultants Pte Ltd (HQ) - SKM9605Y

SKM9605Y - Submitted by: LKK Auto Consultants Pte Ltd (HQ)



1/26: General View



2/26: General View



3/26: General View



4/26: General View



5/26: General View



6/26: General View

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2020 13:49 Edit Reg		18 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	YIP SOON FAT JAMES , ID: S0000567C								
Main Claimant:	CHAN HUA ENG								
Vehicle Reg. No.:	SLX1002U	Date of Loss:	15/03/2020 16:00 - :59 [23 Months and 28 Days From LTA Reg. Date (Man Yr)]						
Claim Type:	TP / 2948472048SG	Policy/Cover Note No.:	2100371940						
Vehicle Reg. No. (Insured):	SKM9605Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/03/2020]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX1002U (2948472048SG)
[SKM9605Y]
TP
CHAN HUA ENG
Mar 15 2020 4:00PM
[YIP SOON FAT JAMES]
Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	18/03/20 17:49	General View													1	Load JPG	☒			
2	18/03/20 17:49	General View													1	Load JPG	☒			
3	18/03/20 17:49	General View													1	Load JPG	☒			
4	18/03/20 17:49	Odometer Reading													1	Load JPG	☒			
5	18/03/20 17:49	Chassis Number													1	Load JPG	☒			
6	18/03/20 17:49	General View													1	Load JPG	☒			
7	18/03/20 17:49	General View													1	Load JPG	☒			
8	18/03/20 17:49	General View													1	Load JPG	☒			
9	18/03/20 17:49	General View													1	Load JPG	☒			
10	18/03/20 17:49	General View													1	Load JPG	☒			
11	18/03/20 17:49	General View													1	Load JPG	☒			
12	18/03/20 17:49	General View													1	Load JPG	☒			
13	18/03/20 17:49	General View													1	Load JPG	☒			
14	18/03/20 17:49	General View													1	Load JPG	☒			
15	18/03/20 17:49	General View													1	Load JPG	☒			
16	18/03/20 17:49	General View													1	Load JPG	☒			
17	18/03/20 17:49	General View													1	Load JPG	☒			
18	18/03/20 17:49	General View													1	Load JPG	☒			
19	18/03/20 17:49	General View													1	Load JPG	☒			
20	18/03/20 17:49	General View													1	Load JPG	☒			
21	18/03/20 17:49	General View													1	Load JPG	☒			
22	18/03/20 17:49	General View													1	Load JPG	☒			
23	18/03/20 17:49	General View													1	Load JPG	☒			
24	18/03/20 17:49	General View													1	Load JPG	☒			
25	18/03/20 17:49	General View													1	Load JPG	☒			
26	18/03/20 17:49	General View													1	Load JPG	☒			
27	18/03/20 17:49	General View													1	Load JPG	☒			
28	18/03/20 17:49	General View													1	Load JPG	☒			
Documentation															1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	18/03/20 17:56	TP GIA REPORT													1	Load PDF				
2	18/03/20 17:56	TP POLICE REPORT													1	Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)														Thumbnail	Print			
1	20/03/20 12:09	OI GIA REPORT													1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004203/EQD3E2

Date: 20/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100371940
Claimant Vehicle No : SLX1002U **Insured Vehicle No :** SKM9605Y
 Date of Loss: 15/03/2020 Nature of Claim: TP Claim No: 2948472048SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX1002U**
 Make & Model: KIA CERATO K3, 1.6 SUNROOF (A) Engine No: G4FGHH691700
 Reg. Date: 16/03/2018 (Man. Year: 2017) Chassis No: KNAFZ411MJ5761741
 Colour: Blue Odometer: 47856 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/03/2020
 Date Inspected: 18/03/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Broken	0.00 F	*- F
7	1		*REAR END PANEL	Dented	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
9	1		*REAR RH FENDER	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >