

ASS. REC. BY: REP 05/SMD20004205/Kv d3 Special Instruction:

Surveyor: ASSIGNMENT (Office)
From (Person): Grace Teo of SMD Date/Time: 18/3/2020 @ 3:40pm

Estimated Cost: _____ Bill to: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: SLU 6579E Insured: SLK 8853C
at Workshop no: Lim Tan Motor Tel: 9992 1329 / 6452 0893
of Blk 176 Sim Ming Drive # 03-09 10

Policy No: _____ Claim No: CMTD2001085 / THE
Sun Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11/03/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS wp? R.O.D. Est. _____
Date/Time: 18/3/2020 @ 3:44pm Person Contacted: VERUS Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate
	SLU 6579E - X	
	SLK 8853C - NBA/MSG19007 5-137	D.O.A. 21/04/2019
25/3/20	Email proli revised to Thelma	
9/4/20	Kenneth confirmed \$2631.76 (Red 1201.60, 319)	

NOT AUTHORIZED

LKK Kenneth

2 MAR 2020

ESTIMATE TO REPAIR

VEHICLE NO. : SLU 6579 E
MAKE : HONDA
MODEL : VEZEL 1.5X CVT
YEAR : 2017
CHASSIS NO : RU11230301

Table with 2 columns: Field (SURVEYOR NAME, DATE OF SURVEY, TIME OF SURVEY) and Value.

DATE : 16-Mar-20
DATE OF ACCIDENT : 11-Mar-20
THIRD PARTY REF : SLK 8853 C
THIRD PARTY REF : SOMPO INSURANCE SINGAPORE PTE. LTD.

Main table with columns: Qty, Parts Description/ Labour, Type, Unit Price, Nett Item Amt, Amount. Includes handwritten notes like 'Src', 'Crg', 'short' and various numerical calculations.

NOT AUTHORIZED
Resurvey By pain
Uday

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a 'Without Prejudice' basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: