

ok

done ✓

ASS. REC. BY: \_\_\_\_\_ REF: CS/NOI 20004216 / UT d32b Special Instruction: \_\_\_\_\_

Summary: \_\_\_\_\_ ASSIGNMENT (Office)

From (Person): Wong Josephine of UOI Date/Time: 18/3/2020 @ 5:08pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 3790R Insured: YQ 1371L

at Workshop m/s M-Tech Motor Tel: 6784 0077 / 97354567

of Blk 900S Tampines street 93 # 01-252

Policy No: \_\_\_\_\_ Claim No: M12D13/42004

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A 13/03/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

Date/Time: 5:15pm @ 18/3/2020 Person Contacted: Alex H.O.D. Endorsement: \_\_\_\_\_

Vehicle IN OUT

| Date/Time | Action/Instruction Estimate |
|-----------|-----------------------------|
|           | <u>SJN 3790R - X</u>        |
|           | <u>YQ 1371L - X</u>         |
|           |                             |
|           |                             |
|           |                             |
|           |                             |

RECEIVED 5 MAR 2020

Date/Time, File Pass to? ☐ : Preli. Report

1) 25/3 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I. (\$) 700+

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ ) ☐ : Interview (\$ ) ☐ : Tech. Invs (\$ ) ☐ : Weekend (\$ )

Survey Fee: 170

Transportation: 60

S + RD, SI 80+80

Photo: 25

Others: \_\_\_\_\_

TOTAL 415

6/6/2020