

22/03/2021

ASS. REC. BY:

REF: 08/AIG 20004217 / Gsd3

Special Instruction:

Surveyor: Quo Wang

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 19/3/2020 @ 7:48am

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV /  CS

To Inspect Vehicle No: \_\_\_\_\_

SLE 9843G

Insured: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

Motor Image

Tel: \_\_\_\_\_

8611 33195

of \_\_\_\_\_

19 Long & Joo Puyoh

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

9999939181

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

TBA

Make of Veh: \_\_\_\_\_

(Client's Record)

D.O.A. \_\_\_\_\_

04/03/2020

CA /  REV

REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: \_\_\_\_\_

8:34am @ 19/3/2020

Person Contacted: \_\_\_\_\_

Daniel

Vehicle  IN /  OUT

Date/Time	Action/Instruction	Estimate	(✓)
		<u>SLE 9843G - CC6 / AIG 18017769 / Aeb392</u>	
		<u>DOA: 17/09/2018</u>	