COMFORTDELGRO ENGINEERING

Our Job Ref No . 305388386						ENGINEERING		
Date : 1. Apr. 2020						ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	ALIZATI	ON FO	RM				6546 8156	
То	: <u></u>			LKK		Fax:		
Attn				RAM				
Vehicle Reg No. : SHD:				3637C	Date	e of Accident:	17. Mar. 2020	
The	survey	and est	timates of	the repairs of the abo	ove-mentione	d vehicle are a	as follows:-	
1.	The r	epair jo	b shall bil	to:	HINA		SKL6988S	
2.	The finalized amount shall be:							
	(a) Spare Parts after List discount							
	(b)	Labou	ur Charges	s				
		Total	for Part-E	By-Part Repair Cost				
	(c.) Lumpsum Repair Total for Lumpsu Final Lumpsum			um repair cost after l	_ess:	=	\$2,500,00	
		rınaı	Lumpsur	n Repair cost			\$2,500.00	
3. 4.	Estimated normal period for repairs: working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days							
5.			or your ass					
	Signature :			Signature: Name: Date:			1	
							Ram	
							104/2020	
	Fax	:	6546 815	6				
or (Official	Use O	nly					
	Item			Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
. Rental Rate P/Day					YES			
2. Loss of Income Paid				40 - 500	NO			
3. St	urvey F	ees						
LTA Search Fee Medical Fees (on behalf				\$7.49				
of driver, if applicable)								
0	verrun			100				
Rema	arks:							