

ASS. REC. BY:

REF: CS3/III 20001314/ USD302-1

Special Instructions:

J/C

Surveyor:

MARCUS

Derrick Pao

ASSIGNMENT (Office)

19/3/2020

From (Person):

Gabriel wee

of

III

Date/Time:

22/01/2020 @ 9:42am

Estimated Cost:

Bill to:

① TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLH 97134

Insured:

SH 9182 G

at Workshop in/s

Bluwel Automotive

Tel:

67452088

of

1 Kaki Bukit Avenue 6 # 01-55 Autobay

Policy No:

MCOM0015

Claim No:

MCT20010447

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

18/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:52am @ 22/1/2020

Person Contacted:

Sally

Vehicle ID:

① OUT

Date/Time

Action/Instruction

10/1/2020 X

SLH 97134 - X

SH 9182 G - SH/19/02/2020 04:45/104

22/1/2020 2:15

Dismantle part : 31/01/2020 0256PM

Subant L/S @ 2400 H hrs.
 (\$ 500/- Red - 17%)

RECEIVED 20 MAR 2020

250+11=261

261-131=130

ASSIGNMENT

PRS

Date

Time

30/01/2020

Estimated Cost

CIC / TP / WS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle At:

SLH 9713H

at Workshop n/a:

Bluwel Automotive

at 1 Kaki Bukit Ave 6 # 01-55

Insured

Autobuy

Policy No.

Claims No.

Sum Insured


Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value

47k

IDAC Accident Rpt

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs

days

Res

Yes or No

Lum Sum

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted

Vehicle: IN / OUT

Veh No

SLH 9713H

V Regn

11/16

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make

Peugeot

30080pc

1560

Colour

s. blue

AC

Insured / Std / NI / NA

Sp Reading

60520

T/Radix: Insured / Std / NI / NA

Eng/No.

C/No.

VF300447TGS 082765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / MOHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/1/20

D.O.A.

30/1/20

Survey held at

1132AM

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2076/2

No other. PRS MA33277

RECEIVED 31 JAN 2020

Form/Type: The Past or:

31/01/20

If

Type 24

Form/Type: The Present or:

If

Form/Type: The Past or:

PRS

Form/Type: The Present or:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Inspection Fee

If

If

If

If

If

Addl Fee:

Site trip

15

Interview

15

Tech. fee

15

Total

45

120

11

131

Celine Fong (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 March 2020 10:44 AM
To: 'Derrick Tan'; assignments
Cc: 'Sherini Pillai'; SUR
Subject: RE: PAPER SURVEY SLH9713H III REF: MCT20010447

Dear Derrick,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Derrick Tan <DerrickTan@iii.com.sg>
Sent: Thursday, 19 March 2020 10:41 AM
To: 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Sherini Pillai <sherini@iii.com.sg>
Subject: PAPER SURVEY SLH9713H III REF: MCT20010447

Dear Sir/Mdm,

Please conduct paper survey for the below TP vehicle and let us have your report URGENTLY. LOD uploaded and rights granted to you in Merimen.

TP Veh No. : SLH9713H.

Thank you.

Best Regards,

Derrick Tan
Motor & Work Injury Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
Tel: 6347 6100, Ext – 264

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance

Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com



INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1987

IN , INTERNATIONAL INSURANCE PTE LTD
Co. No. 198703792X | GST Reg. No. M2-0078806-X
SAC Street 804 & 805 10B Building Singapore 040711
Office (65) 63476100 Email insure@ii.com.sg
Fax (65) 62244174 Website www.ii.com.sg

PRESERVE

MCT/2001 0442

UNINSURED LOSS

PRESERVE

12/1/01

SUBRO

PRESERVE

LPPN

128

INVESTIGATION FEE

SURVEY FEES

LEGAL FEES

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS

 *** FAX TX REPORT ***

TRANSMISSION OK

JOB NO. 3592
 DESTINATION ADDRESS 964382313
 SUBADDRESS
 DESTINATION ID
 ST. TIME 16/03 07:32
 TX/RX TIME 01'06
 PGS. 2
 RESULT OK

CROSSBORDERS LLC

Advocates & Solicitors | Commissioners of Oaths | Notary Public

Our Ref:
 Your Ref:

AJ.lk.7158.2020.B/PD
 SH9182G

TO: TEH SOON LEE
 Blk 345 Tampines Street 33
 #09-360
 Singapore 520345



0 MAR 2020

BY CERTIFICATE OF
 POSTING

WITHOUT PREJUDICE

MAIN OFFICE
 133 NEW BRIDGE ROAD
 #22-02/04/05
 CHINATOWN POINT
 SINGAPORE 059413

TEL: 6438 1323
 FAX: 6438 2313

cc: India International Insurance Pte Ltd
 (Motor Claims Dept)
 36 Robinson Road
 #16-01 City House
 Singapore 068877

BY PDX

WITHOUT PREJUDICE

Dear Sirs

RE: CLAIMANT: KUN SOON JIN ADRIAN
 ACCIDENT INVOLVING VEHICLES NO. SLH9713H & SH9182G ALONG SUMANG
 LINK ON 18.01.2020.

We are instructed by the abovenamed to claim damages against you in connection with an accident on 18 January 2020 at about 11:05 hours along Sumang Link involving our client's vehicle no. SLH9713H and vehicle registration number SH9182G driven by you at the material time.


We are instructed that the accident was caused by the negligence of you in the driving, management and control of vehicle registration number SH9182G.

As a result of the accident, our client's vehicle registration number SLH9713H was damaged and our client has been put to loss and expense, particulars of which are as follows:-

A Damages

- a. Cost of Repairs (inclusive GST)
 b. Loss of Use (9 days x \$80.00 per day)

\$ 3,103.00



CROSSBORDERS LLC

Advocates & Solicitors | Commissioners of Oaths | Notary Public

Our Ref:
Your Ref:

AJ.tk.7158.2020.BW-PD
SH9182G



0 MAR 2020

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413

TEL: 6438 1323
FAX: 6438 2313

TO: **TEH SOON LEE**
Blk 345 Tampines Street 33
#09-360
Singapore 520345

BY CERTIFICATE OF
POSTING

WITHOUT PREJUDICE

cc: **India International Insurance Pte Ltd**
(Motor Claims Dept)
36 Robinson Road
#16-01 City House
Singapore 068877

BY PDX

WITHOUT PREJUDICE

Dear Sirs

RE: **CLAIMANT: KOH SOON JIN ADRIAN**
ACCIDENT INVOLVING VEHICLES NO. SLH9713H & SH9182G ALONG SUMANG
LINK ON 18.01.2020

We are instructed by the abovenamed to claim damages against you in connection with an accident on 18 January 2020 at about 11:05 hours along Sumang Link involving our client's vehicle no. SLH9713H and vehicle registration number SH9182G driven by you at the material time.

We are instructed that the accident was caused by the negligence of you in the driving, management and control of vehicle registration number SH9182G.

As a result of the accident, our client's vehicle registration number SLH9713H was damaged and our client has been put to loss and expense, particulars of which are as follows:-

A Damages		
a. Cost of Repairs (inclusive GST)	\$	3,103.00
b. Loss of Use (9 days x \$80.00 per day) (inclusive of Sunday and 2 days Pre-Repair Inspection Notice and 2 Chinese New Year Holiday)	\$	720.00
B Disbursements		
a. LTA Search	\$	7.49
b. GIA Report	\$	29.00
c. Survey Report	\$	609.00
C LEGAL COSTS (AT THIS STAGE)		
	\$	749.00
	\$	5,217.49

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413

Our Ref: AJ.tk.7158.2020.BW-PD
Your Ref: SH9182G

TEL: 6438 1323
FAX: 6438 2313

10 MAR 2020

cc: ✓ COMFORT TRANSPORTATION PTE LTD
383 Sin Ming Drive
Gas Building
Singapore 575717

BY CERTIFICATE OF
POSTING

WITHOUT PREJUDICE

cc: India International Insurance Pte Ltd
(Motor Claims Dept)
36 Robinson Road
#16-01 City House
Singapore 068877

BY PDX

WITHOUT PREJUDICE

Dear Sirs

**RE: CLAIMANT: KOH SOON JIN ADRIAN
ACCIDENT INVOLVING VEHICLES NO. SLH9713H & SH9182G ALONG SUMANG
LINK ON 18.01.2020**

We are instructed by the abovenamed to claim damages against you in connection with an accident on 18 January 2020 at about 11:05 hours along Sumang Link involving our client's vehicle no. SLH9713H and vehicle registration number SH9182G driven by you at the material time.

We are instructed that the accident was caused by the negligence of you in the driving, management and control of vehicle registration number SH9182G.

As a result of the accident, our client's vehicle registration number SLH9713H was damaged and our client has been put to loss and expense, particulars of which are as follows:-

A	Damages		
a.	Cost of Repairs (inclusive GST)	\$	3,103.00
b.	Loss of Use (9 days x \$80.00 per day) (inclusive of Sunday and 2 days Pre-Repair Inspection Notice and 2 Chinese New Year Holiday)	\$	720.00
B	Disbursements		
a.	LTA Search	\$	7.49
b.	GIA Report	\$	29.00
c.	Survey Report	\$	609.00
C	LEGAL COSTS (AT THIS STAGE)	\$	749.00
		\$	5,217.49

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

We enclose herewith copies of the following documents in support of our client's claim:-

- a) GIA Report lodged by our client (SLH9713H) with sketch plan;
- b) GIA Report lodged by you (SH9182G) with sketch plan together with photographs of your motor vehicle no. SH9182G;
- c) Result of LTA search on your vehicle registration no. SH9182G;
- d) Repair Bill from Bluwel Automotive Service Pte Ltd;
- e) Vehicle Assessment Report & Invoice from Mc-Coy Appraiser Pte Ltd;
- f) Sixty-Nine (69) colour photographs depicting the damage to our client's motor vehicle no. SLH9713H; and
- g) Vehicle Owner Particulars of our client's vehicle no. SLH9713H.


We have on 21 January 2020 notified your insurers **India International Insurance Pte Ltd** of the accident and pre-repair inspection of our clients' vehicle was carried out by your insurer.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days** of your receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks** of your receipt of this letter.

Yours faithfully



CrossBorders LLC

Email: corene@crossbordersllc.com (secretary)

encs

cc: SLH9713H

20/01/2020 MON 10:12 FAX

001/004

MSME2000944 / BME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 18/01/2020 15:53
SUBMITTED BY: Che Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/01/2020 15:03
Date Of Accident 18/01/2020 11:05
Exact Location Of Accident SUMANG LINK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH9713H
Insured/Policyholder
Name Of Registered Owner KOH SOO JIN ADRIAN
NRIC No SXXXX882A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-81387845
Alternative Phone No OFFICE-81387845
Vehicle Particulars
Manufacturer PEUGEOT
Model 3008
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own Insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P10098882R01
Cover Note Number

Driver

Name of Driver KOH SOO JIN ADRIAN
NRIC No SXXXX882A
Date Of Birth 02/03/1975
Occupation INDOOR
Date Of Driving Pass 03/06/1994
Driving Experience 25 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-81387845
Fax Number
Contact Number OFFICE-81387845
EMail Address NOEMAIL

20/01/2020 MON 10:12 FAX

002/004

Address 92 PUNGGOL DRIVE #12-07
 Postcode 828795
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information:
 Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: TYLER KOH
 GENDER: MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STATIONARY. SUDDENLY, VEHICLE B HIT ONTO MY VEHICLE REAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH91520
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

20/01/2020 MON 10:12 FAX

003/004

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report in the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




20/01 2020 MON 10:12 FAX

004/004

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my vehicle was stationary / suddenly vehicle B HIT ONTO
my vehicle rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:Driver's Signature
(If driver is not the policyholder)
Date & Time:Reporting Officer's Signature
Name:
NRIC/FIN No.:

10/20/2020 10:12:13

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 11:48
Date Of Accident	18/01/2020 11:05
Exact Location Of Accident	SENTUL CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9182G
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	TEH SOON LEE
NRIC No	S1776413F
Address	BLK 345 TAMPINES STREET 33 #09-360
General Information of the Accident	
Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLH9713H

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303621K


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Loke Wei Yeng
NRIC/FIN No.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/1/2020 at about 11:05 hrs, I Veh A
 roll forward
 have a slight collision with Veh B at above said
 location. No passenger in my taxi No injury
 reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303621H

Policyholder's Signature
 Date & Time

Driver's Signature
 (if driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name: Loke Wei Yung
 NRIC/FIN No.

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Enquire Vehicle & Owner Information (Vehicle No. SH9182G As At 18 Jan 2020 / 11:05:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: AJ.TX.BW

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717
Current Vehicle Details

Vehicle No.: SH9182G
Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Vehicle No : SLH 9713 H
Make/Model : Peugeot 3008
Name : Koh Soo Jin Adrian
Address : c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Date : 11-Feb-20

QTY	ITEM	AMT (\$)
-----	------	----------

Lump sum repair costs	\$	2,900.00
GST 7 %	\$	203.00
Grand-total	\$	<u>3,103.00</u>

Dollars : Three Thousand One Hundred And Three Only

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Billing Name & Address

Koh Soo Jin Adrian
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Invoice No 20011-01/MY

Date 11 Feb 2020

Vehicle No : SLH 9713 H

Model : Peugeot 3008

Item	Descriptions	Amount S\$
1	Date of inspection : <u>30 Jan 2020</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>69</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 609.00</u>
	SDLS : SIX HUNDRED AND NINE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 20011-01/MY / 2020**
Date of Report : **11 Feb 2020**

Koh Soo Jin Adrian
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 18 Jan 2020

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **30 Jan 2020** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SLH 9713 H**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SLH 9713 H	Engine No	: 10JBHC3045685
Model	: Peugeot 3008	Mileage	: 60520
Year / Capacity	: 2016/1560	Colour	: Silver
Chassis No	: VF30UBHZTGS082765		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 225/50 R17	Michelin	8.00	mm	Sport
REAR O/S	: 225/50 R17	Michelin	8.00	mm	Sport
FRONT N/S	: 225/50 R17	Michelin	8.00	mm	Sport
REAR N/S	: 225/50 R17	Michelin	8.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 4 working days to complete.
5. Enclosed number of photograph : 69 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLH 9713 H
Report No: TP/ 20011-01/MY / 2020

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear end panel	Repair	\$ 1678.00	\$ <i>1</i> <i>X</i>
1	Rear bumper	Damage	\$ 1150.00	\$ <i>20/12</i> 1150.00 ✓
1	Rear bumper lower chrome diffuser	Damage	\$ 367.00	\$ <i>CNE</i> 367.00 ✓
1	Rear bumper reflector lamp	Damage	\$ 158.00	\$ <i>CNE</i> 158.00 ✓
1	Rear bumper inner centre bracket	Damage	\$ 135.00	\$ <i>CNE</i> 135.00 ✓
1	Rear bumper inner side bracket (1 set)	Damage	\$ 130.00	\$ <i>CNE</i> 130.00 ✓
1	Rear bumper reinforcement	Damage	\$ 462.00	\$ <i>TD</i> 462.00 ✓
2	Rear bumper sensors	Damage	\$ 324.00	\$ <i>SUL</i> 324.00 <i>X</i>
2	Rear bumper side retainers	Damage	\$ 72.00	\$ <i>AN</i> 72.00 <i>X</i>
			\$ 4476.00	\$ 2798.00
	Discount	10.0%	\$ 447.60	\$ 279.80
			\$ 4028.40	\$ 2518.20
<u>Special Nett Items</u>				
1	Rear number plate with seal	Damage	\$ 80.00	\$ <i>NE</i> 80.00 <i>60</i>
			\$ 80.00	\$ 80.00

9-2402
102
2161.8


Spare Parts Total \$ 4108.40 \$ 2598.20

Vehicle No: **SLH 9713 H**
 Report No: **TP/ 20011-01/MY / 2020**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 4108.40	\$ 2598.20
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 60.00	\$ 30.00 ✓
2	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00 50
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 440.00 300
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 800.00	\$ 440.00 400
5	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00 X
Total		<u>\$ 6118.40</u>	<u>\$ 3618.20</u>
The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:		\$ 2900.00	3001.8 2401.8

SDLS: TWO THOUSAND NINE HUNDRED ONLY


 Qualified Appraiser

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

682A

Vehicle Details

Vehicle No.:

SLH9713H

Vehicle to be Exported:

No

Intended Deregistration Date:

20 Jan 2020

Vehicle Make:

PEUGEOT

Vehicle Model:

3008 1.6 BLUEHDi EAT6 S/R

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

10JBHC3045685

Chassis No.:

VF30UBHZTG6082765

Maximum Power Output:

88.0 kW (118 bhp)

Open Market Value:

\$21,404.00

Original Registration Date:

24 Nov 2016

First Registration Date:

24 Nov 2016

Transfer Count:

0

Actual ARF Paid:

\$11,966.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility:

No

OPC Cash Rebate Eligibility Expiry Date:

-

OPC Cash Rebate Amount:

-

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 Nov 2026

PARF Rebate Amount:

\$8,974.00

Intended COE Rebate Details

COE Expiry Date:

23 Nov 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$35,668.00

COE Rebate Amount:

\$24,402.00

Total Rebate Amount:

\$33,376.00

The information contained herein is correct as at 20 Jan 2020


OK

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III20001314/Usd3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-03-2020	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9182G	Veh. Inspected	SLH 9713H
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20010447	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	19/03/2020
2. Vehicle Particulars & Condition			
Make & Model	PEUGEOT 3008 (A)	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF30UBHGTGS082765	Colour	SILVER
Odometer	60520	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	MICHELIN	6 mm
L/H Front Tyre	225/50 R17	MICHELIN	6 mm
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/01/2020	Inspection Date	30/01/2020
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 9713H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,678.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,150.00	1,150.00
1	REAR BUMPER LOWER CHROME DIFFUSER	CRACKED	367.00	367.00
1	REAR BUMPER REFLECTOR LAMP	CRACKED	158.00	158.00
1	REAR BUMPER INNER CENTRE BRACKET	CRACKED	135.00	135.00
1	SET REAR BUMPER INNER SIDE BRACKET	CRACKED	130.00	130.00
1	REAR BUMPER REINFORCEMENT	DENTED	462.00	462.00
2	REAR BUMPER SENSORS	SERVICEABLE	324.00	-
2	REAR BUMPER SIDE RETAINERS	NOT NECESSARY	72.00	-
	LESS 10% DISCOUNT		-447.60	-240.20
			4,028.40	2,161.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE WITH SEAL (SN)	NECESSARY	80.00	60.00
			80.00	60.00
<u>LABOUR</u>				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		60.00	30.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		150.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	300.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		800.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	NOT NECESSARY	100.00	-
			2,010.00	780.00
GRAND TOTAL			6,118.40	3,001.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS3/III20001314/Usd3e2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.