

ASS. REC. BY:

REF: CS3 / AIG 20004246 / G1 f31

Special Instruction:

OK

Surveyor: G1

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of

AIG

Date/Time: 19.3.2020 1.37p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 6987 H

Insured:

SLX 6024Z

at Workshop m/s

Yap motor

Tel:

96187155

of BIC 7 Sin ming Industrial Estate #01-82

Policy No:

1800031125

Claim No:

084459470386

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17.3.2020

CA / REV / REP. / REV 24 HRS

mp'

23.3.2020

H.O.D. Endorsement:

Date/Time:

19.3.2020 2.15p.m

Person Contacted:

Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate.
	GBF 6987 H - X
	SLX 6024Z - X
	Dismantle: 23/3/2020.

Surveyor

6rd

REF: AIG CS3/AIG 20604246/Gyfs

PRS mmm

ASSIGNMENT

From:

Date:

23.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 6987H

at Workshop n/s gap motor

of Bk 7 sin ming Industrial Estate #01-82

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: After 11.00am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 1/2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF6987H

Yr Regn:

11 Feb 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

c.c

2488

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

90917

T/Radio:

Insured / Std / NI / NA

Eng/No:

JN1MC2E2680007041

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195R15 (Hifly)

(pear)

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

23-03-20

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The ~~U/C~~ Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

26/3/20 Typist

Report Format:

DAR

Lump Sum / I.B.I.: (\$

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

180

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2020 Edit Reg		24 Mar 2020 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HE RUOYUN, ID: S8987400I								
Main Claimant:	JIA CHENG SERVICE PTE LTD								
Vehicle Reg. No.:	GBF6987H	Date of Loss:	17/03/2020 13:00 - :59						
Claim Type:	TP / 0844594703SG	Policy/Cover Note No.:	1800031125 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX6024Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Motor Repair Service (HQ) 19 Block 7 Sin Ming Industrial Estate Sector C #01-82, 575642 Sin Ming - Tel: 64511705								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (25/03/2020): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Our Ref : CY.GBF6987H.20.YM(HW).wp(PT)

Your Ref : Your insured vehicle – SLX 6024Z

18 March 2020

He RuoYun
c/o **AIG Asia Pacific Insurance Pte Ltd**
(Motor Claims Department)
78 Shenton Way #07-16
Singapore 079120

BY EMAIL

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES GBH 6987H & SLX 6024Z ON
17.03.2020 @ 13:30HRS ALONG BOON LAY WAY OUT FROM TRADE HUB 21**


We are instructed by Jia Cheng Services Pte Ltd to notify you of a road traffic accident on 17.03.2020 @ 13:30hrs along Boon Lay Way out from Trade Hub 21 involving our client's vehicle no. GBF 6987H and vehicle no. SLX 6024Z driven by you at the material time. A copy of the Singapore accident statement is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent
4. Alan Chong
5. Lee Automobile Appraisers Services
6. Impact Analysis Consulting Pte Ltd

Yours faithfully,


C. Yogarajah LLC
Enc

cc: **M/s. YAP MOTOR SERVICE PTE LTD**
Block 7 Sin Ming Industrial Estate
#01-82
Singapore 575642
Mrs. Yap (6451 1705 / 8161 9189)
Mr. Yap (9618 7155)
Fax No: 6451 1706

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	906R
Vehicle Details	
Vehicle No.:	GBF6987H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Mar 2020
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	YD25404772A
Chassis No.:	JN1MC2E26Z0007041
Maximum Power Output:	-
Open Market Value:	\$23,668.00
Original Registration Date:	11 Feb 2017
First Registration Date:	11 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$1,184.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,302.00
COE Rebate Amount:	\$31,877.00
Total Rebate Amount:	\$31,877.00

The information contained herein is correct as at 23 Mar 2020

OK

nissan nv350 Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan NV350 2.5M (Diesel)	\$46,800	\$6,450 /yr	29-Jun-2017	2,488 cc	-	ABWIN (1994) Pte Ltd	Available
New Euro 6 From Agent Tan Chong. Latest Facelift. Call To Enquire Or Viewing! Office No. - 68416666 Jin Hao - 86111600 Zac - 93855930 Bryan Chua - 81120173 Tony - 90065775							
Nissan NV350 Caravan 2.5A (Diesel)	\$51,500	\$6,640 /yr	28-Dec-2017	2,488 cc	-	Sino Credit Pte Ltd	Available
Auspicious Number Plate! Auto Transmission. 1 Owner. In-House Loan. Please Feel Free To Call Us If You Need Any Additional Information! Office No. - 87777752 / 63484811 Jean - 94878135							
Nissan NV350 2.5A (Diesel)	\$52,800	\$7,110 /yr	30-Aug-2017	2,488 cc	1,800 km		Available
1 Owner, Super Rarely Used That's Why Super Low Mileage, As Good As Driving A New Van, No Accidents Before, Still Under Agent Warranty. Office No. - - Jennifer - 96629062							
Nissan NV350 2.5M (Diesel)	\$47,800	\$6,600 /yr	22-Jun-2017	2,488 cc	-		Available
1 Direct Owner, Regularly Maintain, Practical 5 Door And Low Maintenance Popular Vehicle. Call For A Test Drive Now. Office No. - - Edmund - 85589145							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Find the right Rental Car for you - get short term rental, long term lease, private hire cars, wedding cars to cars for p-plate probation drivers. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2020 sgCarMart. All rights reserved.

14/12/2020

E-FILE

E-Mail Address

NOEMAIL

Address

BLK 541 YISHUN STREET 51
#10-206

Postcode

750641

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

-

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

-

Was notice of intended Prosecution given?

NO

If Yes against whom?

-

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLX6024Z

Vehicle Make/Model/Colour

-

Details Of Properties

-

Vehicle Category

PRIVATE CAR

Name of Driver

-

NRIC/Passport Number

-

Contact Number

-

Address

-

Postcode

-

Insurance Company Name

-

Nature Of Damage

-

No. Of Passenger (Including Driver)

-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIC Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my working and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information"; and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) settling the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) to regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time

17-15/10

Driver's Signature

(if driver is not the policyholder)

Date & Time

17-15/10

Reporting Centre Personnel's Signature

Name


NRIC/FIN No. Poh Kwee Choo

SKETCH PLAN

Gantry Entry
Entrance

A - GBF 6987H

B - SLX 60042



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the date of 17 March 2022, at 1:30pm, my vehicle (SPATEL NO. 6987H) was driving into Burnay Way, out from Trade Hub 2.1 when my vehicle was ~~was~~ slightly landed and scratched the left column, next to my vehicle's side door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



[Handwritten signature]

[Handwritten signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Employee's Signature & Name
Poh Kwee Choo
NRIC/INTEL

1) Damaged 2) Disposed 3) Cracked 4) Bent 5) Scratched
6) Deformed 7) Stuffed 8) Buckled 9) Broken 10) Necessary
11) Missing 12) Torn 13) Unconfirmed 14) Not Working

VAN / LORRY (Rear)

(1) Replace (2) Repair (3) Check (4) Not Confirmed (5) NC

Vehicle No: **6BE6987H**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		Rock			
		Rock panel LH repair			

No of Items: _____

Assessor: _____






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2020 Edit Reg		19 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: HE RUOYUN , ID: S89874001									
Main Claimant: JIA CHENG SERVICE PTE LTD									
Vehicle Reg. No.: GBF6987H		Date of Loss: 17/03/2020 13:00 - :59 [37 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0844594703SG		Policy/Cover Note No.: 1800031125 (Comprehensive)							
Vehicle Reg. No. (Insured): SLX6024Z		Policy No. (Claimant):							
		Excess:							
Repairer: Yap Motor Repair Service (HQ) 19 Block 7 Sin Ming Industrial Estate Sector C #01-82, 575642 Sin Ming - Tel: 64511705									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/04/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (25/03/2020): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF6987H (0844594703SG)
[SLX6024Z]
TP
JIA CHENG SERVICE PTE LTD
Mar 17 2020 1:00PM
[HE RUOYUN]
Yap Motor Repair Service

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/03/20 12:06	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	26/03/20 12:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
30	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
31	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
32	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
33	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
34	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
35	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/03/20 17:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
38	26/03/20 17:25	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
39	26/03/20 17:25	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
40	26/03/20 17:25	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	25/03/20 14:05	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004246/GYF3E2

Date: 30/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800031125

Claimant Vehicle No: GBF6987H

Insured Vehicle No: SLX6024Z

Date of Loss: 17/03/2020

Nature of Claim: TP

Claim No: 0844594703SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF6987H

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A)

Reg. Date: 11/02/2017 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: YD25404772A

Chassis No: JN1MC2E26Z0007041

Odometer: 90917 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: HIFLY 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: HIFLY 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2020

Date Inspected: 23/03/2020 Inspected At:

Yap Motor Repair Service (HQ)
19 Block 7 Sin Ming Industrial Estate
Sector C #01-82
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BODY PANEL	Repair	0.00 F	*- F
2	1		*SLIDING DOOR LH	Buckled	0.00 F	*- F
3	1		*REAR LH RIM COVER	Cut	0.00 F	*- F
4	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
F=Franchise part.				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >