

12/01/2020

ASS. REC. BY

REF: 033/FWD20004266/Gtd3k

Special Instructions

Signature: Chao Qiang  
Mei Men

ASSIGNMENT (Office)

From (Person): Venessa Chan

at Fwp

Date/Time: 1pm @ 19/3/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 4680R

Insured: SLL 9670B

at Workshop m/s Koi Motor

Tel: 92781189

of 176 Sin Ming Drive # 04-12

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17/03/2020

CA / REV / REP. / REV 24 HRS lap

H.O.D. Endorsement:

Date/Time: 1:05pm @ 19/3/2020

Person Contacted: ERIC

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate (X)
	SLJ 4680R - X	Dismantle part : 20/03/2020
	SLJ 9670B - X	After repair : 25/03/2020
	Submit PRS Report	RECEIVED 20 MAR 2020

ASS. F20. BY:

BQ

PRS

REF:

FWD CS3/FWD 2000 4266/G1d3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Koi Motor

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ4680R

11 Regn:

12

2006

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Ahi's 1.6 cc 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

171820

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053 ZEC 107137225

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/70R14

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18-07-20

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/3

GIA later Give

\$4000 - \$5000

24/3/2020

Date/Time, File Pass to?



Prel. Report

1) 26/3 Typist



Final Report

Date/Time, File Return to?

2)

Report Format:

PRS

Dump Sum / M.B. etc

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Meal and (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

80

50

50

180

## Denise Tay (LKKAuto)

---

**From:** Venessa Chan - SGUser <venessa.chan@fwd.com>  
**Sent:** Friday, 20 March 2020 9:55 AM  
**To:** Chuapk\_1973@yahoo.com.sg  
**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser; CRM and all customer engagements - SG Common  
**Subject:** ACCIDENT INVOLVING SLL9670B & SLJ4680R ON 17.03.2020 CLAIM REF: 1202000013987/LT

Dear Mr Chua Poh Khoo,

We'd like to let you know that we have received one Third Party claim notification regarding the accident on 17.03.2020. The third party's plate number SLJ4680R. The third party is represented by Koi Motor Works.

The officer in charge for this matter is Lionel Tan.

There is no need for you to respond or do anything more if you'd like us to proceed with this third party claim assessment. If you have additional information and/or documentation about the accident or third-party claim, please email us at [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com) by 27.03.2020.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims



**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



### ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Limited Liability Partnership  
Owner ID: 922F

### Vehicle Details

Vehicle No.: SLJ4680R  
Vehicle to be Exported: No  
Intended Deregistration Date: 24 Mar 2020  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA ALTIS 1.6 AUTO  
Primary Colour: Silver  
Manufacturing Year: 2006  
Engine No.: 3ZZ4620096  
Chassis No.: MR053ZEC107137225  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$15,355.00  
Original Registration Date: 27 Dec 2006  
First Registration Date: 27 Dec 2006  
Transfer Count: 2  
Actual ARF Paid: \$16,891.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 26 Dec 2021  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$25,636.00  
COE Rebate Amount: \$9,000.00  
Total Rebate Amount: \$9,000.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Mar 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/03/2020 14:51
Date Of Accident	17/03/2020 08:45
Exact Location Of Accident	ALONG CTE AFTER AMK AVE TOWARDS YISHUN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ4680R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	URBAN WHEELER LEASING LLP
Co Reg No	T18LL1922F
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96849845

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	20001056-00011
Cover Note Number	NA

### Driver

Name of Driver	LIM BOON BENG
NRIC No	S0033723D
Date Of Birth	03/12/1954
Occupation	OUTDOOR
Date Of Driving Pass	08/10/1975
Driving Experience	44 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81435940
Fax Number	
Contact Number	
Email Address	URBANWHEELERLLP@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : SEAH GENDER: : FEMALE
Passenger 2	NAME: : LUCIUS GENDER: : MALE
Passenger 3	NAME: : LAVOMME GENDER: : FEMALE
Passenger 4	NAME: : LETTICIA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD, ON THE SECOND LANE FROM THE RIGHT. WHEN A VEHICLE IN FRONT OF ME APPLIED BRAKES AND STOPPED, I MANAGED TO STOP MY VEHICLE BEHIND IT AND WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL9670B
-----------------------------	----------

Vehicle Make/Model/Colour	PEUGEOT / 308 SW ALLURE PURETECH 1.2 A/T 2WD S/R
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA POH KHOON
NRIC/Passport Number	S7336042J
Contact Number	97463543
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

# SLJ4680R

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)  
REPORTING OFFICER  
HASHIM BIN KAMARI

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

18 March 2020

Sketch Plan #2



CTE TO YISIMIN

X ~~21~~


A9: 9LJ460P

B9: 9LL9670B

CONTACT POINT

REFER TO ATTACHED STATEMENT.

I/We declare the foregoing particulars are true in every respect.

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NASC/TIN No.: \_\_\_\_\_

### Sketch Plan #3

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD, ON THE SECOND LANE FROM THE RIGHT. WHEN A VEHICLE IN FRONT OF ME APPLIED BRAKES AND STOPPED, I MANAGED TO STOP MY VEHICLE BEHIND IT AND WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED.

STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

18 March 2020 at 11:29 AM

Date/Time:

18 March 2020 at 11:29 AM

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI






































## CLAIM SUBFOLDER TRACKING




























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2020 <a href="#">Edit Reg</a>		19 Mar 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Chua Poh Khoo, ID: S7336042J								
Main Claimant:	URBAN WHEELER LEASING LLP, Co. Reg. No.: T18LL1922F								
Vehicle Reg. No.:	SLJ4680R	Date of Loss:	17/03/2020 00:00 - :59 [158 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1202000013987	Policy/Cover Note No.:	PNPV2020-00002015 (Comprehensive) Coverage: 17/03/2020 - 16/03/2021						
Vehicle Reg. No. (Insured):	SLL9670B	Policy No. (Claimant):							
		Excess:							
Repairer:	KOI MOTOR WORKS (HQ) BLK 176 SIN MING DRIVE #04-12 SIN MING AUTOCARE, 575721 Sin Ming - Tel: 6454 6335 / 9632 3791								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/03/2020]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLJ4680R (1202000013987)  
[SLL9670B]  
TP  
URBAN WHEELER LEASING LLP  
Mar 17 2020 12:00AM  
[Chua Poh Khoon]  
KOI MOTOR WORKS

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
27	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
28	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
29	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
30	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
31	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/03/20 09:38	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/03/20 09:39	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
36	20/03/20 09:39	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
37	24/03/20 09:14	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
39	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
40	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
41	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
42	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
43	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
44	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
45	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
46	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
47	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
48	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
49	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
50	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
51	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
52	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
53	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
54	24/03/20 09:14	Dismantled Parts		<input checked="" type="checkbox"/>
55	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
56	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
57	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
58	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
59	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
60	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
61	26/03/20 09:52	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	20/03/20 09:48	SLJ4680R TP GIA		<input type="checkbox"/>
2	20/03/20 09:48	SLL9670B OI GIA		<input type="checkbox"/>
3	20/03/20 09:56	EMAIL TO OI		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div> ^ v </div> </div> </div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20004288/GTD3E2

Date: 27/03/2020

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00002015

Claimant Vehicle No: SLJ4680R Insured Vehicle No: SLL9670B

Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: 1202000013987

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLJ4680R  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4620096  
 Reg. Date: 27/12/2006 (Man. Year: 2006) Chassis No: MR053ZEC107137225  
 Colour: Silver Odometer: 171820 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/03/2020

Date Inspected: 19/03/2020 Inspected At:

KOI MOTOR WORKS (HQ)  
 BLK 176 SIN MING DRIVE #04-12 SIN  
 MING AUTOCARE  
 Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 27 Mar 2020)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLJ4680R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >