

22/03/2020

ASS. REC. BY:

REF: CS/CTI 20004272/ Ut d30

Special Instruction:

Survey:

ASSIGNMENT (Office)

From (Person): Ben Tang

of CTI

Date/Time: 19/3/2020 @ 5:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBH 551K

Insured: SJY 7943H

at Workshop m/s: Croka Motor

Tel: 6752 7740

of 1 Keiki Bukit Avenue 6 #02-02 Autobay

Policy No: DMPC SH 9335219000

Claim No: SNM 20D 201265

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 10/03/2020

CA / REV / REP. / REV 24 HRS

lwp1

20/03/2020

H.O.D. Endorsement:

Date/Time: 5:08pm @ 19/3/2020

Person Contacted:

Lee Lee

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	FBH 551K - X	
	SJY 7943H - X	

RECEIVED 25 MAR 2020

Surveys m

REF: CTI 5/CTI 200472/4/013

ASSIGNMENT

From: Date: 20.3.2020

Veh No: FBH 551K Yr Regn: 213

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

To Inspect Vehicle No: FBH 551K at Workshop m/s Erofin motor of 1 Kaki Bukit Ave 6 702-62

Make: Honda ANF 125 c.c 125

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No: Botby Puy

C/No: MLH JA203XR5000405

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70-90-17

R: 80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 2500/k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp"

Vehicle: IN / OUT

Date: Person Contacted:

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. mm L/Bal. mm

D.O.A. 10/3/20 D.O.I. 20/3/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, O/S 20%

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
25/3/20	24A 440 Bal 24.5/11ah. CD 1 f: 1mb 2/5 @ 1200 with AH key (Red. (Red: 4206.70, 77%))

Date/Time, File Pass to? Preli. Report

1) 25/3/20 Typist Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: 270

Transportation: \$ + RS, \$

Photos

Others

TOTAL: 270

Report Format: TP

Lump Sum / I.B.I: (\$ 1200)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2020 11:41
Date Of Accident	10/03/2020 12:40
Exact Location Of Accident	ALONG LORONG 06 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH551K
Insured/Policyholder	
Name Of Registered Owner	POH TIAN POH
NRIC No	SXXXX317A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82256526
Alternative Phone No	OTHERS-82256526
Vehicle Particulars	
Manufacturer	HONDA
Model	ANF125MSS A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5097874564-02
Cover Note Number	
Driver	
Name of Driver	POH TIAN POH
NRIC No	SXXXX317A
Date Of Birth	11/03/1952
Occupation	INDOOR
Date Of Driving Pass	12/02/1976
Driving Experience	44 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82256526
Fax Number	
Contact Number	OTHERS-82256526
Email Address	NOEMAIL

Address	BLK 8 #07-433 HAIG ROAD
Postcode	430008
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KIM KEAT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 231 LORONG 8 TOA PAYOH , POSTCODE: 310231 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2529999 - FAX NO: 63554311
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20200312/2049:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJY7943H
Vehicle Make/Model/Colour	VOLKSWAGEN / JETTA 1.4 TSI AT 1K23Q5 MX
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG GIM TENG
NRIC/Passport Number	SXXXX937H
Contact Number	91259130
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	POH TIAN POH
Approximate Age	68
Injuries Sustain	
Injured person in which vehicle?	FBH551K
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 8 #07-433 HAIG ROAD
Postcode	430008

Accident Sketch Plan

1. Name of the accident: ...

2. Date and time of the accident: ...

3. Location of the accident: ...

4. Name of the driver: ...

5. Name of the witness: ...

6. Name of the police officer: ...

7. Name of the insurance company: ...

8. Name of the lawyer: ...

9. Name of the court: ...

10. Name of the judge: ...

11. Name of the jury: ...

12. Name of the jury foreman: ...

13. Name of the jury clerk: ...

14. Name of the jury bailiff: ...

15. Name of the jury witness: ...

16. Name of the jury witness: ...

17. Name of the jury witness: ...

18. Name of the jury witness: ...

19. Name of the jury witness: ...

20. Name of the jury witness: ...

21. Name of the jury witness: ...

22. Name of the jury witness: ...

23. Name of the jury witness: ...

24. Name of the jury witness: ...

25. Name of the jury witness: ...

26. Name of the jury witness: ...

27. Name of the jury witness: ...

28. Name of the jury witness: ...

29. Name of the jury witness: ...

30. Name of the jury witness: ...

31. Name of the jury witness: ...

32. Name of the jury witness: ...

33. Name of the jury witness: ...

34. Name of the jury witness: ...

35. Name of the jury witness: ...

36. Name of the jury witness: ...

37. Name of the jury witness: ...

38. Name of the jury witness: ...

39. Name of the jury witness: ...

40. Name of the jury witness: ...

41. Name of the jury witness: ...

42. Name of the jury witness: ...

43. Name of the jury witness: ...

44. Name of the jury witness: ...

45. Name of the jury witness: ...

46. Name of the jury witness: ...

47. Name of the jury witness: ...

48. Name of the jury witness: ...

49. Name of the jury witness: ...


50. Name of the jury witness: ...

POH — — — — — POH


Police Officer

(POLICE OFFICER)
 22 KAVELAN AVENUE #02-07
 Singapore 110225
 Tel: 6746 6746
 Fax: 6746 6746
 Email: 6746 6746

Accident Sketch Plan



refer to police report no. 1/2004/2/204



POH

POH

Police Department
1000 Park Ave. #1000
Singapore 11000
Tel: 6742 4000 Fax: 6749 7300



**SINGAPORE
POLICE FORCE**



T/20200312/2049

1 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20200312/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/03/2020 13:07		Vide Report No.:		Station Diary No.: 16	
Informant's Particulars					
Name of Informant: POH TIAN POH			Address: APT BLK 8 HAIG ROAD #07-433 SINGAPORE 430008		
ID Type / ID No.: NRIC NO / S0715317A			Contact No.:		Mobile: 82256526
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 68	Date of Birth: 11/03/1952	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/03/2020 12:40	Type of Location:
Location: LORONG 6 TOA PAYOH TRAFFIC JUNCTION TURNING TO FLYOVER (PIE)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No Yes <i>Sgt Anon</i>

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH551K	Motorcycle	HONDA	ANF125MSS A	Black		0
SJY7943H	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBH551K	NTUC Income Insurance Co-Operative Limited	5097874564-02	21/02/2020	20/02/2021



**SINGAPORE
POLICE FORCE**



T/20200312/2049

2 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20200312/2049

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	POH TIAN POH	ID No.	S0715317A
Related Vehicle	FBH551K (Motorcycle)	Contact No.	82256526
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	10/03/2020	Date Discharge	10/03/2020
No. of Days granted Medical Leave	07	Degree of Injury	NIL Serious & Sgt Aman
Driver			
Name	ONG GIM TENG	ID No.	S8711937H
Related Vehicle	SJY7943H (Car)	Contact No.	91259130
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION

I WAS ON THE WAY TO TAN TOCK SENG HOSPITAL FOR MY CHECKUP, I WAS AT THE TRAFFIC LIGHT AND WHEN IT TURNED GREEN I CONTINUED DRIVING FORWARD, THEN SUDDENLY VEHICLE SJY7943H CRASH INTO THE REAR OF MY BIKE. I FELL ALONG WITH MY BIKE, THEN THE DRIVER OF SJY7943H GOT OUT OF THE VEHICLE AND HELPED ME UP. THE DRIVER ADMITTED THAT IT WAS HIS MISTAKE AND HE CALLED THE AMBULANCE FOR ME. THE AMBULANCE THEN CAME AND I WAS CONVEYED TO TAN TOCK SENG HOSPITAL.



**SINGAPORE
POLICE FORCE**



T/20200312/2049

3 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999



Report No. T/20200312/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 1 AMANULLAH BIN ABDUL RAHIM	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 12/03/2020 13:07
Officer In Charge Of Case: TP / GIT / SI ONG CHEE HIEN Contact No.: 65476437	Classification Of Case: SN 64
Authentication Stamp NP168	 <p>SIGNATURE</p>



**SINGAPORE
POLICE FORCE**



T/20200311/2046

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200311/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/03/2020 12:36	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars				
Name of Informant: POH TIAN POH		Address: APT BLK 8 HAIG ROAD #07-433 HAIG VIEW SINGAPORE 430008		
ID Type / ID No.: NRIC NO / S0715317A		Contact No.: Home/Office:		Mobile: 82256526
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 68	Date of Birth: 11/03/1952	Type of Informant: Rider	
Race: Chinese		Language:		Institution / School Name:
Occupation: DRIVER		Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 10/03/2020 12:40	Type of Location: Straight Road
Location: Along Road 1 LORONG 2 TOA PAYOH				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH551K	Motorcycle	HONDA	ANF125MSS A	Black		0
SJY7943H	Car	VOLKSWAGO N	JETTA 1.4 TSI AT 1K23Q5 MX	Red		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200311/2046

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBH551K	NTUC Income Insurance Co-Operative Limited	5097874564-02	21/02/2020	20/02/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	POH TIAN POH		ID No.	S0715317A
Related Vehicle	FBH551K (Motorcycle)		Contact No.	82256526
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	10/03/2020		Date Discharge	10/03/2020
No. of Days granted Medical Leave	07		Degree of Injury	Serious
Driver				
Name	ONG GUN TENG		ID No.	S8711937H
Related Vehicle	SJY7943H (Car)		Contact No.	91259130
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME & LOCATION.

I WAS ON THE WAY TO TAN TOCK SENG HOSPITAL FOR MY CHECKUP. WHILE ON MY WAY, I WAS AT A TRAFFIC LIGHT AND WHEN IT TURNED GREEN I CONTINUE DRIVING FORWARD, THEN SUDDENLY VEHICLE SJY7943H CRASH INTO THE REAR OF MY BIKE. I FELL ALONG WITH MY BIKE, THEN THE DRIVER OF SJY7943H GOT OUT OF THE VEHICLE AND HELPED ME UP. THE DRIVER ADMITTED THAT IT WAS HIS MISTAKE AND HE CALLED THE AMBULANCE FOR ME. THE AMBULANCE THEN CAME AND I WAS CONVEYED TO TAN TOCK SENG HOSPITAL.



**SINGAPORE
POLICE FORCE**



T/20200311/2046

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20200311/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
WINSTON KOH WEN ZHONG *wt*

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
SI ONG CHEE HIEN
Contact No.: 65476437

Authentication Stamp
NP168

Signature Of Informant:

POH

Date/Time:
11/03/2020 12:36

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature: *wt*

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 317A

Vehicle Details

Vehicle No.: FBH551K
Vehicle to be Exported: No
Intended Deregistration Date: 23 Mar 2020
Vehicle Make: HONDA
Vehicle Model: ANF125M55A
Primary Colour: Black
Manufacturing Year: 2012
Engine No.: JA203E2000405
Chassis No.: MLHJA203XB5000405
Maximum Power Output: -
Open Market Value: \$1,588.00
Original Registration Date: 21 Feb 2013
First Registration Date: 21 Feb 2013
Transfer Count: 0
Actual ARF Paid: \$239.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Feb 2023
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$1,512.00
COE Rebate Amount: \$440.00
Total Rebate Amount: \$440.00

The information contained herein is correct as at 12 Mar 2020

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
ROAD TRANSPORT (AMENDMENT) ACT, 2019 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5097874564-02 Cover : Third Party

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : FBH551K |
| Chassis Number | : MLHJA203XB5000405 |
| 2. Name of Policyholder | : POH TIAN POH |
| 3. Effective Date of Insurance | : 21 Feb 2020 |
| 4. Expiry Date of Insurance | : 20 Feb 2021 |
| 5. Persons or Classes of Persons entitled to drive# | |

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: POH TIAN POH
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : THINK ONE AUTOMOBILE & TRADING PTE LTD (00000571089)
Date of Issue : 05 Feb 2020 13:48 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Chief Executive

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 317A

Vehicle Details

Vehicle No.: FBH551K
Vehicle to be Exported: No
Intended Deregistration Date: 23 Mar 2020
Vehicle Make: HONDA
Vehicle Model: ANF125MSS A
Primary Colour: Black
Manufacturing Year: 2012
Engine No.: JA203E2000405
Chassis No.: MLHJA203XB5000405
Maximum Power Output: -
Open Market Value: \$1,588.00
Original Registration Date: 21 Feb 2013
First Registration Date: 21 Feb 2013
Transfer Count: 0
Actual ARF Paid: \$239.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Feb 2023
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$1,512.00
COE Rebate Amount: \$440.00
Total Rebate Amount: \$440.00

The information contained herein is correct as at 23 Mar 2020

OK

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

MIVA

Owner : Poh Tian Poh

Accident Date : 10-Mar-20

Vehicle No : FBH 551 K

Vehicle Model : Honda Wave

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes <i>L R 80</i>	\$ <i>Best</i> 240.00 <i>x</i>
2	Fork outer tubes	\$ <i>SC</i> 250.00 <i>x</i>
1	Fork under bracket	\$ <i>17</i> 185.00 <i>x</i>
1	Front sport rim	\$ <i>17</i> 320.00 <i>x</i>
1	Front rim shaft	\$ <i>17</i> 42.00 <i>x</i>
1	Front rim bearing	\$ <i>17</i> 38.00 <i>x</i>
1	Front brake disc	\$ <i>17</i> 155.00 <i>x</i>
1	Headlamp	\$ <i>17</i> 95.00 <i>x</i>
2	Side mirrors <i>48</i>	\$ <i>OK/17</i> 96.00 <i>PC</i>
2	Front signals	\$ <i>17</i> 100.00 <i>x</i>
1	Handle-bar	\$ <i>Best</i> 105.00 <i>x</i>
1	Handle-bar end	\$ <i>SC</i> 35.00 <i>—</i>
1	Hand grip	\$ <i>17</i> 50.00 <i>✓</i>
1	Brake lever	\$ <i>SC</i> 32.00 <i>—</i>
1	Front footrest bracket	\$ <i>SC</i> 55.00 <i>—</i>
1	Front footrest rubber	\$ <i>17</i> 28.00 <i>—</i>
1	Brake pedal	\$ <i>17</i> 48.00 <i>—</i>
1	Rear footrest -R/H	\$ <i>17</i> 38.00 <i>x</i>
1	Rear footrest bracket	\$ <i>17</i> 65.00 <i>x</i>
1	Exhaust assy	\$ <i>SC</i> 425.00 <i>x</i>
1	Exhaust protector	\$ <i>SC</i> 65.00 <i>—</i>
1	Rear taillamp	\$ <i>17</i> 88.00 <i>x</i>
2	Rear absorbers <i>198</i>	\$ <i>NISUM</i> 390.00 <i>PC</i>
1	Swing-arm	\$ <i>17</i> 385.00 <i>x</i>
1	Chain cover	\$ <i>SC</i> 185.00 <i>x</i>
1	Rear fender	\$ <i>17</i> 68.00 <i>—</i>
1	Fairing assy (1 set)	\$ <i>17</i> 505.00 <i>✓</i>
		\$ 4,088.00
	Less 10%	\$ 408.80
		\$ 3,679.20

Not Allowed

2/5 # 1200 / 4 hrs.

Whip...

1234
102
11106

c/f: \$ 3,679.20

Special Nett Items

1	Number plate (1 set) <i>Rec</i>	\$	<i>Rec</i>	28.00	<i>10</i>
2	Fork oils	\$	<i>11</i>	30.00	<i>2</i>
2	Fork oil seals	\$	<i>17</i>	56.00	<i>2</i>
1	Steering cone bearing (1 set)	\$	<i>11</i>	85.00	<i>X</i>
1	Rear box	\$	<i>cur</i>	250.00	<i>150</i>
1	Rear box bracket	\$	<i>11</i>	100.00	<i>X</i>
1	Front tyre	\$	<i>11</i>	150.00	<i>2</i>
1	Helmet	\$	<i>11</i>	120.00	<i>X</i>
		\$		<u>819.00</u>	

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service.	\$		50.00	<i>35</i>
2	To check wiring and reset headlamp focusing	\$	<i>11</i>	80.00	<i>X</i>
3	To provide labour.	\$		380.00	<i>250</i>
4	To repair body frame.	\$	<i>11</i>	400.00	<i>X</i>
		\$		<u>910.00</u>	

Grand Total \$ 5,408.20



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

1533-6
27
1244

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2020		25 Mar 2020 10:37 Edit Adj Rpt	\$1,200.00 Edit Estimates	\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	POH TIAN POH		
Vehicle Reg. No.:	FBH551K	Date of Loss:	10/03/2020 12:00 - :59 [84 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D201265	Policy/Cover Note No.:	DMPCSN19335219000
Vehicle Reg. No. (Insured):	SJY7943H	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/04/2020]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***FBH551K (SNM20D201265)**
[SJY7943H]
 TP
POH TIAN POH
Mar 10 2020 12:00PM
 [-]
Erofia Motor Trading Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View In Browser		
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
2	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
3	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
4	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
5	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
6	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
7	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
8	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
9	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
10	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
11	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
12	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
13	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
14	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
15	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
16	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
17	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
18	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
19	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
20	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
21	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
22	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
23	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
24	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
25	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
26	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
27	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
28	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
29	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
30	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
31	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
32	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
33	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
34	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
35	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
36	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	
37	25/03/20 11:02	General View				Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
39	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
40	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
41	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
42	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
43	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
44	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
45	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
46	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
47	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
48	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
49	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
50	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
51	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
52	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
53	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
54	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
55	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
56	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
57	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
58	25/03/20 11:02	General View	Load JPG	<input checked="" type="checkbox"/>
59	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	25/03/20 11:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120004272/UTD3E2

Date: 01/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN19335219000
Claimant Vehicle No :	FBH551K	Insured Vehicle No :	SJY7943H
Date of Loss:	10/03/2020	Nature of Claim:	TP
		Claim No:	SNM20D201265

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH551K	Engine No:	JA203E2000405
Make & Model:	HONDA ANF125, 125cc (A)	Chassis No:	MLHJA203XB5000405
Reg. Date:	21/02/2013 (Man. Year: 2012)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	80-90-17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,498.20	1,350.60	3,147.60	69.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	285.00	625.00	68.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,408.20	1,635.60	3,772.60	69.76
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	5,408.20	1,200.00	4,208.20	77.81

INSPECTION

Date of Assignment:	25/03/2020		
Date Inspected:	20/03/2020	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 01 Apr 2020)
Parts:	N/A HONDA ANF125 125cc (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH551K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES (LOCAL REPAIR)	Bent	216.00 FS	*80.00 FS
2	2		*FORK OUTER TUBES	Serviceable	250.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
4	1		*FRONT SPORT RIM	Not Necessary	320.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	42.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
7	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
8	1		*HEADLAMP	Not Necessary	95.00 FL	*- FL
9	1		*SIDE MIRRORS	O/S Cut	96.00 FL	*48.00 FL
10	2		*FRONT SIGNALS	Not Necessary	100.00 FL	*- FL
11	1		*HANDLE-BAR	Bent	105.00 FL	*105.00 FL
12	1		*HANDLE-BAR END	Scratched	35.00 FL	*35.00 FL
13	1		*HAND GRIP	Necessary	50.00 FL	*50.00 FL
14	1		*BRAKE LEVER	Scratched	32.00 FL	*32.00 FL
15	1		*FRONT FOOTREST BRACKET	Bent	55.00 FL	*55.00 FL
16	1		*FRONT FOOTREST RUBBER	Torn	28.00 FL	*28.00 FL
17	1		*BRAKE PEDAL	Cut	48.00 FL	*48.00 FL
18	1		*REAR FOOTREST - R/H	Not Necessary	38.00 FL	*- FL
19	1		*REAR FOOTREST BRACKET	Not Necessary	65.00 FL	*- FL
20	1		*EXHAUST ASSY	Serviceable	425.00 FL	*- FL
21	1		*EXHAUST PROTECTOR	Scratched	65.00 FL	*65.00 FL
22	1		*REAR TAILLAMP	Not Necessary	88.00 FL	*- FL
23	1		*REAR ABSORBERS	N/S Twisted	390.00 FL	*195.00 FL
24	1		*SWING-ARM	Repair	385.00 FL	*- FL
25	1		*CHAIN COVER	Serviceable	185.00 FL	*- FL
26	1		*REAR FENDER	Deformed	68.00 FL	*68.00 FL
27	1		*SET FAIRING ASSY	Cut	505.00 FL	*505.00 FL
28	1		*REAR NUMBER PLATE	Bent	28.00 FS	*10.00 FS
29	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
31	1		*SET STEERING CONE BEARING	Not Necessary	85.00 FS	*- FS
32	1		*REAR BOX	Cut	250.00 FS	*150.00 FS
33	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
34	1		*FRONT TYRE	Not Necessary	150.00 FS	*- FS
35	1		*HELMET	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,883.00	1,474.00
- List Item Discount on L Items 10.00/10.00% (S\$)	384.80	123.40
Total Parts (S\$)	4,498.20	1,350.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING, AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
4	TO REPAIR BODY FRAME	New	400.00	0.00
Gross Labour Cost (S\$)			910.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >