

ASS. REC. BY: PaulREF: CC4/FCI20004275/ ea3

848A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SMK 573 Bat Workshop m/s PERFORMANCEof 303, MURMURA RDInsured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 113K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMK 573 B Yr Regn: 2019 / MARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 216 I 4000 cc 1499Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 26975 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB96V12020ED05730Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/03/2020 D.O.I. 22/06/2020Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	848A
Vehicle No.:	SMK573B
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2020
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	35185504B38A15A
Chassis No.:	WBA6V12020ED05730
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$31,412.00
Original Registration Date:	28 Mar 2019
First Registration Date:	28 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$35,977.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2029
PARF Rebate Amount:	\$26,982.00
COE Expiry Date:	27 Mar 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,659.00
COE Rebate Amount:	\$23,362.00
Total Rebate Amount:	\$50,344.00

The information contained herein is correct as at 22 Jun 2020

OK



Used 2019 BMW 2 Series 216i Gr. X



Merimen e-Claims X



PARE/CC

mart.com/used_cars/info.php?ID=869446&DL=3365

▶ BMW 2 Series 216i Gran Tourer

Overview

Financial

Accessories

Similar

Research

Photos

Map



Our Accreditations

Singapore
Vehicle
Traders
Association

Price \$119,800

Depreciation ⓘ \$11,570 /yr
View models with similar depreReg Date 16-Sep-2019
(9yrs 2mths 24days COE left)

Mileage 50 km

Manufactured ⓘ 2019

Road Tax ⓘ \$684 /yr

Transmission Auto

Dereg Value ⓘ \$48,912 as of today (change)

OMV ⓘ \$24,215

COE ⓘ \$31,917

ARF ⓘ \$25,901

Engine Cap 1,499 cc

Power 80.0 kW (107 bhp)

Curb Weight ⓘ 1,490 kg

No. of Owners ⓘ 1

Type of Vehicle MPV

Features

109Bhp TwinPower Turbocharged Engine, 190Nm Torque, 7 Speed DCT Gearbox, 0 To 100Km/H In 11.7s, Bluetooth, Keyless Start/Stop, Reverse Sensors. View specs of the BMW 2 Series Gran Tourer

