

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC3/AXA13013412/Kha3s2-1		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: RICHARD ANG			Date: 14-04-2020 Code: AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJL 7912R	Veh. Inspected	SHD 5264G	
	Policy No.	P0735858	Coverage (\$)	0.00	
	Claim No.	C0276628	Excess (\$)	0.00	
	Assign From		Assign Date	24/07/2013	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH (A)	c.c	1987	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	JTDGJ20W805001962	Colour	RED	
	Odometer	386915	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	FALKEN	7 mm	
	L/H Front Tyre	195/65 R15	FALKEN	7 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	3 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	3 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/07/2013	Inspection Date	24/07/2013	
	Survey held at	y held at TRANS-CAB AUTO SERVICES PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	_				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			