

22/03/2002

ASS. REC. BY:

REF:

CS3/CT1 20004315/Gg f3⁵²

Special Instruction:

Survivor: GQ

ASSIGNMENT (Office)

From (Person): Tan Kah Leng of CT1 Date/Time: 20.3.2000 16.37p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 1846B Insured: GBE 95771

at Workshop m/s Eng Shing Mechanical Tel: 64537380
of 160 Sin Ming Pkwy #06-21

Policy No: DMCVSN30373919022 Claim No: SNM2007201358

Sum Insured: Excess:

Make of Veh: D.O.A. 17.3.2000
(Client's Record) 23.3.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 20.3.2000 5.13p.m Person Contacted: Mr Ong H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLX 1846B - X
	GBE 95771 - CS/EGJ19000434/UC19362-1 H.O.A - 04/01/2019
21/3/20	Submit Pres.

PRS

ASSIGNMENT

From:

Date: 23.3.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 1846B

at Workshop m/s Eng Shing mechanical

of 160 sin ming Drive #06-21

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX1846B

Yr Regn: 19 Mar 2018

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c 1318

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

40918

T/Radio: Insured / Std / NI / NA

Eng/No:

JHMERK 3850 JX 213928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23-03-20

Survey held at

w/s

2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

24/3/2020

RECEIVED 24 MAR 2020

Date/Time, File Pass to?

04/3/2020

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

PRS.

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	18 Mar 2020		20 Mar 2020 16:37 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TAN TUA CHYE ANDY		
Vehicle Reg. No.:	SLX1846B	Date of Loss:	17/03/2020 00:00 - :59
Claim Type:	TP / SNM20D201358	Policy/Cover Note No.:	DMCVSN30373919022 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE9577T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/03/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Pauline Tham <pauline.tham@sg.cntaiping.com>
Sent: Friday, 20 March, 2020 4:35 PM
To: Oracle Law Corp; Tan Kah Leong
Cc: sur@lkkauto.com; assignments@lkkauto.com; admin-d@lkkauto.com
Subject: FW: Our Ref: SB/PO/Acc/2020-9330 Your Ref: SNM20D201358/GBE9577T/TKL
Attachments: 1- 9330 - CNTP PRI_20200318105126.pdf; 2- 9330 - LIST OF MS_20200318155625.pdf
Importance: High

Without Prejudice

Dear Alvin,

Thanks for your call.

Dear LKK.

Oracle Law inform that car will be in the workshop on Monday.

Please contact workshop directly.

Details of Workshop

Eng Shing Mechanical Works
160 Sin Ming Drive
#06-21 Sin Ming Autocity S(575722)
Tel No.: 6453-7380 ; Fax No. 6252-4129

Thanks.

Pauline Tham

Senior Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Pauline Tham

Sent: Wednesday, March 18, 2020 4:12 PM

To: Oracle Law Corp <mail@oraclelaw.sg>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Subject: RE: Our Ref: SB/PO/Acc/2020-9330 Your Ref: SNM20D201358/ GBE9577T/TKL
Importance: High

Without Prejudice

Hi Karol,

We refer to your letter.

We are not agreeable to your proposed surveyor.

We will assign our panel surveyor M/s LKK Auto to conduct the Pre-repair survey.

Please contact our surveyor to conduct the pre repair inspection before returning the repaired vehicle to the claimant.

Dear LKK

Please liaise with third party on PRS.

Thanks.

Pauline Tham
Senior Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Wednesday, March 18, 2020 4:01 PM
To: Pauline Tham <pauline.tham@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Our Ref: SB/PO/Acc/2020-9330 Your Ref: SNM20D201358/ GBE9577T/TKL

Dear Pauline

PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SLX 1846B & GBE 9577T ALONG HORNE ROAD PARKING LOT
NO:20 INFRONT OF NTUC ON 17-03-2020 @ 8 A.M.

Please refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Karol Su

From: Pauline Tham <pauline.tham@sg.cntaiping.com>
Sent: Wednesday, 18 March 2020 2:31 pm
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Oracle Law Corp <mail@oraclelaw.sg>
Subject: RE: OUR REF: SNM20D201358/ GBE9577T/TKL - Your Ref: SB/PO/Acc/2020-9330

Without Prejudice

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.
We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS / STA

Adrian Ling
Kelvin Ang
See Chew Seng
Mohd Fadhilah Bin Osman
Xing Quo Qiang
Kenneth Kong
Simon Ho
Chua Weijie
Marcus Chua
Henry Ng

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.
Thank you.

Thanks.

Pauline Tham
Senior Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6541 | F: (65) 6224 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, March 18, 2020 1:32 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; mail@oraclelaw.sg; Pauline Tham <pauline.tham@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D201358/ GBE9577T/TKL - Your Ref: SB/PO/Acc/2020-9330

Dear Pauline,

Please assist to conduct PRS for SLX1846B.

Note : officer in charge – Kah Leong 63896193.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Oracle Law Corp <mail@oraclelaw.sg>
Sent: Wednesday, March 18, 2020 10:54 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Our Ref: SB/PO/Acc/2020-9330 Your Ref: Insurer of GBE 9577T

Dear Sir,

PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SLX 1846B & GBE 9577T ALONG HORNE ROAD PARKING LOT NO:20 INFRONT OF NTUC ON 17-03-2020 @ 8 A.M.

Please refer to attachments the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Karol Su

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045722

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/03/2020 16:48
Date Of Accident	17/03/2020 08:00
Exact Location Of Accident	HORN ROAD (PARKING LOT NO:20)INFRONT NTUC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX1846B
Insured/Policyholder	
Name Of Registered Owner	TAN TUA CHYE ANDY
NRIC No	SXXXX847E
Email Address	ANDY-NONI@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96804389
Alternative Phone No	OFFICE-96804389

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.3 L (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MT001958-R00
Cover Note Number	

Driver

Name of Driver	TAN TUA CHYE ANDY
NRIC No	SXXXX847E
Date Of Birth	06/06/1968
Occupation	INDOOR
Date Of Driving Pass	24/08/1993
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96804389
Fax Number	
Contact Number	OFFICE-96804389
Email Address	ANDY-NONI@YAHOO.COM


Sketch Plan Pg. 1


Vehicle Number SV 1846E


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed** by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

12:34pm
17 MAR 2020

Reporting Centre Personnel's Signature
Name: **ARY CHUA** DID : +65 6946 6973
NRIC/FIN No.: HP : +65 9186 5437
Email : arychua@hogda.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	847E
Vehicle Details	
Vehicle No.:	SLX1846B
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Mar 2020
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	L13B11030426
Chassis No.:	JHMGK3850JX213928
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$15,285.00
Original Registration Date:	19 Mar 2018
First Registration Date:	19 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$5,285.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2028
PARF Rebate Amount:	\$3,963.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,000.00
COE Rebate Amount:	\$31,929.00
Total Rebate Amount:	\$35,892.00

The information contained herein is correct as at 23 Mar 2020

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Mar 2020		20 Mar 2020 16:37 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -			
Main Claimant:	TAN TUA CHYE ANDY			
Vehicle Reg. No.:	SLX1846B	Date of Loss:	17/03/2020 00:00 - :59 [23 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM20D201358	Policy/Cover Note No.:	DMCVSN30373919022 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBE9577T	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Eng Shing Mechanical Works (HQ) 160 Sin Ming Drive, #06-21 Sin Ming Autocity, 575722 Sin Ming - Tel: 64537380			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/03/2020]			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLX1846B (SNM20D201358)**
[GBE9577T]




































TP

TAN TUA CHYE ANDY

Mar 17 2020 12:00AM

[-]

Eng Shing Mechanical Works

Upload Documents Upload Photos Compose New Letter			View View In Browser ▼	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/03/20 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/03/20 09:28	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/20 10:17	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/20 10:18	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
37	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
38	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
39	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
40	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
41	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
42	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
43	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
44	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
45	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
46	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
47	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
48	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
49	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
50	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
51	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
52	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
53	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
54	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
55	25/03/20 10:18	Dismantled Parts	 Load JPG	✓
56	25/03/20 10:18	Dismantled Parts	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20004315/GQF3S2
Date: 26/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30373919022
Claimant Vehicle No: SLX1846B Insured Vehicle No: GBE9577T
Date of Loss: 17/03/2020 Nature of Claim: TP Claim No: SNM20D201358

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX1846B Engine No: L13B11030426
Make & Model: HONDA JAZZ, 1.3 L (A) Chassis No: JHMGK3850JX213928
Reg. Date: 19/03/2018 (Man. Year: 2018) Odometer: 40918 km
Colour: Grey
Engine Capacity: 1318 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/03/2020
Date Inspected: 23/03/2020 Inspected At: Eng Shing Mechanical Works (HQ)
160 Sin Ming Drive, #06-21 Sin Ming Autocity
Singapore 575721
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2020)
Parts:	144	HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX1846B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >