

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AIG	DATE	: 20-Mar-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT:			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJL9490C	Asher.	
MODEL	: MAZDA 3	JM6BN24ASJ0175739	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 18-Mar-20
		TIME	: 12:15HRS
THIRD PARTY REQUESTOR / CONTACT JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del</i>	1	\$ 1,080.00	\$ 1,080.00
2	FRONT BUMPER SIDE RETAINER <i>ne LH</i>	2	\$ 64.50	\$ 129.00
3	FRONT BUMPER REINFROCEMENT <i>ne</i>	1	\$ 630.00	\$ 630.00
4	FRONT BUMPER REINFROCEMENT COVER <i>ne</i>	1	\$ 155.60	\$ 155.60
5	FRONT BUMPER DAYLIGHT LH <i>ne</i>	1	\$ 230.00	\$ 230.00
6	FRONT BUMPER DAYLIGHT HOUSING LH <i>ne</i>	1	\$ 120.00	\$ 120.00
7	HEADLAMP (LED) LH <i>could</i>	1	\$ 3,598.60	\$ 3,598.60

TOTAL PRICE \$ 5,943.20

LESS 20% \$ 1,188.64

SUB TOTAL PRICE \$ 4,754.56

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>ne</i>	1	\$ 25.00	\$ 25.00

TOTAL \$ 25.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>200</i>	
---	--	-------------	------------	--

2	TO SPRAY PAINT AFFECTED AREA	\$	1,000.00	200	
3	WIRING CHECK	\$	80.00	30	

430

TOTAL

\$2,080.00

ESTIMATE REPORT

TOTAL PARTS COS: \$ 4,779.56

TOTAL LABOUR CO: \$ 2,080.00

TOTAL REPAIR COS: \$ 6,859.56

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj
t/s 20/03/20
03 Days

total: 4345.48.

t/s: 3.4K. ✓

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: