

VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue 9
Singapore 639197
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/1

Document no.
Document date 23-03-2020
Customer no. 5211050673
Customer GST-ID
Dealer 39999
Job order number 2020000812/ 1
Job order date 23-03-2020
Service Advisor TIOU CHUAN CHEE

License plate SLG6292E	Model code 5C83EZB0	First registration 23-01-2020	VIN WWWZZZ16ZKM509501	Model Beetle Cabriolet 1.2 I TSI 77kW DSG	Mileage 500
---------------------------	------------------------	----------------------------------	--------------------------	--	----------------

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
5C5807217BHGRU	Cover For Bumper Primed FRT BUMPER <i>x R</i>	1	pcs.	1,313.79	#1	1,313.79	1,405.76
5C5807184A	Guide Piece RHF SIDE BRACKET <i>x ?</i>	1	pcs.	33.43	#1	33.43	35.77
5C5821022D	Fender RHF <i>x R</i>	1	pcs.	597.40	#1	597.40	639.22
5C5821136	Cross Support RHF FENDER BRACKET <i>?</i>	1	pcs.	66.37	#1	66.37	71.02
5C2941032D	Gas Discharge Headlight W RHF <i>x</i>	1	pcs.	2,859.28	#1	2,859.28	3,059.43
	LABOUR	<i>A1.5</i>	pcs.	840.00	#1 <i>1260</i>	3,360.00	3,595.20
	Spray Painting	<i>A2</i>	pcs.	800.00	#1 <i>1600</i>	3,200.00	3,424.00
	AIG DIRECT SETTLEMENT DOA : 21/03/2020 TP VEH : SCG5522E SURVEY BY :						

Quotation valid till 30-03-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	11,430.27	7%	853.32	12,190.27	13,043.59
Total	760.00	11,430.27		853.32	12,190.27	13,043.59

Steve CLKK)
8322 8813

WRL PHL
P/P

Customer

Ry PHL SLY
27/3/20, 11-15am

Service Advisor

VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions)

LKK and Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

4 days