



SMRT Accident Vehicle Repair Estimates

SMRT Taxis Pte Ltd
 Park E4, Singapore
 Number: 68662623
 Fax: 68662672
 14/2020
 Sun

Section A - Accident Details

Registration Number	SHF489Y
Case Reference Number	TAX/03/20/2060
Registration Date	30/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMED ZAHRI BIN ONAN
Type of Accident	Side Swipe
Accident Date and Time	19/3/2020 10:30 PM
Accident Reported Date and Time	20/3/2020 10:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106235
Special Instruction to ARC, if any	RIGHT HAND PORTION DAMAGE
Prepared Date and Time	20/3/2020 2:29 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

60. +
 7.8 +
 21.6 +
 120. +
 670.8 +
 168.6 +
 1,048.8
 ..0..
 500. +
 950. +
 60. +
 20. +
 20. +
 1,550.
 ..0..
 1,048.8 +
 1,550. +
 2,598.8
 x
 80. x
 2,079.04 *

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$2,232.00	\$950.00
Total Spare Part Cost	\$5,722.70	\$1,048.80
Total Other Cost	\$820.00	(\$398.80)
TOTAL COST	\$9,619.70	\$2,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	25/03/2020 12:22 PM	25/03/2020 10:10 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP= 0 day.	Lump Sum Repair, After paint photo.