

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Mar 2020 Edit Reg		20 Mar 2020 00:00 Edit Adj Rpt	S\$800.00 Edit Estimates	S\$800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SUNDHARA ASTHAGIRI RAJ RAM ANANTH , ID: S7460523J, Tel: +6599999999									
Main Claimant: SMRT TAXIS PTE LTD									
Vehicle Reg. No.:	SHC4639X	Date of Loss:	19/03/2020 00:00 - :59 [66 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3177122702SG	Policy/Cover Note No.:	1900010556 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMH4909G	Policy No. (Claimant):	D-19093197MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 02/04/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (06/07/2020): Alert - Adj Mandate Approved (S\$1435.00) - SHC4639X - Claim Handler: Loh, Chee-H... - AIG_SG (25/03/2020): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4639X (3177122702SG)**
[SMH4909G]
TP
SMRT TAXIS PTE LTD
Mar 19 2020 12:00AM
[SUNDHARA ASTHAGIRI RAJ RAM ANANTH]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/20 11:21	TP VIDEO	Load MP4	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/04/20 12:56	Chassis Number	Load JPG	☒
2	07/04/20 12:56	Odometer Reading	Load JPG	☒
3	07/04/20 12:56	General View	Load JPG	☒
4	07/04/20 12:56	General View	Load JPG	☒
5	07/04/20 12:56	General View	Load JPG	☒
6	07/04/20 12:56	General View	Load JPG	☒
7	07/04/20 12:56	General View	Load JPG	☒
8	07/04/20 12:56	General View	Load JPG	☒
9	07/04/20 12:56	General View	Load JPG	☒
10	07/04/20 12:56	General View	Load JPG	☒
11	07/04/20 12:56	General View	Load JPG	☒
12	07/04/20 12:56	General View	Load JPG	☒
13	07/04/20 12:56	General View	Load JPG	☒
14	07/04/20 12:56	General View	Load JPG	☒
15	07/04/20 12:56	General View	Load JPG	☒
16	07/04/20 12:56	General View	Load JPG	☒
17	07/04/20 12:56	General View	Load JPG	☒
18	07/04/20 12:56	General View	Load JPG	☒
19	07/04/20 12:56	General View	Load JPG	☒
20	07/04/20 12:56	General View	Load JPG	☒
21	24/04/20 11:13	After Repair Photo	Load JPG	☒
22	24/04/20 11:13	After Repair Photo	Load JPG	☒
23	24/04/20 11:13	After Repair Photo	Load JPG	☒
24	24/04/20 11:13	After Repair Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/20 12:04	TP GIA REPORT	Load PDF	
2	24/03/20 12:04	TP ESTIMATE - MARKED	Load PDF	
3	02/04/20 15:53	LETTER TO OI	Load PDF	
4	04/07/20 11:26	LTA SEARCH	Load PDF	
5	04/07/20 11:26	LOD	Load PDF	
6	23/07/20 09:58	Authorisation to Act	Load PDF	
7	23/07/20 09:58	Release Voucher	Load PDF	
8	23/07/20 09:58	RENTAL MILEAGE	Load PDF	
9	23/07/20 09:58	RENTAL RECEIPT	Load PDF	

Video				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
10	23/07/20 09:58	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	26/03/20 08:19	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMH4909G (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4639X (TP veh)		
Date of Accident:	19/03/2020		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				5,118.40
Final Repair Cost	:	\$				800.00
Loss of Use	:	\$				200.00
						4.00 days at \$50.00 per day
Rental (if any)	:	\$				428.00
						4 days
LTA / GIA Search Fee	:	\$				7.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				1,435.00

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	1,435.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

23 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20004410/QEA3S2**Date:** 23/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900010556
Claimant Vehicle No :	SHC4639X	Insured Vehicle No :	SMH4909G
Date of Loss:	19/03/2020	Nature of Claim:	TP
		Claim No:	3177122702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4639X		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1422929
Reg. Date:	19/09/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U605750611
Colour:	Maroon	Odometer:	434967 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,046.40	476.03	2,570.37	84.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,072.00	420.00	1,652.00	79.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,118.40	896.03	4,222.37	82.49
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	5,118.40	800.00	4,318.40	84.37
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$107.00/day) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,435.00		

INSPECTION

Date of Assignment:	20/03/2020	
Date Inspected:	20/03/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Crushed	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F
3	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
4	1		*BUMPER SEAL, RR RH	Serviceable	65.70 F	*- F
5	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
6	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
7	1		*END PANEL	Serviceable	602.10 F	*- F
8	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
9	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
10	1		*FENDER RR/RH	Serviceable	766.80 F	*- F
11	1		*STICKER DECAL SMRT	Serviceable	7.80 F	*- F
12	1		*STICKER DECAL 6555 8888	Serviceable	21.60 F	*- F
13	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
F=Franchise part.						
					Total Parts (S\$)	3,046.40
						476.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	676.00	200.00
2	SPRAY PAINT.	New	936.00	200.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	20.00
5	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	0.00
6	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
7	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			2,072.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >