

## ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring #08-1339 Singapore 470130 Tel: 9450 7920

Date: 11/04/2020

Car Number: SGD2929D Model: NISSAN SYLPHY

Damaged Area: (Rear Right Portion Damaged)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair :

## Parts / Material:

1	Rear RH Door	
2	Rear RH Door Protector 165'. 00	
3	Rear RH Door Protector Clips	
4	Rear RH Door Weather Strip	
5	Rear RH Door Inner Trimboard	
6	Rear RH Door Inner Trimboard Clips	
7	Rear RH Door Top Hinge	
8	Rear RH Door lower Hinge	
9	Rear RH Door Glass Outer Channel	
10	Rear RH Door Glass Regulator Assy	
11	Rear RH Door Lock Assy	
12	Right Rocker Panel	
13	Rear RH Fender	

00	\$	985.00
su	\$	215.00
11	\$	25.00 ★
11	\$ \$	325.00 X
17	\$	475.00
11	\$	40.00 ×
47	\$	86.00 ×
11	\$	86.00 x
11	\$	295.00 ×
11	\$	525.00 >
11	\$	420.00 ×
11		Repair
~		Repair
Parts:	\$	3,477.00
Less Parts 10%:	\$	347.70
Total Parts :	\$	3.129.30

To Remove, Repair & Renew Affected Accident Areas To Putty, Spray Paint on Affected Accident Areas To Check & Re-Connect all electrical wiring To Renew & Re-Connect Rear RH Door Components To Conduct Wheel Alignment To Rust Proof Affected Areas

TOTAL PARTS:	\$ 3,129.30	
TOTAL LABOUR:	\$ 2,540.00	
TOTAL REPAIR COST:	\$ 5,669.30	9-1150
DATE OF CURVEY / INCREC	1:20	

DATE OF SURVEY / INSPECTED: 2/035 RECOMMENDED PART BY PART / LUMP SUM: RECOMMENDED NUMBER OF DAYS: SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

1372.

FINALISED AMOUNT:

	\$ 1,000.00 200
	\$ 900.00 HOO
	\$ 40.00 乂
	\$ 200.00 🕥
	\$ 11 200.00 x
	\$ 200.00 37
Total Labour :	\$ 2,540.00

LKK Auto Consultants nence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

## Acknowledged by Repairer

Signature:

Date: