

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2020 <a href="#">Edit Reg</a>		24 Mar 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:	MS DEBBIE HAN SIOW CHIN, ID: S7207044E			
Main Claimant:	TOH BOON CHIONG, ID: S7931762D			
Vehicle Reg. No.:	ET9292A	Date of Loss:	20/03/2020 00:00 - :59 [133 Months and 11 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 2475511340SG	Policy/Cover Note No.:	1700050249 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLR5601X	Policy No. (Claimant):		
		Excess:		
Repairer:	Sze Kang Automobile Spraying Services (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17, 568047 Ang Mo Kio - Tel: 64812712			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 02/04/2020]			
Claimant's Solicitor:	S L LAW CHAMBERS - Tel: 69099355/62924667			

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (25/03/2020): <a href="#">Request to upload TP GIA Report</a></li> </ul>		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													



## Claim Documents

**\*ET9292A (2475511340SG)**  
**[SLR5601X]**  
**TP**  
**TOH BOON CHIONG**  
**Mar 20 2020 12:00AM**  
**[MS DEBBIE HAN SIOW CHIN]**  
**Sze Kang Automobile Spraying Services**

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
10	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
11	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
12	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
13	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
14	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
15	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
16	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
17	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
18	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
19	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
20	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
21	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
22	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
23	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
24	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
25	06/04/20 15:47	General View	Load JPG	<input checked="" type="checkbox"/>
26	06/04/20 15:47	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
27	06/04/20 15:47	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>

**Documentation**
1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/03/20 14:41	OI GIA REPORT	Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG20004437/BQD3S2**Date:** 13/04/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700050249
<b>Claimant Vehicle No :</b>	ET9292A	<b>Insured Vehicle No :</b>	SLR5601X
Date of Loss:	20/03/2020	Nature of Claim:	TP
		Claim No:	2475511340SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>ET9292A</b>	Engine No:	VR38007769A
Make & Model:	NISSAN GTR, 3.8 (A)	Chassis No:	R35005299
Reg. Date:	09/02/2009 (Man. Year: 2008)	Odometer:	111035 km
Colour:	Grey		
Engine Capacity:	3799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	285/35 ZR20	Rear Tyre Size:	305/30 ZR20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	24/03/2020	
Date Inspected:	03/04/2020	Inspected At: Sze Kang Automobile Spraying Services (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17 Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT NUMBER PLATE GARNISH	Cut	0.00 F	*- F	
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F	
4	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*- F	
5	1		*FRT LH SIDE LAMP	Dislodged	0.00 F	*- F	
6	1		*FRT RH SIDE LAMP	Dislodged	0.00 F	*- F	
7	1		*FRT RH FENDER INNERSHIELD	Dislodged	0.00 F	*- F	
					<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**