

ASS. REC. BY:

REF: CS/AGI 2006 4450 /A/F3

Special Instruction:

Surveyor: Adnan ✓

ASSIGNMENT (Office)

From (Person): My Ramia

of AGI

Date/Time: 24.3.2020 3.09 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 1110D

Insured: SPJ 3456 A

at Workshop m/s CAS Garage Pte Ltd

Tel: 87827171

of 1 Kaki Bukit Ave 6 # 02-22

Policy No:

Claim No: C10006022

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.3.2020

25.3.2020

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time: 24.3.20 5.00p.m

Person Contacted: Allan

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJG 1110D - X
	SPJ 3456 A - (C71AIG 11009590 / UP5322 DOA - 19/05/2011)

ASS. REC. BY:

REF: AG1

ASSIGNMENT

From: _____ Date: 25.3.2020

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 11'0D

at Workshop m/s CAS Garage

of 1 kaki Bukit Axl L #02-22 Autobay

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 141

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJG110D. Yr Regn: 2016 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Odyssey C.C. 2356

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RC11118503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/45R18

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>25/03/20</u>	

Survey held at: CAS.

Des. of Damages: Frt / Rear / O/S / NI / UIC / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Budget Direct.</u>

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / L.S.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Add Fee: : Site Insp (\$) _____

: Interview (\$) _____

: Tech. Invs (\$) _____

: Weekend (\$) _____

Summer Lee (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Tuesday, 24 March, 2020 3:09 PM
To: Admin-D (LKKAuto)
Cc: SUR; Julie Mangubat
Subject: FW: PRI - ACCIDENT INVOLVING SJG 1110D AND SFJ 3456A ALONG BLK 459 TAMPINES ST 42 ON 22.03.2020 || C10006022
Attachments: SJG1110D.pdf; SFJ3456A.pdf

Hi Team,

We would like to arrange TP PRS for SJG1110D. TP has chosen Mr. Adrian to survey this vehicle.

Workshop information:

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185

F +65 6725 0853

E ivy.r@budgetdirect.com.sg

**Budget
Direct**
insurance



Customer Care +65 6221 2111

Claims +65 6221 2199

Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore

239924

budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is

confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Nicole Chong <nicole@casgarage.sg>
Sent: Tuesday, 24 March 2020 1:48 PM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Cc: Claims <claims@budgetdirect.com.sg>; Allan Goh <allan@casgarage.sg>; CAS Garage Garage <contact@casgarage.sg>; Julie Mangubat <julie.m@budgetdirect.com.sg>
Subject: Re: PRI - ACCIDENT INVOLVING SJG 1110D AND SFJ 3456A ALONG BLK 459 TAMPINES ST 42 ON 22.03.2020 || C10006022

Dear Ivy,

We request LKK Adrian to survey our client's vehicle.

From: Nicole Chong <nicole@casgarage.sg>
Sent: Tuesday, 24 March 2020 12:28 PM
To: Claims <claims@budgetdirect.com.sg>
Cc: Allan Goh <allan@casgarage.sg>; CAS Garage Garage <contact@casgarage.sg>
Subject: PRI - ACCIDENT INVOLVING SJG 1110D AND SFJ 3456A ALONG BLK 459 TAMPINES ST 42 ON 22.03.2020

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly arrange survey our client's vehicle

Do let us know when is the available date and time for inspection of the vehicle at:

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Thank you and have a nice day! Hope to hear from you soon

Regards,

Nicole Chong

Admin and Finance Officer

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

WITHOUT PREJUDICE

Regards,

Nicole Chong

Admin and Finance Officer

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay, Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

MSME20035814 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 23/03/2020 17:18
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/03/2020 17:18
Date Of Accident	22/03/2020 18:50
Exact Location Of Accident	BLK 459 TAMPINES ST 42
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG1110D
Insured/Policyholder	
Name Of Registered Owner	TAN KOK HWA
NRIC No	SXXXX563H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90475229
Alternative Phone No	OFFICE-90475229

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5085038183-03
Cover Note Number	

Driver

Name of Driver	TAN KOK HWA
NRIC No	SXXXX563H
Date Of Birth	09/12/1963
Occupation	INDOOR
Date Of Driving Pass	03/04/1981
Driving Experience	38 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90475229
Fax Number	
Contact Number	OFFICE-90475229
EEmail Address	NOEMAIL

Address	BLK 468 HOUGANG AVE 8 #12-1510
Postcode	530468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM AH TOH
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 22/03/2020 AT ABOUT 1848HRS, I WAS TRAVELLING STRAIGHT ALONG BLK 459 TAMPINES ST 42. SUDDENLY, VEHICLE B CAME OUT OF CARPARK WITHOUT CHECKINGG THE TRAFFIC, CAUSING THE DAMAGES TO THE LEFT HAND PORTION OF MY VEHICLE A AND MY FRONT RIM OF THE LEFT HAND SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SFJ3456A
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22-07-2020, at about 1848, I was travelling straight along tampines st 42, blk 459, suddenly, vehicle B came out of carpark without checking the traffic, causing the damages to the left hand portion of my vehicle A and my front rim of the left hand side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/PII No.:

Noir Autoworks Pte Ltd

Name SJG1110 D

Date 2020-March-24 10:10p.m.

Honda : Odyssey : RC Series : RC1 Two Wheel Drive

Left Front			Right Front		
Actual	Before	Specified Range	Actual	Before	Specified Range
-2°34'		0°45' 0°45'	-0°21'		0°45' 0°45'
		4°35' 6°35'			4°35' 6°35'
0°55'		0°05' 0°05'	-0°01'		0°05' 0°05'
		12°10' 13°40'			12°10' 13°40'
		11°25' 14°25'			11°25' 14°25'

Front			
	Actual	Before	Specified Range
Cross Camber	-2°13'		0°45' 0°45'
Cross Caster			0°45' 0°45'
Total Toe	0°54'		0°10' 0°10'

Left Rear			Right Rear		
Actual	Before	Specified Range	Actual	Before	Specified Range
-2°13'		2°30' -1°00'	-1°40'		2°30' -1°00'
0°47'		0°00' 0°16'	0°06'		0°00' 0°16'

Rear			
	Actual	Before	Specified Range
Total Toe	0°53'		0°00' 0°31'
Thrust Angle	0°20'		