

NATIONAL Assessment Centre Services

(wef 1 Jan 2005)

MA 1200 36277

Date In: 24/1/20 16:58	Job description	Date & Time Completed	Done by
Ref No: MA/INC 2000 4455144	SAS e-filing		
Veh No: GBJ 4799B	E-mail (within 3hrs, A/C 2hrs)		
IP: 23/1/20 17:35	I-Motor Claim Form	MT/1089498-001	25/1/20 10:02
	I-Motor W/O (within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

☒ IP / Reporting Only

IP Insurer:

Preferred Wksp / INC Assign Wksp / OW: (JWG) Tel: Fax:

IP Particulars: Veh No: PA 3737T. INC () / Non-INC ()

Owner / Driver: () Tel: ()

Policy No: () Period: () Cover Type: ()

Confirmed by: () Date: Time: ()

Insured/Driver Liability: () % [Note-Est. Status (WO): N: 0-20%; P: 21-79% P: 80-100%]

Year of Registration: () Warranty: YES () / NO ()

Excess: (\$) Loading: \$1,000 () / \$2,000 ()

General Remarks:

() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (ISC Ref: 6000 6616) Date of completion: Done by:

1) Apply for Transport Allowance () / Courtesy Car ()

2) QC Check / Post Repair Inspection ()

3) Upload Resurvey Photo [Repair Cost > \$3000] ()

Injury:

Date/Time	Actions

MA 2000 3337

Claimants Particulars:

Driver/Owner:

Contact No:

Damaged Portion:

QC Checked by (Engr-In-Charge):

Auditors Comments:

Date:

Time:

Invoice Preparation Checklist	Am (S)	Payable (S)
1) AR: Accident Reporting (\$30);	32.00	
2) DA: Damage Assessment (\$100); INC (\$50)	80.00	
3) TP: Towing Fee \$40/\$45		
4) PT: Follow-Through Survey \$120		
5) PT: Follow-Through Survey (Resurvey) \$30		
For claimant against INC Only (wef 10 Jan 2005)		
6) TR: Re-inspection \$75		
7) NI: Idao DA + SMRT Survey \$160		
8) NTUC Additional Services:-		
ON:		
*N5: Courtesy Car / Tpt Allowance \$5		
*N6: Repair Co-ordination \$10	10.00	
*N7: Post Repair Inspection \$25		
*N8: DV / Collect Excess Coordination \$5		
TP (N11): TP (N11) against INC \$20		
9) N12: Idao Mobile \$0		
Invoice dated	Fee Charged	
Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/03/2020 16:58
Date Of Accident	23/03/2020 17:35
Exact Location Of Accident	JUNC OF BENOI RD & GUL CIRCLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ4799B
Insured/Policyholder	
Name Of Registered Owner	TCK EXPRESS (S) PTE. LTD.
Co Reg No	2XXXXX631M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66846646

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5114821907
Cover Note Number	

Driver

Name of Driver	LOW CHEE KEONG
NRIC No	SXXXX908Z
Date Of Birth	02/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	20/07/1993
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90224625
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 176 BISHAN ST 13 #11-145
Postcode	570176
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JNC5234 (MOTORCYCLE)
Number of vehicles (including own vehicle) involved in the accident	6
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20200324/2080

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA3737T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number FBK1587K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number FBM4666K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number JNC5234
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SJS2628H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOW CHEE KEONG

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? GBJ4799B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

JK EXPRESS (S) PTE

Company ROC 201627631M

10 Senang Crescent

Singapore 418584

Policyholder's Signature

Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20200324/2080

DECLARATION

I/We declare the foregoing particulars are true in every respect.

TGK EXPRESS (S) PTE L

Company ROC 201627631M

10 Senang Crescent

Policyholder's Signature:  416584

Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Date of Accident : 23/3/20 Accident Time: 17:45³⁵ (24-HR-FORMAT)
 Accident Place : Junc of Benoi Rd & Gul Circle.
 Vehicle Reg. No (Car plate No.) : GBJ4799B Vehicle Make/Model: Toyota Hiace.
 Insurance Company : _____ Policy No. _____
 Name of Registered Owner : Company / Individual TCK Express CS) Pte Ltd.
 ID of Registered Owner : Co Reg No: _____ Owner's NRIC No: _____
 : Co Contact No: _____ Owner's Contact No: 66846646.
 DRIVER'S Name : Low Chee Keong DRIVER'S NRIC No: _____
 DRIVER'S Date of Birth : _____ DRIVER'S License Pass Date: _____
 Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
 DRIVER'S Address : _____
 DRIVER'S Contact No / Alt No. : 1) 9022 4625 2) _____
 DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)
 Email Address : _____
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (including Driver): 1 Passenger Name: _____ Gender: M/F
 Was the accident reported to the police? YES \ NO Passenger Name: _____ Gender: M/F
 Was there any video Captured by car camera: YES \ NO Any Injuries: YES \ NO Injured Name: Driver
 Injured Name: _____
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Other Party Driver's Particulars (if any)

Vehicle Reg No: _____	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

Other Party Driver's Particulars (if any)

Vehicle Reg No: _____	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

Jwg



SINGAPORE POLICE FORCE



T/20200324/2080

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200324/2080

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/03/2020 14:22	Vide Report No.: J/20200323/0136	Station Diary No.: 73
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: LOW CHEE KEONG	Address: APT BLK 176 BISHAN STREET 13 #11-145 SINGAPORE 570176
ID Type / ID No.: NRIC NO / S6829908Z	Contact No.: Home/Office: Mobile: 90224625
Nationality: SINGAPORE CITIZEN	Email:
Sex: Male Age: 51 Date of Birth: 02/08/1968	Type of Informant: Driver
Race: Chinese	Language: Institution / School Name:
Occupation: Van driver	Driving Licence Information: Class: 2B,3,4 Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/03/2020 17:35	Type of Location: T-Junction
Location: Along Road 1 BENOI ROAD				
Junction of Benoi Road and Gul Circle				
Weather: Clear	Road Surface: Wet	Road Speed Limit:		
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working	Traffic Volume: Heavy		
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK1587K	Motorcycle	PIAGGIO	VESPA PRIMAVERA 150			0
FBM4666K	Motorcycle	YAMAHA	SNIPER T150	Blue		0
GBJ4799B	Van	TOYOTA	HIACE VAN TURBO 5DR MT	White	Seriously Damaged	0
JNC5234						0



**SINGAPORE
POLICE FORCE**



T/20200324/2080

2 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200324/2080

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA3737T	Van	TOYOTA	HIACE 3.0DX A	White		0
SJS2628H	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO			0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LOW CHEE KEONG	ID No.	S6829908Z
Related Vehicle	GBJ4799B (Van)	Contact No.	90224625
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	23/03/2020	Date Discharge	23/03/2020
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Name	Pek Hong Kau	ID No.	S1323656I
Related Vehicle	PA3737T (Van)	Contact No.	84369560
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 23/03/2020 at about 1735Hrs I was travelling along the Benoi Road and I wanted to turn into Gul Circle. I was travelling on the first lane and subsequently while turning into Gul Circle a van by the car plate of PA3737T that was travelling along Benoi Rd towards Jln Ahmad Ibrahim hit the left side of my vehicle.

Due to the impact my car spun and I hit 4 other vehicles (3 Motorbike (FBM666K, FBK 1587K & JNC5234) and 1 car(SJS2628H)). I am unsure which vehicle was on which lane as I could not see when my van spun.

Subsequently I alighted from the vehicle to make a check and noticed the my passenger door could not be opened I then checked the sliding doors at the side and noticed that they could not be closed and were



**SINGAPORE
POLICE FORCE**



T/20200324/2080

3 of 4

Report No. T/20200324/2080

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

dented.

Subsequently I only exchanged particulars with the driver of PA3737T.

Police and Ambulance were also at scene.

At about 2030hrs I went to Tan Tock Seng Hospital to see a doctor as I felt pain at my neck and back. I was then given 3 days of MC.

I am lodging this report as I was instructed by the police officers at scene.

I wish to state that I have an in car camera however I do not have a Memory card.



**SINGAPORE
POLICE FORCE**



T/20200324/2080

4 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200324/2080

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

SC2 XAVIER LAI GOON THENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 2 HO JIEKANG, IVAN

Contact No.: 65476170

Signature Of Informant:

Date/Time:

24/03/2020 14:22

Classification Of Case:

SN 061

Authentication Stamp

NP168

SIGNATURE

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)**Policy Query**

Policy No.

Date of Accident

Vehicle No.(For Motor)

GBJ4799B

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5114821907	5114821907-000012	TCK EXPRESS (S) PTE. LTD.	201627631M	GFM	Comprehensive	GBJ4799B	GBJ4799B	29/12/2019	28/12/2020

Claim Handling

Accident MT/1089498

Policy No.	5114821907	Vehicle No.	GBJ47998	GST Registration No.	201627631M
Certificate No.	5114821907-000012				
Policyholder Name	TCK EXPRESS (S) PTE. LTD.	Cover Type	Comprehensive	Policyholder NRIC	201627631M
Product Code	FLEET MASTER INSURANCE	Contact No.(Office)		Loading	0
Contact No.(Mobile)	66846646	Special Remark		Contact No.(Home)	
Email Address		TCA	☐ No ☐ Yes	eCode	No *
KFK	☐ No ☐ Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No

▼ Accident Details

Report Date	25/03/2020 09:52	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Cross Junction
Date of Accident	23/03/2020	Time of Accident hh:mm	17:35	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	JUNC OF BENDI RD & GUL CIRCLE				

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess			
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess					
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	Yes	GST Registration Date	20/02/2017
GST Registration No.	201627631M	GST Status Verified	Yes
Modification History	25/03/2020 09:55:57 System changed GST Registered from No to Yes 25/03/2020 09:55:57 System changed GST Registration No. from null to 201627631M 25/03/2020 09:55:57 System changed GST Registration Date from null to 20/02/2017		

▼ Policyholder Mailing Address

Address 1	10 SENANG CRESCENT	Address 2	SINGAPORE 416584	Address 3	
Address 4		Address Type	Singapore address	Post Code	416584
Unit No.	06-20	Related Policy Number	5114821907		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	02/08/1968
Unnamed driver Name	LOW CHEE KEONG	Driver NRIC	SXXXX908Z	Driving Experience	26
Register Date of Driver License	20/07/1993	Driver Age	51	Contact No.(Home)	
Contact No.(Mobile)	90224625	Contact No.(Office)		Address 3	SINGAPORE 570176
Address 1	BLK 176 #11-145	Address 2	BISHAN STREET 13	Post Code	570176
Address 4		Address Type	Singapore address		
Unit No.	11-145				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 OD-MD New

Claim Type *	OD-MD	Insured Name	TCK EXPRESS (S) PTE. LTD.	Insured NRIC	2016	
Contact No.(Mobile)		Contact No. (Home)		Contact No. (Office)	NIL	
Email Address		OI Vehicle Number	GBJ47998	TP Vehicle Number	PA37	
Claim Description	GBJ47998 / PA3737T ON 23 Mar 2020				Name of Preferred Workshop	DWG
Preferred Workshop	90697882	Insured Liability	Fully at Fault	GIA report	Received	
Preferred Workshop (refer below)		Preferred Repair Option		Claim Close Date	25/03/2020 11:08	
Date Registered		Report Taken By	LIEW SHAN HUI	Workshop Repairer		
					Date Received	25/0
					Total Loss but Repaired	
					OD Excess Collected by Workshop	

☒ Print AK letterSave Submit

Attachment

Accident No.	MT/1089498	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	25/03/2020 10:02
Path *			
Choose File	No file chosen	Clear	Category *
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read		Clear	Please Select

Category *

Confidential

Urgency *

Des

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	NRIC/ Driving License	Normal	NRIC/ Driving License 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	SAS	Normal	SAS 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:02	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:01	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 25 Mar 2020 10:00	Photos	Normal	Photos 2020-3-25

Video List

Uploaded By/Date	Folder Date	File Name	Source
		Display in New Window	Scan and uploading

ASSIGNMENT (IDAC)**By CSO- Nature of Accident:**

- 1) Vehicle hit Vehicle: () 2) Vehicle hit ?? ()
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn. Property () b) Road Work Object ()
- (Eg: signboard, barrier, tree etc) c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
- when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information**Remarks to appear in Works Order & Assessment report**

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle InformationVeh No: **G8J 4799B** Yr Regn: **30 Apr 2019**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV / Truck / Trailer orMake & Model: **Toyota Hiace Van Turbo** SDR 2982 c.c.Colour: **White** Transmission Type: Auto / ManualEng/No: _____ Sp. Reading: **46360**C/No: **JTFHT 02 P 700 24 8824**Gen. Cond: Good / Fair / Poor / Burnt orSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: **195 R15C**R: **_____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. **5** mm R/Bal. **5** mmL/Bal. **5** mm L/Bal. **5** mmParallel Import: Yes / No Towed-In: Yes / NoRepair Type: LS / I.B.I. Towing Required: Yes / NoNo of Repair Days: **15** Vehicle in Idac: Yes / NoD.O.I. **25/3/2020** Time: **10.10 am****By Assessor- 2) Comments**

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991386	Fit Number Plate			
1002	991387	Fit Number Plate Base			
1003	991403	Fit Bumper			
1004	991477	Fit Bumper Upper			
1005	991387	Fit Bumper Lower			
1006	991441	Fit Bumper Side			
1007	991443	Fit Bumper Side			
1008	991325	Fit Bumper Bracket			
1009	991433	Fit Bumper Reinforcement			
1010	991466	Fit Bumper Signal Lamp			
1011	995100	Fit LH Bumper Fog Lamp Cover			
1012	991355	Fit RH Bumper Fog Lamp Cover			
1013	995079	Fit LH Bumper Fog Lamp			
1014	995080	Fit RH Bumper Fog Lamp			
1015	991793	Fit Grille			
1016	991328	Fit Grille Emblem			
1017	990347	Fit Grille Sticker			
1018	991799	Fit Grille Chrome Moulding			
1019	991891	Fit Panel			
1020	991874	Fit Lower Panel			
1021	991128	Fit Panel Emblem			
1022	990247	Fit Panel Sticker			
1023	991891	Fit Panel Garnish			
1024	991222	Fit Apron Panel			
1025	991527	Fit Corner Panel			
1026	991532	Fit Corner Panel Signal Lamp			
1027	995245	Fit Signal Lamp LH			
1028	995246	Fit Signal Lamp RH			
1029	995153	Fit LH Headlamp Assy			
1030	991821	Fit RH Headlamp Assy			
1031	995088	Fit LH Side Lamp			
1032	995089	Fit RH Side Lamp			
1033	992149	Fit Wiper Panel			
1034	995043	Fit Wiper Nozzle			
1035	992140	Fit Wiper Arm			
1036	992142	Fit Wiper Blade			
1037	992145	Fit Wiper Link			
1038	992148	Fit Wiper Motor			
1039	995045	Wiper Panel Garnish			
1040	992093	Fit Windscreen			
1041	992097	Fit Windscreen Rubber			
1042	992098	Fit Windscreen Sealant			
1043	992114	Fit Windscreen Outer Pillar			
1044	992113	Fit Windscreen Inner Pillar			
1045	991019	FRP Bracket			
1046	991020	FRP Unit			
1047	991958	Fit Side Mirror (Big)			
1048	991959	Fit Side Mirror (Small)			
1049	991962	Fit Side Mirror (Round)			
1050	995015	Fit Wing Mirror Stay			
1051	992013	Fit Support Panel			
1052	990248	Bonnet			
1053	990287	Bonnet Lock			
1054	990273	Bonnet Hinge			
1055	990305	Bonnet Rubber			
1056	990119	Air Con Condenser			
1057	990123	Air Con Fan Assy			
1058	990149	Air Con Liquid Pipe			
1059	995066	Air Con Receiver Drier			
1060	995071	Radiator			
1061	992738	Radiator Cowlings			
1062	992742	Radiator Fan Assy			
1063	992758	Radiator Hose Top			
1064	992741	Radiator Expansion Tank			
1065	992596	Oil Cooler			
1066	991131	Power Steering Cooler Pipe			
1067	990131	Air Duct			
1068	990070	Air Cleaner Assy			
1069	990119	Battery			
1070	990121	Battery Bracket			

Vehicle No: GBJ 4799B

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Wheel Cap	CRA		
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre	DD		
1105	995071	Frt RH Fender	607		
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door	BUC		
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar LH	BUC		
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker	NEC		
		Frt Door Rear Pillar Inner Trim			

Condition (1) New (2) Replaced (3) Missing (4) Damaged (5) Scratched (6) Bent (7) Discoloured (8) Discoloured (9) Scratched (10) Scratched (11) Necessary (12) Missing (13) Too (14) Unconfirmed (15) Not Working

VAN / LORRY (Rear)

ACTION (AC)
(1) Replace (✓) (2) Repair (X) (3) Check (E)
(4) Not Consistent (BC)

Ang 1985

283

Vehicle No:

GBJ4799B

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD		
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Stop Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	BC		
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	BC		
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem	NEC		
1183	994643	Tailgate Outer Handle	NEC		
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass	BR		
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC		
1196	994607	Tailgate Glass Sealant	NEC		
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock	DM		
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel	BT R		
1204	995065	Spare Tyre	BT		
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel RH & LH	BC		
2071	992866	Rear Body Panel Inner LH	BC		
2072	995329	Sliding Door LH	BC		
2073	995328	Sliding Door RH LH Inner Board	BR		
2074	994295	Sliding Door Handle LH			
2075	994300	Sliding Door Lock LH	BT		
2076	994313	Sliding Door Rubber LH	TN		
2077	994291	Sliding Door Bottom Roller LH	BT		
2078	994317	Sliding Door Top Roller LH	BT		
2079	994306	Sliding Door Rail LH	BT		
2080	994315	Sliding Door Stepboard	BT		
2081	994316	Sliding Door Stepboard Garnish	BT		
1224	993621	Rear LH Mudflap Wheel Cap	CUT		
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre	TN		
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		Roof Panel	BC		
		" Lining	AS		
		Rear Body Panel (LH Inner Board)	CRA		
		LH Rocker Panel	BT		
		Rear LH Wheel Housing (Inner Board)	CRA		
		Sliding Door LH Hinge			
		Rear Floor Board	CRA		
		Sliding Door LH Inner Handle	CRA		
		" " Edge Protector	BT		
		Rear LH Wheel Housing	BC		
		Rear Body Panel (RH Inner Board)			
		Fuel Pipe	BT		
		Rear LH Leaf Spring Bracket			

No of Items:

Assessor:

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ALLIUM LAC

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

3 1/2 3

Vehicle No: GBJ 4199 B

Undercarriage				CON	AC	Qty
NAC	INC	Item				
1372	995163	Frt LH Shock Absorber			?	
1373	991944	Frt LH Shock Absorber Mounting			?	
1374	990632	Frt LH Coil Spring				
1375	995198	Frt LH Knuckle Arm			?	
1376	995199	Frt LH Knuckle Arm Bearing			?	
1377	995178	Frt LH Lower Arm			?	
1378	995169	Frt LH Upper Arm				
1379	995183	Frt LH Tie Rod				
1380	995143	Frt LH Drive Shaft				
1381	990661	Frt LH Control Arm				
1382	992062	Frt LH Trailing Arm				
1383	991848	Frt LH Leaf Spring				
1384	991293	Frt LH Brake Disc Rotor				
1385	991281	Frt LH Brake Caliper				
1386	991292	Frt LH Brake Pipe				
1387	991287	Frt LH Brake Hose				
1388	991295	Frt LH Brake Sensor Wire				
1389	991989	Frt Stay Bar Bracket				
1390	994455	Steering Rack & Pinion				
1391	994435	Steering Cross Member				
1392	994519	Frt Sub Frame				
1393	992003	Frt Sub Frame Mounting				
1394	991217	Frt Anti Roll Bar				
1395	991219	Frt Anti Roll Bar Linkage				
1396	990887	Engine Block				
1397	990890	Engine Block Gasket				
1398	990972	Engine Oil Sump				
1399	990960	Engine Oil				
1400	992224	Gear Box Assy				
1401	992229	Gear Box Gasket				
1402	992241	Gear Box Oil Sump				
1403	992257	Gear Oil				
1210	990534	Centre Exhaust Pipe Assy				
1211	990532	Centre Exhaust Mounting				
1404	991134	Floor Panel				
1405	993719	Rear LH Shock Absorber			?	
1406	993723	Rear LH Shock Absorber Mounting				
1407	993170	Rear LH Coil Spring			?	
1408	993550	Rear LH Knuckle Arm			?	
1409	993551	Rear LH Knuckle Arm Bearing			?	
1410	993597	Rear LH Lower Arm				
1411	993884	Rear LH Upper Arm				
1412	995161	Rear LH Drive Shaft				
1413	995216	Rear LH Control Arm				
1414	993881	Rear LH Trailing Arm				
1415	993573	Rear LH Leaf Spring				
1416	992941	Rear LH Brake Disc Rotor				
1417	992937	Rear LH Brake Caliper Assy				
1418	990434	Rear LH Brake Pipe				
1419	992946	Rear LH Brake Hose				
1420	993819	Rear Sub Frame				
1421	993820	Rear Sub Frame Mounting				
1422	992813	Rear Anti Roll Bar				
1423	990168	Rear Anti Roll Bar Linkage				
1424	990202	Axle Beam			?	
1425	990170	Rear Axle Panhard Rod				
1426	990810	Differential Assy				
1427	992706	Propeller Shaft				

[illegible]

Assessor: _____

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	631M
Vehicle Details	
Vehicle No.:	GBJ4799B
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KD2851505
Chassis No.:	JTFHT02P700248824
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,813.00
COE Rebate Amount:	\$21,643.00
Total Rebate Amount:	\$21,643.00

The information contained herein is correct as at 24 Mar 2020

OK

9 - 1.2mths

6,500/yr

M.V. \$59,000
\$21,643

Net value \$37,357



Toyota Hiace Price Range Depreciation 2019 Vehicle Type

Advanced Search

Home » Used Cars » KSL Automotive Pte Ltd » Toyota Hiace 3.0M

Toyota Hiace 3.0M

Overview Financial Accessories Similar Research Photos Map



Price	\$67,800	Lifespan	04-Dec-2039
Depreciation ⓘ	\$6,990 /yr View models with similar depre	Reg Date	05-Dec-2019 (9yrs 8mths 10days COE left)
Mileage	N.A.	Manufactured ⓘ	2019
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$12,245 as of today (change)	OMV ⓘ	\$28,138
COE ⓘ	\$12,618	ARF ⓘ	\$1,407
Engine Cap	2,982 cc	No. of Owners ⓘ	2
Curb Weight ⓘ	1,700 kg		
Type of Vehicle	Van		

Features

1 Of The Most Reliable Commercial Vehicle In The Market Now! Provide You With Quality Performance, Definite Asset To Your Business. View specs of the Toyota Hiace

Accessories

CD Player, Reverse Camera, Reverse Sensor, Front Recording Camera And Many More Free Gift Will Be Given!

Description

\$0 Drive Away! No Gimmick! Toyota Hiace From Borneo Motors. Cheapest In The Market! Ready Stock! 3 Years Warranty And 8 Free Servicing By Borneo Motors. Euro 6 Engine, Low Fuel Consumption, Most Reliable Model For Heavy Duty, Drive Off With Only \$2500. Included Insurance And First Month Installment. Still Waiting For? Call Our Friendly Sales Team Now! Definitely A Different Expert.

Category

Almost New Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Price Chart

Summary



Click on the point to view the vehicle

Shortlist Compare Add note
Report Error More Actions

Seller Information

KSL Automotive Pte Ltd

37 vehicles for sale. 38 sold in past 3 mths

2A Kian Teck Avenue Level 3
Tel: 62660777
Search cars nearby

Zhong Yuan 92332542
Lee 97961166
Kevin Lim 81825505

CREDIT
COUNSELLING
SINGAPORE

Cre

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal COE Toyota Wish 1.8A



2,98% P.A, 0 admin, 2,8k down,
monthly \$688, 2 Years Warranty
Engine & Gearbox
GV Credit StarAd

KA-HUP

HOTLINE: 6741 9997

[View our cars](#)

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

18 vehicles

Toyota Hiace 3.0m

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace 3.0m		Any	Any	2019	Any	Any	Any	Available
	Toyota Hiace 3.0M		\$67,800	\$6,990 /yr	05-Dec-2019	2,982 cc	-	Van	Available
Fuel Type: Diesel \$0 Drive Away! No Gimmick! Toyota Hiace From Borneo Motors. Cheapest In The Market! Ready Stock! 3 Years Warranty And 8 Free Servicing By Borneo Motors. Euro 6 Engine, Low Fuel Consumption, Most Reliable Model For Heavy Duty, Drive Off With Only \$2500. Inc... KSL Automotive Pte Ltd Posted: 24-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota Hiace 3.0M		\$63,000	\$6,670 /yr	30-Aug-2019	2,982 cc	2,100 km	Van	Available
Fuel Type: Diesel You Sit Inside You Still Can Smell The New Car Smell! 3.0M With 5 Doors Is Definitely Helpful With Your Goods Delivery Since You Can Open The Van From Both Sides! Posted: 23-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota Hiace 3.0M		\$61,777	\$6,560 /yr	21-Aug-2019	2,982 cc	-	Van	Available
Fuel Type: Diesel Newly Register Toyota Hiace Borneo Motors Unit, Come With 3 Years Or 100,000Km Warranty And 8 Time Free Servicing By Borneo Motors! Loan With Low Interest Rate, Trade In Welcome, Call Now To Find Out More! Posted: 23-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota Hiace 3.0M		\$64,800	\$6,680 /yr	05-Dec-2019	2,982 cc	15 km	Van	Available
Fuel Type: Diesel New Agent Unit! No Admin Fee. GST/ARF/COE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100k Km Warranty! With Free 8 x Times Servicing! Doorstep Discussion Welcome. Trade In Available To Offset Your Previous Vehicle! What You Need, We Can He... Car (S) Pte Ltd Posted: 21-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota Hiace (For Lease) \$1,400/mth TOYOTA HIACE FOR LEASE (BRAND NEW READY STOCK) More info about this vehicle								
	Toyota Hiace 3.0M		\$62,800	\$6,780 /yr	26-Jun-2019	2,982 cc	-	Van	Available
Fuel Type: Diesel Offer Price And Package Till In Of The Month! Cheapest In The Market! GST Inclusive! No Hidden Cost! Ready Stocks! Immediate Registration! New Euro 6 Facelift! 3 Years Warranty Or 100000km! 8 x Free Servicing! Loan Up To 100% Available! Attractive Loan Pack... Net Link Partners Pte Ltd Posted: 21-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota Hiace 3.0M		\$66,800	\$7,140 /yr	02-Aug-2019	2,982 cc	-	Van	Available
Fuel Type: Diesel Free 8 Times Servicing With Agent. 3 Years/100000km Warranty. Depreciation Less Than \$7k. High/Full Loan Available. Call Us Now! Ezy-1 Pte Ltd Posted: 20-Mar-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
Compare	Tc		\$64,800	\$6,670 /yr	11-Dec-2019	2,982 cc	15 km	Van	Available
	Fuel T								



Toyota Hiace 3.0M

Fuel Type: Diesel

\$66800! Agent Unit, 5 Doors, Register As First Owner, All In Price, Call Us Now To Make A Booking Before The Price Increase.

SG Motor Link Pte Ltd

Posted: 19-Feb-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace

PREMIUM AD



Toyota Hiace 3.0M

\$67,800

\$7,250 /yr

29-Jul-2019

2,982 cc

8 km

Van

Available

Fuel Type: Diesel

Latest Euro 6 Toyota Hiace Van Manual 5 Doors From Borneo Motors. 3 Years Or 100000km Warranty. Free 8 Times Servicing Packages. Number 1 Best Selling Cargo Van, 100% Loan, High Trade In For Old. This Price Inclusive GST. Immediate Delivery.

PREMIUM AD

Posted: 13-Feb-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 3.0M

\$59,800

\$6,660 /yr

15-Mar-2019

2,982 cc

18,404 km

Van

Available

Fuel Type: Diesel

New Arrival! Cheapest In Town! Super Low Mileage Done At 18000km Only! 1st Owner! (Borneo Motors Unit!) Very Mint Condition! Interior & Exterior Looks Like New! Driver's Seat Plastic Still Intact! Drives Like A New Vehicle! Durable Euro 5 Engine! Under 3yrs/10000...

Posted: 04-Feb-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 3.0M

\$67,800

\$7,290 /yr

09-Jul-2019

2,982 cc

8 km

Van

Available

Fuel Type: Diesel

Latest Euro 6 Toyota Hiace Van Manual 5 Doors From Borneo Motors. 3 Years Or 100000km Warranty. Free 8 Times Servicing Packages. Number 1 Best Selling Cargo Van, 100% Loan, High Trade In For Old. This Price Inclusive GST. Immediate Delivery.

PREMIUM AD

Posted: 24-Jan-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Hiace 3.0m, Toyota Hiace 3.0m Singapore, used Toyota Hiace 3.0m Singapore, used Toyota Hiace 3.0m, used vehicles Singapore or even buy used Toyota Hiace 3.0m Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2020 sgCarMart. All rights reserved.

Compare

Claim Handling

Task Transfer Exit

Accident MT/1089498

LOGS SAL SUB

Policy No.	5114821907	Vehicle No.	GBJ47998	GST Registration No.	201627631M
Certificate No.	5114821907-000012				
Policyholder Name	TCK EXPRESS (S) PTE. LTD.			Policyholder NRIC	201627631M
Product Code	FLEET MASTER INSURANCE	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	66846646	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	25/03/2020 09:52	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Cross Junction
Date of Accident	23/03/2020	Time of Accident hh:mm	17:35	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	JUNC OF BENOI RD & GUL CIRCLE				

Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess			
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess					
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		

Benefits

GST Registered Information

GST Registered	Yes	GST Registration Date	20/02/2017
GST Registration No.	201627631M	GST Status Verified	Yes
Modification History	25/03/2020 09:55:57 System changed GST Registered from No to Yes 25/03/2020 09:55:57 System changed GST Registration No. from null to 201627631M 25/03/2020 09:55:57 System changed GST Registration Date from null to 20/02/2017		

Policyholder Mailing Address

Address 1	10 SENANG CRESCENT	Address 2	SINGAPORE 416584	Address 3	
Address 4		Address Type	Singapore address	Post Code	416584
Unit No.	06-20	Related Policy Number	5114821907		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver	Driver DOB	02/08/1968
Unnamed driver Name	LOW CHEE KEONG	Driver NRIC	SXXXX9082	Driving Experience	26
Register Date of Driver License	20/07/1993	Driver Age	51	Contact No.(Home)	
Contact No.(Mobile)	90224625	Contact No.(Office)		Address 3	SINGAPORE 570176
Address 1	BLK 176 #11-145	Address 2	BISHAN STREET 13	Post Code	570176
Address 4		Address Type	Singapore address		
Unit No.	11-145				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
Modification History			

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimie Bin Mantau

LOGS SAL SUB

Claim Type	OD-MD	Insured Name	TCK EXPRESS (S) PTE. LTD.	Insured NRIC	201627631M
Contact No.(Mobile)		Contact No. (Home)		Contact No. (Office)	NIL
Email Address		OI Vehicle Number	GBJ47998	TP Vehicle Number	PA3737T
Claim Description	GBJ47998 / PA3737T ON 23 Mar 2020			Name of Preferred Workshop	JWG INTERNATIONAL PTE LTD
Preferred Workshop 90697883	Preferred Repair Option	Preferred Workshop (refer below)	Insured Liability report	Fully at Received	
Date Registered	25/03/2020 11:09	Claim Close Date		Date Received	25/03/2020 10:02
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	HIACE VAN	Engine Capacity	1.1
Date of Registration	30/04/2019	Classis No.	JTFHT02P700248824		

Towing Required * ☒ Yes ☐ NoVehicle in IDAC * ☒ Yes ☐ NoParallel Import * ☐ Yes ☒ No

Type of Tender * Own Damage

Assessor Name * SIMON

Survey Current Status

IDAC/Workshop Name NATIONAL ASSESSMENT CENTR

IDAC/Workshop Location 51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss * ☐ Yes ☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK:NO OF REPAIR DAYS:15 DAYS.1X FRT LH WHEEL CAP - REPLACE.1X FRT LH DOOR REAR PILLAR - REPLACE.1X STICKER REPLACE.1X FRT DOOR REAR PILLAR INNER TRIM - UNCONFIRM.1X REAR END PANEL - REPLACE.1X TAIL GATE RUBBER - UNCONFIRM.1X SLIDING DOOR HANDLE LH - UNCONFIRM.1X SLIDING DOOR LOCK LH - REPLACE.1X SLIDING DOOR RUBBER LH - REPLACE.1X SLIDING DOOR TOP ROLLER LH - REPLACE.1X SLIDING DOOR STEPBOARD - REPLACE.1X REAR LH WHEEL CAP - REPLACE.1X REAR LH WHEEL RIM - UNCONFIRM.1X REAR BODY PANEL LH INNER BOARD - REPLACE.1X REAR FLOOR BOARD - REPLACE.1X REAR LH WHEEL HOUSING INNER SHIELD - REPLACE.1X SLIDING DOOR LH EDGE PROTECTOR - REPLACE.1X REAR LH WHEEL HOUSING - REPLACE.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
AUTO COOLER PIPE						
AUTO CRUISE MOTOR	1	16000101	BUMPER (FRONT)	1	Replace	X
AUTO TRANSMISSION	2	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
AXLE	3	145023	BODY PANEL INNER TRIM	1	Unconfirm	X
BACK REST (M/C)	4	264004	FUEL PIPE	1	Replace	X
BACK SEAT	5	16005101	BUMPER RETAINER (FRONT LEFT)	1	Unconfirm	X
BALANCER	6	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
BATTERY	7	21300101	CORNER PANEL (FRONT LEFT)	1	Replace	X
BEADING (M/C)	8	23300202	DOOR (FRONT RIGHT)	1	Replace	X
BELT COVER (M/C)	9	23306102	DOOR RUBBER (FRONT RIGHT)	1	Unconfirm	X
BELT TENSIONER	10	32200302	NUMBER PLATE BRACKET (REAR)	1	Unconfirm	X
BODY	11	16000102	BUMPER (REAR)	1	Replace	X
BODY (M/C)	12	35300101	REVERSE SENSOR (LEFT)	1	Unconfirm	X
BOLT CAP (M/C)	13	35300102	REVERSE SENSOR (RIGHT)	1	Unconfirm	X
BOLT HEAD COVER (M/C)	14	42000101	TAIL LAMP (LEFT)	1	Unconfirm	X
BONNET	15	42000102	TAIL LAMP (RIGHT)	1	Replace	X
BOOT	16	419001	TAIL GATE	1	Replace	X
BOX (M/C)	17	41900501	TAIL GATE EMBLEM (RIGHT)	1	Replace	X
BOX BRACKET (M/C)	18	419035	TAIL GATE STICKER	2	Replace	X
BOX CARRIER (M/C)	19	419011	TAIL GATE GLASS	1	Replace	X
BOX DOOR	20	419013	TAIL GATE GLASS MOULDING	1	Replace	X
BOX STICKER (M/C)	21	419015	TAIL GATE GLASS SEALANT	1	Replace	X
BRACE PANEL	22	419023	TAIL GATE LOCK	1	Replace	X
BRAKE	23	419022	TAIL GATE INNER TRIM	1	Unconfirm	X
BRAKE - ABS	24	256005	FLOOR PANEL	1	Repair	X
BRAKE (M/C)	25	390001	SPARE TYRE	1	Unconfirm	X
BUMPER	26	390003	SPARE TYRE BRACKET	1	Replace	X
CABIN	27	14501301	BODY PANEL (LEFT)	1	Replace	X
CAMBER	28	14501302	BODY PANEL (RIGHT)	1	Replace	X
CAMSHAFT	29	14500801	BODY INNER PANEL (LEFT)	1	Replace	X
CAR AUDIO SYSTEM	30	38900101	SLIDING DOOR (LEFT)	1	Replace	X
CAR JACK	31	38900102	SLIDING DOOR (RIGHT)	1	Replace	X
CARBURATOR	32	389007	SLIDING DOOR INNER BOARD	2	Replace	X
CARGO	33	38900201	SLIDING DOOR BOTTOM ROLLER (LEFT)	1	Replace	X
CARRIAGE	34	38901601	SLIDING DOOR RAIL (LEFT)	1	Replace	X
CARRIER MOUNTING	35	389018	SLIDING DOOR STEPBOARD GARNISH	1	Replace	X
CASTOR	36	43600103	TYRE (REAR LEFT)	1	Replace	X
CATALYTIC CONVERTOR	37	264006	FUEL TANK	1	Unconfirm	X
CD CHANGER	38	264009	FUEL TANK BRACKET	1	Unconfirm	X
CD PLAYER	39	356009	ROOF PANEL	1	Replace	X
CDI UNIT (M/C)	40	356006	ROOF LINING	1	Replace	X
CENTRE BOTTOM	41	35500701	ROCKER PANEL (LEFT)	1	Replace	X
CENTRE BRACKET	42	389008	SLIDING DOOR INNER HANDLE	1	Replace	X
CENTRE CONSOLE	43	389006	SLIDING DOOR HINGES	2	Unconfirm	X
CENTRE COWLING (M/C)	44	30300203	LEAF SPRING BRACKET (REAR LEFT)	1	Unconfirm	X
CENTRE CROSS MEMBER	45	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Unconfirm	X
CENTRE EXHAUST	46	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	X
CENTRE FARING (M/C)	47	36600103	SHOCK ABSORBER (REAR LEFT)	1	Unconfirm	X
CENTRE FOOTREST COVER (M/C)	48	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	X
CENTRE GARNISH	49	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	X
CENTRE GLASS FRAME	50	30500101	LOWER ARM (FRONT LEFT)	1	Unconfirm	X
CENTRE GRILLE	51	30300103	LEAF SPRING (REAR LEFT)	1	Unconfirm	X
CENTRE JAW (M/C)	52	30000103	KNUCKLE ARM (REAR LEFT)	1	Unconfirm	X
CENTRE LOWER MEMBER	53	30000203	KNUCKLE ARM BEARING (REAR LEFT)	1	Unconfirm	X
CENTRE OUTER PILLAR	54	13700102	AXLE BEAM (REAR)	1	Unconfirm	X
CENTRE PILAR						
CENTRE SEAT						
CENTRE SHAFT						
CENTRE SILENCER						
CENTRE STAND (M/C)						
CHAIN (M/C)						
CHAMBER (M/C)						
CHASSIS						
CHROME COVER (M/C)						
CIGARETTE LIGHTER						
CLEANER						
CLUTCH						
CLUTCH (M/C)						



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: GBI 4799B Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: IWG

Collection Date: 30032000 Time: 1404 with Keys: Yes / No

Tow Truck No: 4990J Tow Man: LAI JIAN WEI NRIC: 88000090

Signature: STY

For office use

Attended by: _____

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Zuraimee Bin Mantau <zuraimee.mantau@income.com.sg>
Sent: Monday, 30 March 2020 8:59 AM
To: JWG CLAIMS
Cc: LKK Paya Ubi
Subject: Vehicle GBJ4799B, OD Claim No: MT/1089498-001, DOA: 23/03/2020
Importance: High

Dear JWG International

OD Excess 600 applies.

Vehicle is currently at NAC Paya Ubi.

We award the repair at the agreed global sum amount with no deduction and no further supplementary.

Please arrange to take away the vehicle and update the vehicle company's rep, Mr Joe Chong at 91832139 on the repair status.

Please arrange for **the survey before repair via email directly** to our MTSurvey@income.com.sg.

NOTE: For **ALL Survey/Re-Survey** matters, please **email directly** to our MTSurvey@income.com.sg 1 day advance before 4.30pm.

Please forward the invoice and DV within 7 working days to us once repairs has been done.

Thank you

Zuraimee Bin Mantau
Senior Executive
Operations, Motor & Personal Lines
T +65 6430 7891
www.income.com.sg

 **income**
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.