



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/03/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	✓ 530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$324.00	✓ 262
Total Spray Painting & Panel Beating	\$324.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	✓ CRA
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	✓ CRA
6013482	Body	124-2-2-009-012	O/S FRP REAR LAMP	1.00	\$975.00	100.00	\$0.00	Repair	X SVC
Total					\$2,484.10		\$1,358.19		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

~~L/S~~

After paint photo

Sun Pin (CHK)

20/03/2020

TP without prejudice.

P = \$ 1,358.19

L = \$ 792.00

\$ 2,150.19

P/P
2 days

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63686592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/03/2020
User ID : GohKK2

Section A - Accident Details	
Registration Number	SG6128P
Case Reference Number	BU5/03/20/7017
Registration Date	5/4/2019
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95 EU6
Name of Driver	Nga Yook Lan
Type of Accident	Side Swipe
Accident Date and Time	18/3/2020 6:24 PM
Accident Reported Date and Time	19/3/2020 9:28 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6128P-RIGHT REAR PORTION F29255P (TP) INSURED WITH
Prepared Date and Time	19/3/2020 2:06 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	
Section B - Summary of Repair Estimates	
Summary of Repair Estimates	
Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00
Total Spray Cost	\$324.00
Total Spare Part Cost	\$1,358.19
Total Other Cost	\$0.00
TOTAL COST	\$2,477.19
Lump Sum Total	\$0.00
Number of Repair Days	3.0
Prepared / Adjusted By	Kok Khoon Goh
ARC / Surveyor Sign Off Date	19/03/2020 2:14 PM
Signature	
Remarks	
Section C - Quotation and Accident Invoice Details	
Quotation Number	Invoice Number
Quotation Date	Invoice Date
Invoice Amount	Prepared Date