



Your Ref: S8M00TZ5

Date: 27th April 2020

Our Ref: CS3/ASM18015964/Gqf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Johnny Yong

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLD 932Y

INSURED VEHICLE: SLB 62T

ACCIDENT DATE: 31/08/2018

We thank you for your instruction on 25/03/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLD 932Y from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SLD 932Y, SLB 62T and SJL 5330H.
- c) Police Report of Vehicles SLB 62T
- d) Final Repair Bill of SLD 932Y from M/s Twincar Automotive Pte Ltd.
- e) Colour damaged vehicle photographs of SLD 932Y.

Pre-Repair Inspection Date : 31/08/2018 at M/s N-51 Automotive PL, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLD 932Y
Make & Model	: Toyota Corolla Altis 1.6 CVT
Year of Registration	: 2016
Chassis Number	: MR053REH104549329
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.