

ASS. REC. BY:

REF:

CS3/AIG2000-1489/ESD3

Special Instructions:

Singer: Steve

ASSIGNMENT (Office)

From (Person): Teo Ericweihong of _____
Estimated Cost: _____

of ALG

Date/Time: 25/3/2020 @ 11:44am

Estimated Cost:

Bill to:

OD-TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6793K

Insured:

S12 4369E

at Workshop m/s

B's Performance

Tek:

6397 5920

of

7 Soon lee street # 01-38

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record

D.O.A. 21/03/2020

CA / REV / REP. / REV 24 HRS

1wpl

Wan lee

H.O.D. Endorsement:

Date/Time: 11:53am 23/3/2020

Person Contacted:

19th

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SLJ 6493K - NBA/INC 180,000,000 / y	DWA: 16/05/2018
	SJL 4369F - NA/MS 412014186/01	DWA: 11/7/2012

Steve

AIG

CS 3/AIG 20004489/ESD3

1

Veh No: 020 07/5K Yr Regn: 21/12/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota ARIS C.C. 1598

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 76512 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROSSREH104560699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/552R16

R: cl

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 21/7/20 D.O.I. 25/3/20

Survey held at R's Performance

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Des. of Damages : Frt / Rear / (O/S) / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Prelim. Report

☒: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2/

Add Fee: ☐ : Site Insp (\$☐ Interview (\$)

Tech. Invs (\$

☐ : Weekend (\$)

Report Format : *PRS*

Lump Sum / L.B.J. (\$)

Survey Fee:



Transportation:

Photos

3) Others

TOTAL

FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V...

From: Teo, Ericweihong
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Hor, Yinrul, Abu Kassim, Noor Mariesa, Subramaniam, Divyashni
Sent: 3/25/2020 11:44:02 AM
Attachments:  20200324173442785.pdf  20200324173442785.pdf

Hi LKK,

Kindly assist on attached PRI.

Thank you.

Regards,

Eric Teo Wei Hong

AIG

Claim Adjuster II,

Singapore— Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1002213

Ericweihong.Teo@aig.com | www.aig.com

From: Teo, Ericweihong

Sent: Wednesday, March 25, 2020 11:42 AM

To: Janice Kee <janice.kee@ksteoptr.com>

Cc: bsperformancepteltd@gmail.com; Charlotte Choy <charlotte.choy@ksteoptr.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ4369E AND SLJ6793K ON 21/03/2020

Without Prejudice

Your Reference: TKS/B501-ACC-SLJ6793K.20/cc
Our Reference : SJZ4369E

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.
Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our appointed surveyor for the pre-repair inspection.

Thank you.

Regards,

Eric Teo Wei Hong

AIG

Claim Adjuster II,

Singapore— Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1002213

Ericweihong.Teo@aig.com | www.aig.com

From: Janice Kee <janice.kee@ksteoptr.com>

Sent: Wednesday, March 25, 2020 11:31 AM

To: Teo, Ericweihong <Ericweihong.Teo@aig.com>

Cc: bsperformancepteltd@gmail.com; Charlotte Choy <charlotte.choy@ksteoptr.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ4369E AND SLJ6793K ON 21/03/2020

This message is from an external sender; be cautious with links and attachments.

Dear Sir

We refer to your email of even date.

Please be informed that our client is not agreeable to your appointed motor surveyor from the list you provided as a single joint expert.

Our client will appointed Mr Alan Cheong from CL Appraiser Pte Ltd as Single Joint Expert.

Thank you.

Regards,

Janice Kee

c/o Teo Keng Siang LLC

111 North Bridge Road,

#29-07/08 Peninsula Plaza,

Singapore 179098

Tel: 6333 4222 Fax: 6333 5676

On Wed, Mar 25, 2020 at 11:03 AM Teo, Ericweihong <Ericweihong.Teo@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-03-31 23:03 EDT to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

From: Ericweihong.Teo@aig.com
To: janice.kee@ksteoptr.com
Cc: bsperformancepteltd@gmail.com ,charlotte.choy@ksteoptr.com ,Kok-Chong.Lim@aig.com ,NoorMariesa.AbuKassim@aig.com ,Yinrul.Hor@aig.com ,Divyashni.Subramaniam@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJZ4369E AND SLJ6793K ON 21/03/2020
Date: Wed, 25 Mar 2020 03:03:48 +0000
Without Prejudice

Your Reference: TKS/B501-ACC-SLJ6793K.20/cc
Our Reference : SJZ4369E

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Eric Teo Wei Hong

AIG

Claim Adjuster II,

Singapore— Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1002213

Ericweihong.Teo@aig.com | www.aig.com

From: Janice Kee <janice.kee@ksteoptr.com>

Sent: Wednesday, March 25, 2020 8:33 AM

To: Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>

Cc: bsperformancepteltd@gmail.com; Charlotte Choy <charlotte.choy@ksteoptr.com>

Subject: [EXTERNAL] Pre Repair Survey for SLJ 6793 K (Your Ref: SLZ 4369 E Our Ref: TKS/B501-ACC-SLJ6793K.20/cc)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you

Regards,

Janice Kee

c/o Teo Keng Siang LLC

111 North Bridge Road,

#29-07/08 Peninsula Plaza,

Singapore 179098

Tel: 6333 4222 Fax: 6333 5676

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	881Z
Vehicle Details	
Vehicle No.:	SLJ6793K
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY340968
Chassis No.:	MR053REH104560699
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	21 Dec 2016
First Registration Date:	21 Dec 2016
Transfer Count:	1
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2026
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$32,324.00
Total Rebate Amount:	\$45,810.00

The information contained herein is correct as at 25 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/03/2020 15:01
Date Of Accident	21/03/2020 10:00
Exact Location Of Accident	RIVER VALLEY ROAD / EU TONG SENG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ6793K
Insured/Policyholder	
Name Of Registered Owner	DURAI RAJ MURUGAPPA
NRIC No	SXXXX881Z
Email Address	MURUGAPPA2000@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98503474
Alternative Phone No	OFFICE-98503474

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80477215QMX
Cover Note Number	

Driver

Name of Driver	DURAI RAJ MURUGAPPA
NRIC No	SXXXX881Z
Date Of Birth	03/07/1976
Occupation	INDOOR
Date Of Driving Pass	01/11/2010
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98503474
Fax Number	
Contact Number	OFFICE-98503474
EMail Address	MURUGAPPA2000@YAHOO.COM

Address	BLK 646 JURONG WEST STREET 61 #02-144
Postcode	640646
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ4369E
Vehicle Make/Model/Colour	BMW 740 AUTO
Details Of Properties	LEFT SIDE PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	BRANDS HYRONIMUS ADRIANUS WICHELMUS MARIA
NRIC/Passport Number	
Contact Number	87823208
Address	NA
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting on the 2nd lane (River Valley Road) at the traffic junction and my vehicle was in my lane and stationary. Few cars were in front me. Suddenly a vehicle 'B' from the Rear 1st lane went into lane and hit into my Right wing mirror causing damages. Some parts fell on the road. My Right front fender inner shield were also damaged.

We exchange particulars and two vehicles involved and went to do private 'Sketch plans' but finally agreed on Insurance claim.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Q389/R 364-01 Rev 001/01

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(01) Bent (02) Dental (03) Presented (04) Clocked (05) Cut (06) Scratched
(07) Deformed (08) Stalled (09) Docked (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfined (15) Not Working

MOTOR CAR (RED)

(1) Replace ($\sqrt{\quad}$) (2) Region (S) (3) Check (\checkmark)
(4) Not Consistent (44C)

Vehicle No:

SLJ 6793K

Rights Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Fit RH Door	SCR	R	
1317	991654	Fit RH Door Protector			
1318	991601	Fit RH Door Hinge			
1319	991685	Fit RH Door Wing Mirror	BR	✓	
1320	991583	Fit RH Door Garnish			
1321	991639	Fit RH Door Glass Outer Moulding			
1322	991588	Fit RH Door Glass Inner Moulding			
1323	991584	Fit RH Door Glass			
1324	991595	Fit RH Door Glass Regulator			
1325	991596	Fit RH Door Glass Regulator Motor			
1326	991662	Fit RH Door Rubber			
1327	991636	Fit RH Door Outer Handle			
1328	991607	Fit RH Door Inner Handle			
1329	991625	Fit RH Door Lock w/Key			
1330	991624	Fit RH Door Lock			
1331	991562	Fit RH Door Central Lock			
1332	991675	Fit RH Door Switch			
1333	991617	Fit RH Door Inner Trim Board			
1334	991568	Fit RH Door Checker			
1335	991575	Fit RH Door Felt			
1336	991688	Fit RH Door Wire Harness			
1337	991683	Fit RH Door Window Glass Pillar			
1338	991640	Fit RH Door Outer Pillar			
1339	991613	Fit RH Door Inner Pillar			
1340	991646	Fit RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Fit RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1009	991300	Fit Bumper			
1006	991325	Fit Bumper Bracket			
1007	991462	Fit Bumper Side Retainer			
1008	991433	Fit Bumper Reinforcement			
1010	991468	Fit Bumper Sponge			
1011	991427	Fit Bumper Protector			
1014	991301	Fit Bumper Moulding			
1015	991407	Fit Bumper Lower Spoiler			
1030	991821	Fit RH Headlamp Assy			
1032	995089	Fit RH Side Lamp			
1105	995071	Fit RH Fender	SCR	R	
1107	991744	Fit RH Fender <i>Left End</i>	NR	✓	
1108	991752	Fit RH Fender Protector			

NAC	INC	Item	CON	AC	Q
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1372	994070	Roof Top Panel			
1373	994098	Roof Top Moulding			
1374	994085	Roof Top Air-bag			
1375	994084	Roof Top Air-bag Sensor			
1376	994083	Roof Top Air-bag Control Unit			
1377	992958	Rear Bumper			
1378	992976	Rear Bumper Bracket			
1379	993068	Rear Bumper Side Retainer			
1380	993045	Rear Bumper Reinforcement			
1381	993077	Rear Bumper Sponge			
1382	993040	Rear Bumper Protector			
1383	993026	Rear Bumper Moulding			
1384	993023	Rear Bumper Lower Spoiler			
1385	995116	Rear RH Taillamp			
1386	993456	Rear RH Fender			
1387	993450	Rear RH Fender Protector			
1388	990247	Sticker			

1/4/2020

2 day

No. of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)





































PRI









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2020 Edit Reg		25 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ORANGE PINE PTE LTD , Co. Reg. No.: -									
Main Claimant: DURAI RAJ MURUGAPPA									
Vehicle Reg. No.: SLJ6793K		Date of Loss: 21/03/2020 10:00 - :59 [39 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2854372444SG		Policy/Cover Note No.: 1900247040 (Comprehensive)							
Vehicle Reg. No. (Insured): SJZ4369E		Policy No. (Claimant):							
		Excess:							
Repairer: B's Performance Pte Ltd (HQ) 7 SOON LEE STREET, #01-38 ISPACE, 627668 Pioneer - Tel: 6397 5920									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 03/04/2020]									
Claimant's Solicitor: TEO KENG SIANG LLC - Tel: 63334222									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ6793K (2854372444SG)
[SJZ4369E]
TP
DURAI RAJ MURUGAPPA
Mar 21 2020 10:05AM
[ORANGE PINE PTE LTD]
B's Performance Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/20 17:55	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/20 17:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/03/20 17:55	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/03/20 17:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
41	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
42	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
43	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
44	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
45	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
46	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
47	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
48	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
49	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
50	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
53	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
54	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
55	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
56	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
57	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
58	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
59	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
60	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
61	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
62	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
63	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
64	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
65	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
66	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
67	31/03/20 18:19	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
68	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	31/03/20 18:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	31/03/20 18:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	31/03/20 18:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 09:37	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/03/20 14:37	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004489/ESD3E2
Date: 03/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900247040
 Claimant Vehicle No: SLJ6793K Insured Vehicle No: SJZ4369E
 Date of Loss: 21/03/2020 Nature of Claim: TP Claim No: 2854372444SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ6793K
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY340968
 Reg. Date: 21/12/2016 (Man. Year: 2016) Chassis No: MR053REH104560699
 Colour: Grey Odometer: 76512 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/03/2020
 Date Inspected: 25/03/2020 Inspected At: B's Performance Pte Ltd (HQ)
 7 SOON LEE STREET, #01-38 ISPACE
 Singapore 627668
 Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT RH DOOR WING MIRROR	Broken	0.00 F	*- F
3	1		*FRT RH FENDER	Repair	0.00 F	*- F
4	1		*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >