



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA20004511/R1sf3e2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 15-09-2020



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 4213J	Veh. Inspected	SKZ 1923M
Policy No.	AVFMSB0000591904	Coverage (\$)	0.00
Claim No.	NSV2000116/KW	Excess (\$)	0.00
Assign From	KIN WONG	Assign Date	25/03/2020

2. Vehicle Particulars & Condition

Make & Model	RENAULT GRAND SCENIC 1.5 DCI	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VF1RFA00862895230	Colour	GREY
Odometer	9512	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	MICHELIN	6 mm
L/H Front Tyre	195/55 R20	MICHELIN	6 mm
R/H Rear Tyre	195/55 R20	MICHELIN	6 mm
L/H Rear Tyre	195/55 R20	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/03/2020	Inspection Date	21/07/2020
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------