

ASS. REC. BY:

REF:

CS/TM1 2006 4534/F4-13

Special Instruction:

Surveyor:

Ram

ASSIGNMENT (Office)

From (Person):

Francis Ng Kwa Kay

of

TND

Date/Time:

26.3.2000 10.16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 8901E

Insured:

GBA 3241Y

at Workshop m/s

Combrade Igro

Tel:

62148300

of

59 Loyang Drive

Policy No:

MS 011771

Claim No:

M 200 2151

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24.3.2000

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

26/3/24 11.14pm

Person Contacted:

Juman

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SH 8901E - X

GBA 3241Y - X

Row

ASSIGNMENT

Learning Targets / L.E.J.: 10 491

N/S	O/S

Our Job Ref No : 305389887Date : 31/03/20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : RAM: SH8901E24/03/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: TOKIO GBA3241Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

\$491.00**Total for Part-By-Part Repair Cost**\$491.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : RAMDate : 31/03/2020**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2020 Sendback Est	25 Mar 2020 10:07 \$680.52	26 Mar 2020 10:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANG MO KIO MOTOR SERVICE, Co. Reg. No.: 26028100W			
Main Claimant:	CTPL			
Vehicle Reg. No.:	SH8901E	Date of Loss:	24/03/2020 15:00 - :59 [17 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / M2002131	Policy/Cover Note No.:	MS011771 (Third Party Only) Coverage: 09/11/2019 - 08/11/2020	
Vehicle Reg. No. (Insured):	GBA3241Y	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300			
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/04/2020]			
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)


Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Team: ARC Repair TP(CLSO)	JOB CARD	Sales Order: 305389887	JC NO.:
STOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SH 8901E	MILEAGE
/MS	7010045	MAKE: HYUNDAI	FUEL
STOMER NO	383 SIN MING DRIVE	MODEL IONIQ(G2)	DATE/TIME IN 24.03.2020 16:50
DRESS	Singapore SINGAPORE 575717	YR OF MANU. 08.10.2018	TARGET DATE
	65508755	CHASSIS CODE KMHC851CVKU114604	COMPLETION DATE/TIME
(R)	(O)		
(P)			
COUNT CARD NO.			

7060

Accident Date: 24.03.2020
NATURE: 3P 24.03.2020

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SH 8901E

Engine No.: CH1ANG

Name of Service Advisor

Signature/Date

returned to Service Reception upon collection

Exit Pass

Vehicle No.: SH 8901E

Name of Service Advisor

Date

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2020 08:42
Date Of Accident	24/03/2020 15:45
Exact Location Of Accident	MARSILING LANE BLK 15
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH8901E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGETAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN JECK NAM
NRIC No	SXXXX845D
Date Of Birth	23/10/1950
Occupation	OUTDOOR
Date Of Driving Pass	26/06/1972
Driving Experience	47 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97631038
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 612 WOODLANDS AVENUE 4 #02-463
Postcode	730612
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED *TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA3241Y
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	UNSURE
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199703821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 24 march 2020 @ 12:42 h I

yet (A) Slow down and stop. Suddenly.

veh (R) from my Right Gar park lot

Roll forward and left Vert (A) Right

Front: VEH (R) inside NO driver never pull

hand brake went to the vehicle Beck.

to take thing @ the point of

accident velt (A)

DECLARATION

We declare the foregoing particulars are true in every respect.

COMFORT CORPORATION PEF LTD
CO. REG. NO. 109302821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH8901E
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Mar 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU110360
Chassis No.:	KMHC851CVKU114604
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,968.00
Original Registration Date:	08 Oct 2018
First Registration Date:	08 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$11,956.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Oct 2026
PARF Rebate Amount:	\$8,967.00
Intended COE Rebate Details	
COE Expiry Date:	07 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,228.00
COE Rebate Amount:	\$19,775.00
Total Rebate Amount:	\$28,742.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Mar 2020

OK

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	818901E	Date of Loss:	24/03/2020
Vehicle Reg. No.:	SH8910E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	08/10/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU110360	Chassis No:	MHC851CVKU114604
Odometer:	166639 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	149.52
Miscellaneous Items	11.00
Labour	520.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	680.52
+ GST 7.00% (S\$)	47.64
Nett Amount (S\$)	728.16

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	280.00
2	SPRAY PAINTING	New	240.00
Gross Labour Cost (S\$)			520.00

ComfortDelGro Engineering Pte Ltd/SH8910E/25/03/2020 10:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Handwritten notes and signatures]
 26/3/2020
 25/03/2020 1530 hrs
 Periazhaven (C) 133 811 8
 85622772
 24th Repair photo
 P/P
 2x photo

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305389887
REGN NO : SH 8901E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 08.10.2018
DATE/TIME IN : 24.03.2020 16:50
ACCIDENT DATE : 24.03.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB PANEL BEATING
0001 L merimen
0002 SP SPRAYPAINT CHARGE

280.00

11.00

200.00

SUB-TOTAL : 491.00

TOTAL : 491.00

A NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Wong S. Tan

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Mar 2020 Sendback Est	25 Mar 2020 10:07 S\$680.52	26 Mar 2020 10:16 Edit Adj Rpt	S\$491.00 Edit Estimates	S\$491.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANG MO KIO MOTOR SERVICE, Co. Reg. No.: 26028100W		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SH8901E	Date of Loss:	24/03/2020 15:00 - :59 [17 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2002131	Policy/Cover Note No.:	MS011771 (Third Party Only) Coverage: 09/11/2019 - 08/11/2020
Vehicle Reg. No. (Insured):	GBA3241Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 06/04/2020]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SH8901E (M2002131)
[GBA3241Y]
TP
CTPL
Mar 24 2020 3:00PM
[ANG MO KIO MOTOR SERVICE]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	25/03/20 10:07	Repairer Estimates	1 Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	30/03/20 11:02	Accident Statement From: SC - Reg. No: GBA3241Y, Claimant: ANG MO KIO MOTOR SERVICE	1 Load HTM	

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/03/20 16:54	General View	1 Load JPG	✓
2	31/03/20 16:54	General View	1 Load JPG	✓
3	31/03/20 16:54	General View	1 Load JPG	✓
4	31/03/20 16:54	General View	1 Load JPG	✓
5	31/03/20 16:54	General View	1 Load JPG	✓
6	31/03/20 16:54	General View	1 Load JPG	✓
7	31/03/20 16:54	General View	1 Load JPG	✓
8	31/03/20 16:54	General View	1 Load JPG	✓
9	31/03/20 16:54	General View	1 Load JPG	✓
10	31/03/20 16:54	General View	1 Load JPG	✓
11	31/03/20 16:54	General View	1 Load JPG	✓
12	31/03/20 16:54	General View	1 Load JPG	✓
13	31/03/20 16:54	General View	1 Load JPG	✓
14	31/03/20 16:54	General View	1 Load JPG	✓
15	31/03/20 16:54	General View	1 Load JPG	✓
16	31/03/20 16:54	General View	1 Load JPG	✓
17	31/03/20 16:54	General View	1 Load JPG	✓
18	31/03/20 16:54	General View	1 Load JPG	✓
19	31/03/20 16:54	General View	1 Load JPG	✓
20	31/03/20 16:54	General View	1 Load JPG	✓
21	31/03/20 16:54	General View	1 Load JPG	✓
22	31/03/20 16:54	General View	1 Load JPG	✓
23	31/03/20 16:54	General View	1 Load JPG	✓
24	31/03/20 16:54	General View	1 Load JPG	✓
25	31/03/20 16:54	General View	1 Load JPG	✓
26	31/03/20 16:54	General View	1 Load JPG	✓
27	31/03/20 16:54	General View	1 Load JPG	✓
28	31/03/20 16:54	General View	1 Load JPG	✓
29	31/03/20 16:54	General View	1 Load JPG	✓
30	31/03/20 16:54	General View	1 Load JPG	✓

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=928358&extid=335010&corole=4&... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20004534/FTF3S2

Date: 01/04/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS011771

Claimant Vehicle No: SH8901E

Insured Vehicle No: GBA3241Y

Date of Loss: 24/03/2020

Nature of Claim: TP

Claim No: M2002131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH8901E

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEJU110360

Reg. Date: 08/10/2018 (Man. Year: 2018)

Chassis No: KMHC851CVKU114604

Colour: Blue

Odometer: 166639 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Davanti 8 mm

Rear Left Side:

Davanti 9 mm

Front Right Side: Davanti 8 mm

Rear Right Side:

Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	149.52	0.00	149.52	100.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	520.00	480.00	40.00	7.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	680.52	491.00	189.52	27.85
+ GST 7.00/7.00% (S\$)	47.64	34.37	13.27	27.85
Nett Amount (S\$)	728.16	525.37	202.79	27.85

INSPECTION

Date of Assignment: 26/03/2020 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 25/03/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH8901E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER GRILLE RH	Not Necessary	186.90 FL	-	*- FL
F=Franchise part. L=ListItemDisc.							
					Sub Total (S\$)	186.90	0.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	37.38	0.00
					Total Parts (S\$)	149.52	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	280.00	280.00
2	SPRAY PAINTING	New	240.00	200.00
Gross Labour Cost (S\$)			520.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >