

ASSIGNMENT

From: Date: 26/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJC 5205 J

at Workshop m/s: MJE Motors

of: Bkt 7, 01-96 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJC 5205 J

Yr Regn:

1/6/2006

Type:

M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Corolla

C.C 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

246336

T/Radio: Insured / Std / NI / NA

Eng/No:

3ZZ 4557749

C/No:

MR053ZEC107116878

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/55/16

R: 195/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

24/11/19

D.O.I.

26/11/19 0324PM

Survey held at

MJE Motors

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 5,000k - 6,000k

HS 4058/2 Team
lin
30/3/2020

MV 10,000/2
PV 6885/2
NV 3115/2

Recommend COR of \$ 3115/2 in view of the Net Value.

RECEIVED 18 DEC 2019 With 7 repair days

Team lin
30/3/2020

Team lin
27/11/19

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

PRE

Lump Sum / I.B.J.: (\$

Survey Fee:

120

Transportation:

3 + R.S. SI

Photos


Others

TOTAL

121

ASS. REC. BY: Mr. Lin REF: CS3/III/19020903/BSd3 Special Instruction: 26/3/2020
 From (Person): Derrick Pan ASSIGNMENT (Office) 26/11/19 @ 1:38pm
 of Gabriel wee of III Date/Time: 26/11/19 @ 1:38pm
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SJC 5205J Insured: SHA 1012J
 at Workshop m/s: MJC MOTOR Tel: 6454 2203
 of Blk 7 Sin Ming Ind. Est. Sec. C # 01-94
 Policy No: MCOM005 Claim No: MCT19110571
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 24/11/2019
 (Client's Record)
 CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____
 Date/Time: 2:30pm @ 28/11/19 Person Contacted: Icelly Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Initials (X)</u>
	<u>SJC 5205J - X</u>
	<u>SHA 1012J - CC3 / 116005290 / Kpa3n2</u>
	<u>Don. 18/3/2016</u>

Submit L/S \$ 4,050/- @ 7 days
 (\$ 1,700/- Red - 30%) → COR checked & scan.


06/15/2020 - COR renewed. To submit as adjusted.

- No after repair photos.

- To indicate MV as per Mr Lin Recommendation in his PRS report.

- MV / Repair limit at 3K to state at remark column of Survey report.