



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20004557/Uyd3s2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 14-07-2020



ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 3369T	Veh. Inspected	GBF 8537K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1089557-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	26/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDY2318025096	Colour	BLUE
Odometer	162328 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/70 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/70 R15	YOKOHAMA	6 mm
R/H Rear Tyre	165 R13 (D)	HIFLY	6/6 mm
L/H Rear Tyre	165 R13 (D)	HIFLY	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/03/2020	Inspect Date / Time	27/02/2020 (09:40 AM)
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------