

Your Ref : SLT 230E  
Our Ref : **SMG 5889D/TAP/jp/ws**  
Date : 25 March 2020

Fax : **6538 3708**  
Tel : **3152 0989**  
Email : **accident@kscgp.com**

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

**DATE OF ACCIDENT: 21 March 2020**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your tele-conversation with Ms Peach of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor	Company Name
1.	Ananda Kumar Biswas s/o B N Biswas	United Appraisal and Management Pte Ltd
2.	Tan Ling Ling Candy	Impact Analysis
3.		AJAX Inspection

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Team Autopro Pte Ltd  
160 Sin Ming Drive  
#01-14 Sin Ming Autocity  
Singapore 575722

Contact Person/Tel : Ms Peach (Tel: 8879 9997) / Mr Eric (Tel: 8269 9999)

Yours faithfully,

*WS*

Your Ref : SLT 230E

Our Ref : **SMG 5889D/TAP/jp/ws**

Date : 25 March 2020

**Acknowledgement**

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of \_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date: