	Lim Lim	ASSIGNME				- 1 .	V
From (Person)	Sic to wi Hong	of AJ	ig	D	ate/Time: 19	1.3.1000	6.05 p.m
Estimated Cos			Bill to:				
To inspect Ve		6889D	es .	Insured:		230E	
at Workshop r of 160 Sh	ming page \$101-1	4		Tel:_	6258 199	5	-
Policy No:	U		Claim No:			***	
Sum Insured:			Excess:				70. CO. CO. CO.
Make of Veh:				E	O.O.A. 21.3	2020	
(Client's Record CA / REV / Date/Time:	REP. / REV 24 HRS	P'' erson Contacted; _	Peach_		H.O.D. Endorse	ment:	
Date/Time	Action/Instruction (V) Estimate					
		2 / A10 100	16320 / ALL	b 12.0	1 - 141091	2000	
	SL7 240E - (0	3/ A19 190	ACS	- Chris			
	SLY 260E - (0	57 A15 190	1 9) JAG				

Milmo

ASS, REC. BY:	REF: AIG		Veron
	A	SSIGNMENT	
From:	Date: 26.3.202	-0 Veh No: 5M1G 588	PD Yr Regn: 25/11 1201
Estimated Cost:		Types M.Car / M.Cycle / Bus / Van /	
OD TP/WS/TP RES/OD R	ES / EVA / INV / MV	Truck / Trailer or	16
7	SMG 5899 D	Make: BMW 523	c.c 2497
	autopro	Colour Black	A/C: Insured / Std / NI / NA
the state of the s	# 01-14 Sh ming	Sp.Reading 149522	T/Radio: Insured / Std / NI / N.
Insured:	0	Eng/No: 09997815N5	12B25AF
Policy No.			60 6867132
Claims No.		Gen. Cond: Good / Fair / Poor / Bu	
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leak	ed / Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leak	10,000
Make of Veh:		Modi: Nil / S/Rim / STD A/Rim	or
and the state of t		Tyre Size: F: 245 /4	
(Policy Condition)		R: 245/45	
Remark: The veh had comme	nced its N/S	O/S BS / DUN / EXNOVA /GY / FS / LI	And the second s
repair at the time of		TOYO / YOKO or	
Bal, or Market Value: 4	-6 600 /2	Front	Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. / mm	R/Bal. / n
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. 6 n
Est. Repairs:	days Res.: Yes or No	D.O.A. 21/3/2020	D.O.I. 26/3/2020
Lum Sum:	% 3 Val.: Yes or No		Autopro
A CONTRACTOR	rep'	Des. of Damages (Fit / Rear / C	
CA / REV / REP. / 24	Vehicle: IN	/ OUT	
Date: Person	Contacted:	The U/C / Chassis frame / E	Body Structure affected due to collis
Date / Time Action / Ins	truction		
DXR		(A.)	
4 ()			
* NV 4	6,600/2		
	9,926/2		
NV	6074/2		TGam him
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	27/3/2020
1)	: Final Report	Resurvey No. of Trip:	Survey Fee;
			Transportation:
Date/Time, File Return to?)s+Rssi
Date/Time, File Return to?	Ad	d Fee: Site Insp (\$	J_3+N0,0
	Ad	: Site Insp (\$) Photos
	Ad	Beautiful	

FW: [pri fyna] FW: Re: 2 DAYS NOTICE: SMG 5889 D (Our Ref) and SLT 230 E (... Page 1 of 2

FW: [pri fyna] FW: Re: 2 DAYS NOTICE: SMG 5889 D (Our Ref) and SLT 230 E (Your Ref) Dated 21ST MARCH 2020

From:

Teo, Ericweihong

To:

assignments@lkkauto.com, admin-a@lkkauto.com

Cc:

Chin, Lee-Ying, Lim, Kok-Chong, Subramaniam, Divyashni, Abu Kassim, Noor Mariesa, Hor, Yinrul

Sent:

Wednesday, 25 March, 2020 6:05:34 PM

Hi LKK,

Kindly assist on this.

Thank you.

Regards.

Eric Teo Wei Hong

AIG

Claim Adjuster II,

Singapore- Auto Express & FNOL

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel 8001206556 | Ext: 1002213

Ericweihong.Teo@aig.com | www.aig.com

From: TeamAutoPro North <teamautopl@gmail.com>

Sent: Wednesday, March 25, 2020 5:40 PM

To: Chan, Yoke Shi <<u>vokeshi.chan@aig.com</u>>; Chin, Lee-Ying <<u>Lee-Ying.Chin@aig.com</u>>; Fong, Andy-SY <<u>Andy-SY.Fong@aig.com</u>>; Kaur, Baljit <<u>Baljit.Kaur@aig.com</u>>; Lim, Sheng Yang <<u>ShengYang.Lim@aig.com</u>>; Abu Kassim, Noor Mariesa <<u>NoorMariesa.AbuKassim@aig.com</u>>; Supramaniam, Darshene <<u>Darshene.Supramaniam@aig.com</u>>; Tan, Lily (AIG) <<u>Lily.Tan@aig.com</u>>; Hor, Yinrul <<u>Yinrul.Hor@aig.com</u>>; AlG SGP, Claims-Survey <<u>AIGSGP_ClaimsSurvey@aig.com</u>>

Cc: accident@kscgp.com; jiapei@kscgp.com

Subject: [EXTERNAL] Re: 2 DAYS NOTICE: SMG 5889 D (Our Ref) and SLT 230 E (Your Ref) Dated 21ST MARCH 2020

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Without Prejudice

Our client would like to engage a lawfirm to assist with his case, As such, we will have subject passed on to our client's lawyer for further proceeding.

Thank you.

Dear Jia pei,

Kindly take note.

Thank you.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Peach Ang

Team AutoPro Pte Ltd



Tel: 6258 1955 Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722 Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

On Wed, Mar 25, 2020 at 4:09 PM TeamAutoPro North < teamautopl@gmail.com > wrote:

Dear Sir/Madam,

Road Traffic Accident Involving SMG 5889 D (Our Ref) and SLT 230 E (Your Ref) Dated 21ST MARCH 2020, Time around 19:15HRS

@ ANG MO KIO AVE 1

We represent our client; NICHOLAS YOSUKE ANG to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SMG 5889 D and your insured's vehicle registration number: SLT 230 E.

For efficiency purpose, we are agreeable with the appointment of <u>Mr Lim - LKK</u> as the SJE for subject claim. Please let us know within 2 working days from today your agreeing to the above otherwise kindly send us your list of at least ten (10) motor surveyors, <u>via email to the following personnel</u>:-

Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722		
Email Address	teamautopl@gmail.com		
Contact Person	Eric Lee	8269 9999	

Thank you for your attention to this email and we look forward to your earliest reply.

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Peach Ang

Team AutoPro Pte Ltd



Tel: 6258 1955 Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722 Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	107C
Vehicle No.:	SMG5889D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Mar 2020
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	09997815N52B25AF
Chassis No.:	WBAFP32060C867192
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$49,344.00
Original Registration Date:	25 Nov 2011
First Registration Date:	25 Nov 2011
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$49,344.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2021
PARF Rebate Amount: Intended COE Rebate Details	\$27,139.00
COE Expiry Date:	24 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$12,787.00
Total Rebate Amount:	\$39,926.00

The information contained herein is correct as at 27 Mar 2020

OK

Dep 14,010/48

COE 1 yr 8 untho

MV 46,680 | 2 PV 39,926 | 2 NV 6074 | 2

> 700m like-27/3/2000

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Audi A1 Sportback 1.0A TFSI S-tronic @ \$64,800



1 Owner, Premium Auto Agent Unit.1.98% Interest, 100% Loan Available, ZYes Warranty

ABWIN! ONE-STOP

Post an Ad-Browse by Category

Advertiser Login

Ways of Selling

« Back (1 2 3 4 5) Next »

Sort by Reg. Date

▼ 20 results/page

92 vehicles

BMW 523i

Advanced Search

Any

Price. Depreciation Reg Date

Eng Cap

Mileage

Veh Type Status

Search Selection

BMW 523i

Make

Any

Any

2011

Any

All Available

BMW 5 Series 523i

\$48,000

\$14.840 /vr

13-Dec-2011

2.497 cc

Arriv

124,250 km

Luxury

DIRECT OWNER

20" Sports Rims, Bodykit.

Posted: 09-Mar-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



BMW 5 Series 523i

N,A

09-Dec-2011

2,497 cc

Luxury

SOLD

Paper Plus Boday \$43k, Nice Car Plate, 1 Owner, View To Appreciate. 90% Loan Of The Car Price Available. High Approval Rate. High Trade In. Please Call Or SMS Now For Enquiries And Viewing Appointment.

Posted: 28-Feb-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



BMW 5 Series 523i Highline

N.A

09-Dec-2011

2,497 cc

Luxury

SOLD

Wonderful December 2011 And 01 Owner Only, Very Beautiful Groomed And Clean Interior, Brand New 6 Months Road Tax Paid \$900,00 Until June 2020, View At Holland Road, 4 Expensive Tyres, Drive Until December 2021, Interior Is Very Beautiful And CI Ean And Groom...

DIRECT OWNER

Posted: 23-Jan-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



BMW 5 Series 523i

04-Nov-2011

2.497 cc

Luxury

SOLD

N.A Very Well Maintained And Serviced Regularly By Owner. Flexible Loan Schemes Available! Luxury, Spacious And Comfortable. Call Now To Arrange A No Obligations Viewing!

Car Empire Automobiles Pte Ltd

Posted: 05-Jan-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



BMW 5 Series 523i Highline

\$47,000

\$14,010 /yr

01-Nov-2011

2,497 cc

134,000 km

Luxury

Available

Rare 1 Owner Highline Model In The Market, PML Unit, Well Maintained, High Arf And Coe Therefore High Paper Value, Very Safe Buy. Scrap Now Already \$43,000. Selling Only \$5,500 Above Scrap Only. Trade In And Loan Welcome.

Posted: 25-Mar-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



BMW 5 Series 523i Highline

\$44,800

\$12,650 /yr

Very Good Condition, Car Just Serviced, Interior Groomed, No Sticky Handles Just Changed, No Faults, Perfect For Renewal! No

31-Oct-2011

2,497 cc

120,000 km

Available DIRECT OWNER

Consignment Agents, But Price Can Negotiate. Must Sell. Posted: 20-Mar-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i



BMW 5 Series 523i Highline

N.A

31-Oct-2011

2,497 cc

Luxury

SOLD

Graded B by SToo

Rare 1 Owner Highline Model In The Market With Low Mileage. PML Unit, Well Maintained, High Arf And Coe Therefore High Paper Value. Very Safe Buy. Scrap Now Already \$43,600. Selling Only \$6,288 Above Scrap Only. Trade In And Loan Welcome.

Posted: 22-Feb-2020 Tags: 2011 BMW 523i, BMW 523i, BMW, 523i

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	33 13.00 , 001.00 1
	ACCIDENT STATEMENT
Date Of Report	23/03/2020 19:03
Date Of Accident	21/03/2020 19:15
Exact Location Of Accident	ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMG5889D
Insured/Policyholder	
Name Of Registered Owner	NICHOLAS YOSUKE ANG
NRIC No	SXXXX107C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90911377
Alternative Phone No	OFFICE-90911377
Vehicle Particulars	

Vehicle Particulars

BMW Manufacturer 5231

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

5107614750 Policy Number

Cover Note Number

Driver

NICHOLAS YOSUKE ANG Name of Driver

NRIC No SXXXX107C 16/01/1994 Date Of Birth INDOOR Occupation 30/06/2015 Date Of Driving Pass

4 YEARS AND 8 MONTHS Driving Experience

Gender

(LOCAL) +65-90911377 Mobile Number

Fax Number

OFFICE-90911377 Contact Number

NOEMAIL **EMail Address**

Address

APT BLK 332 SERANGOON AVE 3 #12-261

Postcode

550332

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) Passenger 1

2

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT230E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for Investigation
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by mo.
 - [iv] administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims, history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Shingture

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Consul Personnel's Signature Name

NRIC/FIN NO

SKETCH PLAN

A: 3m65899D B: SLT 230E

DESCRIBE CIRCUMSTANC		
Con ten	alon global de fin	, 2 was travely
on lone 3 i	hun sudderly vehicle B	come or cutting into
ny lue, Z	les to state that 2 kept	whire my lane and the
speed limit.		» ««
	VIII.	
		2
ECLARATION		
	rticulars are true in overy respect	L
Sin,		
onconolder's Signifique Late & Time	Driver's Signature (If driver is not the policyholder) Date & Time	Reporting Centre Parsonnel's Signature Name NRIC/Fin No.



BMW : 5 Series - F10 (2010 - 2016) : Rear Wheel Drive Models : without AFS (Active Front Steering) : Series : 18" Wheel 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-1°20'	-1°19'	-0°42' 0°18'
6°35'	6°35'	
0°44'	0°47'	0°03' 0°07'
10°12'	10°11'	
8°52'	8°52'	
		-2°21' -1°21'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Actual	Before	Specified Range
0°30'	0°30'	-0°42' 0°18'
6°58'	6°58'	
0°47'	0°48'	0°03' 0°07'
8°19'	8°20'	
8°49'	8°49'	
		-2°21' -1°21'

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	Before	Specified Range
-1°50'	-1°48'	-0°30' 0°30'
-0°221	-0°22'	-0°30' 0°30'
1°53'	1°51'	
1°31'	1°35'	-0°02' 0°22'
		-0°30' 0°30'

Rear: Left

Actual	Before	Specified Range
-2°18'	-2°18'	-2°15' -1°25'
0°17'	0°16'	0°07' 0°11'

Camber Toe

	Rear : Right				
Actual	Before	Specified Range			
-1°33'	-1°37'	-2°15' -1°25'			
0°04'	-0°01'	0°07' 0°11'			

Rear

Cross Camber Total Toe Thrust Angle

Actual	Before	Specified Range
-0°45'	-0°41'	-0°30' 0°30'
0°21'	0°15'	0°06' 0°30'
0.06,	0.08,	-0°12' 0°12'

Undercarriage

Condition (CON)
(01) Hent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing (13) Term (14) Unconfirmed (15) Not Working

<u>AS_119N_LOS_1</u>
(1)Replace (√) (2)Repair (X) (3)Clack (7)
(4)Not Consistent (NC)

Vehicle No: SMG 5889 D

NAC	-	Item	CON	AC	Qty	NAC	INC	It
		Frt LH Shock Absorber	137	V			991935	
		Frt LH Shock Absorber Mounting	DD	V			991944	
		Frt LH Coil Spring					990632	
		Frt LH Knuckle Arm .	DD	V			991844	
		Frt LH Knuckle Arm Bearing	JM	1			991845	
		Frt LH Lower Arm	DO	V			991851	
		Frt LH Upper Arm	DD	V		The second second second	992064	_
		Frt LH Tie Rod					992040	
		Frt LH Drive Shaft				-	991692	_
		Frt LH Control Arm					990661	
		Frt LH Trailing Arm					992062	
		Frt LH Leaf Spring					991848	
		Frt LH Brake Disc Rotor					991293	
		Frt LH Brake Caliper					991281	
		Frt LH Brake Pipe					991292	
		Frt LH Brake Hose					991287	
		Frt LH Brake Sensor Wire					991295	
1389	991989	Frt Stay Bar Bracket					993720	
1390	994455	Steering Rack & Pinion					993723	
1391	994435	Steering Cross Member					993173	
		Frt Sub Frame	-				993550	
		Frt Sub Frame Mounting Frt Anti Roll Bar	-		\vdash		993551	
		Frt Anti Roll Bar Linkage	-		\vdash		993601	
		Engine Block	-	-	\vdash		993885	
1397		Engine Block Gasket	-	-			993322	
	990890	Engine Oil Sump	-	-	\vdash		993178	
1300	990972	Engine Oil	+	-	\vdash		995117	
		Gear Box Assy	+	-	\vdash		995110	
		Gear Box Gasket	+	-	\vdash		992942	
		Gear Box Oil Sump	-	-	\vdash		992938 990434	
		Gear Oil	-	-	\vdash		992947	-
		Centre Exhaust Pipe Assy	-	-	\vdash	1439	992947	-
		Centre Exhaust Mounting	-	-	-			+
		Floor Panel	-	-	\vdash	1		+
		Rear LH Shock Absorber	1	-		-		+
1406		Rear LH Shock Absorber Mounting	-	\vdash	\vdash			+
1407		Rear LH Coil Spring	_	-	\vdash	-		+
		Rear LH Knuckle Arm	7. 1	-	\vdash			+
1409	993551	Rear LH Knuckle Arm Bearing			\Box			†
1410	993597	Rear LH Lower Arm						T
1411	993884	Rear LH Upper Arm						T
		Rear LH Drive Shaft					1	T
		Rear LH Control Arm						T
1414	993881	Rear LH Trailing Arm				-	100	T
		Rear LH Leaf Spring						T
		Rear LH Brake Disc Rotor						T
1417	992937	Rear LH Brake Caliper Assy						T
		Rear LH Brake Pipe						T
		Rear LH Brake Hose						T
		Rear Sub Frame						
		Rear Sub Frame Mounting						T
		Rear Anti Roll Bar					9	
		Rear Anti Roll Bar Linkage				1		T
The same of the same of		Axle Beam						T
		Rear Axle Panhard Rod						
		Differential Assy						
1427	992706	Propeller Shaft						
								_

		Vehicle No: SMG 5889	1		
NAC	INC	Item	CON	AC	Qt
1428	991935	Frt RH, Shock Absorber			
		Frt RH Shock Absorber Mounting			
		Frt RH Coil Spring			
		Frt RH Knuckle Arm			
		Frt RH Knuckle Arm Bearing			
		Frt RH Lower Arm	1		
		Frt RH Upper Arm	1	-	-
		Frt RH Tie Rod	-	_	-
_		and the control and the control of t	-	-	-
	-	Frt RH Drive Shaft		_	-
		Frt RH Control Arm	-	_	
		Frt RH Trailing Arm			
		Frt RH Leaf Spring			
		Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
		Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire	1		
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
		Rear RH Coil Spring	1		
1448	993550	Rear RH Knuckle Arm			1
		Rear RH Knuckle Arm Bearing			
		Rear RH Lower Arm	1		
		Rear RH Upper Arm	+-		
1452	993322	Rear RH Drive Shaft	+		-
		Rear RH Control Arm	+		\vdash
1454	005117	Rear RH Trailing Arm	+		-
1455	005110	Rear RH Leaf Spring	-	-	-
		Rear RH Brake Disc Rotor	+	-	-
			+-	-	-
		Rear RH Brake Caliper Assy	-	-	-
		Rear RH Brake Pipe	-	-	⊢
1459	992947	Rear RH Brake Hose	-		-
			-		-
-			+	-	-
			-		_
			1		
		(*)			
9					
					†
				-	+
			+	-	+
-			+	-	+
-			1	-	+
-			-	-	+
	-		-	-	+
			-	-	-
			-	-	1
					1
	Macro And Inc.				
7/3			11 11 11 11 11		
rite and					
- 47			1		1
				_	_

No of Items:

Assessor: Talin Ma

MOTOR CAR (Frt)

	INC		CON	AC	Qt
100		6 Frt Number Plate			1
1002	2 99188	7 Frt Number Plate Base			
100	99188	9 Frt Number Plate Garnish			
1004	99130	0 Frt Bumper 1 Frt Bumper Clips	CUT	V	
1006	99132	5 Frt Bumper Bracket	NEC	V	
1007	7 99146	2 Frt Bumper Side Retainer	1000	-	_
1008	99143	3 Frt Bumper Reinforcement	NEG	V	-
	99131	Frt Bumper Beam	-	-	-
1010	99146	Frt Bumper Sponge	-	_	_
1011	99142	7 Frt Bumper Protector	-	-	
1012	99142	Frt Bumper Pad	+	-	-
1013	99136	Frt Bumper Grille	-	-	
1014	99130	Frt Bumper Moulding			-
1015	99140	Frt Bumper Lower Spoiler			
1016		Frt Bumper Sensor	KUT	V	1
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991353	Frt RH Bumper Fog Lamp Cover			
1020	993073	Frt LH Bumper Fog Lamp	BR	V	
1021	991703	Frt RH Bumper Fog Lamp Frt Grille			
1022		Frt Grille Emblem	-	_	9
1023	991799	Frt Grille Chrome Moulding.	-	-	_
1024	991222	Fit Apron Panel	-	-	
1025	992013	Frt Support Panel	-	-	-
1026	992025	Frt Support Panel Top Garnish Cover		-	
1027	992416	Hom		-	
1028	991277	Frt Brace Panel		7	-
1029	995153	Fit LH Headlamp Assy	CUT	V	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Fr: LH Side Lamp			
1033	990748	Frt RH Side Lamp Bonnet			
	991328	Bonnet Emblem		*	
1035	990287	Bannet Lock	-	-	
1036	990285	Bonnet Insulator	-	+	-
1037	990273	Bonnet Hinge	-	+	-
1038	990261	Bonnet Damper		+	
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1044	990122	Air Con Fan Assy	-	4	
1045	990118	Air Con Suction Pipe (Low Pressure) * Air Con Suction Hose	-	-	_
1046		Air Con Discharge Pipe (High Pressure)	_	-	_
1047	990114	Air Con Discharge Flose	_	-	-
048	990149	Air Con Liquid Pipe	-	-	-
049	995066	A'ir Con Receiver Drier	-	-	-
050	990111	Air Con Compressor Assy	-	-	-
051	995294	Air Con Belt .		1	
0.52	995074	Radiator		1	
053	992738	Radiator Cowling			
054	992742	Radiator Fan Assy			
055	992745	Radiator Fan Clutch			
056	992/58	Radiator Hose Top			
057	992757	Radiator Hose Bottom			
050	000151	Radiator Expansion Tank			
	990151				
061	000000	Air Cleaner Assy			
		Air Cleaner Hose			
		Air Cleaner Resonator			
064	991712	rt Exhaust Manifold			
	991713	rt Exhaust Manifold Cover			
366	991034 1	rt Exhaust Manifold Sensor (Oxygen) ront Exhaust Pipe			_
067	990219	Outers		-	_
	××06.07 1	entrary .	100	1	
168	990224 8	Sattery Cover		-	-
168	990224 E	Battery Cover battery Bracker	-	F	-

NAC	INC	Vehicle No: SNAG				10.
1071		5 Fuse Box	- 0	ON	AC	Qty
1072			-			_
1072	99401	1 Relay Box				-
-	99505	3 Wiper Washer Tank				
1074		2 Wiper Washer Tank Motor				
1075						
1076		O Alternator Belt				
1077	99268	8 Power Steering Pump				
1078		Power Steering Belt				
1079	99443					
1080		2 Power Steering Hose	-	-		
1081		ABS Pump Control Unit	-	-	-	-
1082	99042	7 Brake Master Pump Assy	-	-	-	
1083	00040	Brake Waster Fump Assy	-	-		
1084	00100	Brake Booster Pump Assy	_	_		
The second second	99100	Engine Top Cover	-			
1085	99101			-		
1086		Engine Mounting				
1037	990949	Engine Mounting Frt				. 1
1088	990950	Engine Mounting LH				
1089	990952	Engine Mounting RH			7	
1090	990951	Engine Mounting Rear				
1091	992234	Gear Box Mounting		1	+	
1092	991520	Fit LH Chassis Member	1	+	-	\dashv
1093		Frt RH Chassis Member	-	-	-	\dashv
1094	990728	Frt Vertical Cross Member	-	-	-	\dashv
1095	901863	Frt Lower Cross Member	-	-	-	-
1096	905070	Frt LH Fender	-	-	1	-
1097			DI	2/3	4	_
1098	005147	Frt LH Fender Inner Panel	-	-	-	-
	993147	Frt LH Fender Lamp	-	-		
1099	995148	Frt LH Fender Protector				
1100	991740	Frt LH Fender Inner Shield	TA		1	
1101	995179	Frt LH Mudflap				
1102	995170	Frt LH Wheel Rim	a	TI	/	
1103	994025	Frt LH Rim Cover		1		
1104	995065	Frt LH Tyre				
1105		Frt RH Fender				\neg
1106	991739	Prt RH Fender Inner Panel		\neg	_	\neg
1107	991744	Frt RH Fender Lamp			1	
1108	991752	Frt RH Fender Protector	1	_	+	
1109	991740	Frt RH Fender Inner Shield	+	7	+	-
110	991884	Frt RH Mudflap	1		+	-
1111	992087	Frt RH Wheel Rim -	-	+	+	\dashv
112		Frt RH Rim Cover	+	+	+	-
113		Frt RH Tyre	+-	+	+	-
114		Frt Windscreen Glass	-	+	+	-
115		Frt Windscreen Rubber	-	+	+	-
-			-	-	_	-
116	992108	Frt Windscreen Moulding		1		
117		Frt Windscreen Sealant				
118		ERP Bracket				
119		ERP Unit				
120		Frt Wiper Arm				
121		Frt Wiper Blade	Date.		5 8	
122	995045	Wiper Panel Garnish				
123	991126	Firewall Panel				
124	-	Dashboard Assy	-	-	-	-
125	992282	Glove Box Cover	-	+	+	-
126	THE RESERVE AND DESCRIPTION OF THE PERSON NAMED IN	Glove Box Compartment		+		-
-	004402	Steering Wheel 474	-	-	+	-
-		Steering Wheel Airbag	-	-	-	-
		Steering Wheel Airbag Sensor		_		4
129	990749	Dashboard Airbag				
130		Dashboard Airbag Sensor				1
		Airbag Control Unit		1		
132		Frt Driver Seat	1000	-	1	-
	market an expense of	Frt RH Seat Belt Assy	-	1	-	
		Fit Passenger Scal	7000	+	+	-
					-	
		Frt LH Seat Belt Assy			-	-4
136	990247	Sticker +		1-	1	_
_						1
					1_	1
	i i			1	1.0	
						_