

24/03/20

ASS. REC. BY:

REFCS/ICS20004596/Ktd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Nicholas chua

of

ICS

Date/Time: 27/3/2020 @ 8:44am

Estimated Cost:

Bill to:

OD ~~IP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 2000 A

Insured:

SQZ 3090A

at Workshop m/s

H.C Auto

Tel:

9457 0678

of

160 Sin Ming Drive # 05-09

Policy No:

Claim No:

DMPC 2000070H

Sum Insured:

Excess:

Make of Veh:

D.O.A 25/03/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 8:46am @ 27/3/2020

Person Contacted:

Joe

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate

✓

SLR 2000A - X

SQZ 3090A - X

4596 / 1622

2000

Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 584J

Vehicle Details

| | |
|-------------------------------------|---------------------------------------|
| Vehicle No.: | SLR2000A |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 30 Mar 2020 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | VELLFIRE 2.5Z EDITION CVT 2WD |
| Primary Colour: | White |
| Manufacturing Year: | 2017 |
| Engine No.: | 2ARH895668 |
| Chassis No.: | AGH300123538 |
| Maximum Power Output: | 134.0 kW (179 bhp) |
| Open Market Value: | \$39,576.00 |
| Original Registration Date: | 27 Jul 2017 |
| First Registration Date: | 27 Jul 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$47,407.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 26 Jul 2027 |
| PARF Rebate Amount: | \$35,555.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 26 Jul 2027 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$50,001.00 |
| COE Rebate Amount: | \$36,600.00 |
| Total Rebate Amount: | \$72,155.00 |

The information contained herein is correct as at 30 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/03/2020 16:26
Date Of Accident 25/03/2020 11:45
Exact Location Of Accident SENGKANG E ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR2000A
Insured/Policyholder
Name Of Registered Owner LOW LEE TICK
NRIC No SXXXX584J
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-83224896
Alternative Phone No OTHERS-83224896

Vehicle Particulars

Manufacturer TOYOTA
Model VELLFIRE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number SI19V07979/VPE/R01
Cover Note Number

Driver

Name of Driver LOW LEE TICK
NRIC No SXXXX584J
Date Of Birth 31/07/1974
Occupation OUTDOOR
Date Of Driving Pass 18/09/2003
Driving Experience 16 YEARS AND 6 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83224896
Fax Number
Contact Number OTHERS-83224896
EMail Address NOEMAIL

| | |
|---|----------------------------|
| Address | 31 YISHUN STREET 51 #04-23 |
| Postcode | 767990 |
| Was driver an employee of the Insured's Company | NO |
| No. Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-------------------------------|
| Type Of Accident | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

| | |
|---|-------------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | WITH WORKSHOP - HC AUTO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1


| | |
|-------------------------------------|----------------------|
| Vehicle Registration Number | SGZ3090A |
| Vehicle Make/Model/Colour | HONDA CROSSROAD |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | NUR ZULFAKAR BIN ABU |
| NRIC/Passport Number | SXXXX802Z |
| Contact Number | 93297214 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:

25 MAR 2020


Driver's Signature

(If driver is not the policyholder)

Date & Time:

25 MAR 2020



Reporting Centre Personnel's Signature

Name:

Jenny Lim

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/03/2020 at about 1145 hours, while I was driving my motor vehicle A SRJ000A along Sengkang E Road at the third lane from my right, keeping within my lane. Green light on my favour. Suddenly I felt an impact from my right. I realised that was motor vehicle B SGE 3090A which was driving on my right cut into my lane and his front, left portion hit onto the rear right portion of my motor vehicle A SRJ000A. NO one was injured. I'm lodging this report to claim against the insurer of SGE 3090A.

Lick

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Lick

Policyholder's Signature

Date & Time:

25 MAR 2020

Lick

Driver's Signature

(If driver is not the policyholder)

Date & Time:

25 MAR 2020

u

Reporting Centre Personnel's Signature

Name:

Jenny Lim

NRIC/FIN No.:

H C AUTO PTE L

Block 20 Sector A Sin Ming Ind. Est. # 01-20 Singapore 575678

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

Date : 25 / 03 / 2020

ESTIMATE COSTS OF REPAIR

Mr Low Lee Tick

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SLR 2000 A - Toyota Vellfire 2.5

Accident date : 25 / 03 / 2020

Not Withheld

11 Days

Resuming After Paint

9 days

| Quantity | Descriptions | Amounts | |
|----------|--|--------------------------------|---|
| | | <i>CRMS</i> \$ 2,240.00 | ✓ |
| 1 | 1 pc rear bumper | \$ <i>br</i> 176.00 | ✓ |
| 2 | 1 pc o/s rear bumper side retainer 1 | \$ <i>br</i> 176.00 | ✓ |
| 3 | 1 pc o/s rear bumper side retainer 2 | <i>Bul</i> \$ <i>br</i> 368.00 | ✓ |
| 4 | 1 pc o/s rear bumper side cover | \$ <i>br</i> 128.00 | ✓ |
| 5 | 1 pc o/s rear bumper reflector | \$ <i>br</i> 64.00 | X |
| 6 | 1 pc rear bumper tow cover | <i>gasp</i> \$ 438.75 | X |
| 7 | 1 pc o/s rear bumper top cover | \$ <i>br</i> 9.60 | ✓ |
| 8 | 2 pcs rear bumper clip 1 @ 4.80 | \$ <i>br</i> 448.00 | X |
| 9 | 1 pc rear weather strip | <i>br</i> \$ 1,920.00 | ✓ |
| 10 | 1 pc o/s rear fender | \$ <i>br</i> 1,644.00 | X |
| 11 | 1 pc o/s rear fender inner garnish | \$ <i>br</i> 108.00 | ✓ |
| 12 | 1 pc o/s rear fender quarter glass molding | \$ <i>br</i> 352.00 | ✓ |
| 13 | 1 pc o/s rear fender low protector | <i>br</i> \$ 3,040.00 | ✓ |
| 14 | 1 pc o/s rear sliding door | \$ <i>br</i> 1,120.00 | X |
| 15 | 1 pc o/s rear sliding door inner lock | <i>bill/warp</i> \$ 944.00 | ✓ |
| 16 | 1 pc o/s rear sliding door protector | \$ <i>br</i> 528.00 | X |
| 17 | 1 pc o/s rear sliding door rubber | \$ <i>br</i> 304.00 | ? |
| 18 | 1 pc o/s rear sliding door regulate gear | \$ <i>br</i> 896.00 | ? |
| 19 | 1 pc o/s rear sliding door regulate gear motor | \$ <i>br</i> 480.00 | X |
| 20 | 1 pc o/s rear sliding door centre rail | \$ 2,640.00 | ? |
| 21 | 1 pc o/s rear sliding door auto motor | \$ <i>br</i> 320.00 | X |
| 22 | 1 pc o/s rear sliding door glass outer molding | \$ <i>br</i> 1,216.00 | X |
| 23 | 1 pc o/s rear sliding door inner trim | \$ <i>br</i> 144.00 | X |
| 24 | 1 pc o/s rear sliding door top roller | \$ 224.00 | ? |
| 25 | 1 pc o/s rear sliding door bottom roller | \$ <i>br</i> 256.00 | X |
| 26 | 1 pc o/s rear sliding door centre roller | \$ 416.00 | ? |
| 27 | 2 pcs o/s rear sliding door rail 1 @ 208.00 (top & bottom) | \$ 1,280.00 | ? |
| 28 | 2 pcs rear lower arm 1 @ 640.00 | \$ 640.00 | ? |
| 29 | 1 pc o/s rear upper arm | \$ 22,568.35 | ? |
| | Balance C/FD | | |

H C AUTO PTE LTD

Block 20 Sector A Sin Ming Ind. Est. # 01-20 Singapore 575678

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

Balance B/FD (SLR 2000 A)

\$ 22,568.35

- | | | |
|----|------|------------------------------------|
| 30 | 1 pc | o/s rear knuckle arm |
| 31 | 1 pc | o/s rear knuckle arm bearing |
| 32 | 1 pc | o/s rear trailing arm |
| 33 | 1 pc | o/s rear wheel hub bearing |
| 34 | 1 pc | o/s rear shock absorber |
| 35 | 1 pc | o/s rear bumper lower side garnish |

| | | |
|----|-----------|---|
| \$ | 1,056.00 | ? |
| \$ | 637.00 | ? |
| \$ | 480.00 | X |
| \$ | 960.00 | ? |
| \$ | 256.00 | X |
| \$ | 83.50 | ✓ |
| \$ | 26,040.85 | |
| \$ | 6,510.21 | |
| \$ | 19,530.64 | |

Less 25%

- | | | |
|----|-------|---|
| 36 | 1 pc | rear bumper lower lip |
| 37 | 1 set | rear bumper reverse sensor |
| 38 | 1 pc | o/s rear quarter glass inner seal |
| 39 | 1 pc | o/s rear quarter glass inner gum |
| 40 | 1 pc | o/s rear wheel rim P-1 |
| 41 | 1 pc | o/s rear wheel tyre (Michelin 225/35ZR20) |
| 42 | 1 pc | rear end panel seal |

| | | | |
|-------------|-----------|----|------|
| CNT \$ | 2,500.00 | sn | ✓ |
| sn \$ | 2,048.00 | sn | X |
| \$ | 60.00 | sn | 30sn |
| \$ | 60.00 | sn | 40sn |
| Poll Sur \$ | 2,800.00 | sn | ✓ |
| \$ | 580.00 | sn | X |
| \$ | 256.00 | sn | 30sn |
| \$ | 27,834.64 | | |

- Labour charges
- To putty and spray painting
- To check wiring
- To re-seal anti rust
- Remove and refix rear undercarriage
- To check wheel alignment
- To transfer o/s rear door
- Remove and refix rear quarter glass
- Remove and refix reverse sensor
- Remove and refix cushion seat, garnish, carpet & etc.

| | | |
|----|----------|-------|
| \$ | 2,000.00 | 900l |
| \$ | 1,600.00 | 1200l |
| \$ | 160.00 | 20l |
| \$ | 250.00 | 60l |
| \$ | 450.00 | ? |
| \$ | 100.00 | 60l |
| \$ | 160.00 | 80l |
| \$ | 320.00 | 80l |
| \$ | 100.00 | 50l |
| \$ | 450.00 | 120l |

Plus : 7% GST

Grand total

\$ 33,424.64

\$ 2,339.72

\$ 35,764.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R037291
SLR2000A
17
27.3.20 10:55



Factory Japan 2019.0.2 : Toyota : Alphard / Vellfire : H30 Series : AGH30W

Front : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°16' | -0°16' | -1°00' 0°30' |
| 6°08' | 6°08' | 5°10' 6°40' |
| -0°28' | -0°29' | -0°02' 0°08' |
| 11°46' | 11°46' | 10°50' 12°20' |
| 11°30' | 11°30' | 9°50' 12°50' |
| | | |

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°13' | -0°13' | -1°00' 0°30' |
| 6°20' | 6°20' | 5°10' 6°40' |
| -0°24' | -0°25' | -0°02' 0°08' |
| 11°31' | 11°31' | 10°50' 12°20' |
| 11°18' | 11°18' | 9°50' 12°50' |
| | | |

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°03' | -0°02' | -0°45' 0°45' |
| -0°12' | -0°12' | -0°45' 0°45' |
| 0°15' | 0°14' | |
| -0°53' | -0°53' | -0°05' 0°15' |
| | | |

Rear : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°13' | -1°13' | -1°30' 0°00' |
| 0°03' | 0°03' | 0°03' 0°12' |

Camber
Toe

Rear : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -3°25' | -3°25' | -1°30' 0°00' |
| -0°22' | -0°23' | 0°03' 0°12' |

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 2°12' | 2°12' | -0°45' 0°45' |
| -0°19' | -0°20' | 0°05' 0°25' |
| 0°13' | 0°13' | |
| 0mm | 0mm | |