



Your Ref: MSC/V/18-000932

Date: 06th April 2020

Our Ref: CS1/MSG20004632/R1tf3e2

M/s MSIG Insurance (Singapore) Pte Ltd

4 Shenton Way #21-01

SGX Centre

Singapore 068807

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFQ 669K

INSURED VEHICLE: GBA 6041M

ACCIDENT DATE: 03/07/2018

We thank you for your instruction on 27/03/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFQ 669K from M/s Prominent Appraiser Services Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SFQ 669K.
- c) Colour damaged vehicle photographs of SFQ 669K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFQ 669K
Make & Model	: Nissan GT-R 3.8 A
Year of Registration	: 2008
Chassis Number	: R35003587
Engine Capacity	: 3799 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.