



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/04/2020

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SG1735U
Case Reference Number	BUS/03/20/7030
Registration Date	3/10/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Zhang Wei
Type of Accident	Others
Accident Date and Time	26/3/2020 11:00 AM
Accident Reported Date and Time	26/3/2020 2:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106390
Special Instruction to ARC,if any	LEFT REAR BODY PANEL SCRATCHED AND BUMPER SLIGHT DENTED
Prepared Date and Time	26/3/2020 4:36 PM
Chassis Number	WMAA22ZZ7F7002908
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$602.00	\$528.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	(\$211.60)
<b>TOTAL COST</b>	<b>\$1,397.00</b>	<b>\$846.40</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$850.00</b>
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoon Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	26/03/2020 4:42 PM	30/03/2020 2:38 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/04/2020

User ID : CatherineLee

### Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
<b>Total Labour</b>	<b>\$795.00</b>	<b>\$530.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	\$528.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$602.00</b>	<b>\$528.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$211.60)
<b>Total Other Costs</b>	<b>\$0.00</b>	<b>(\$211.60)</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010001	BODY LH	A01001-CW557	PANEL,SIDE:L7,FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair
6010004	BODY LH	A01001-CW560	PANEL,SIDE:L10,W FRAME,FOR MAN A22 BUS	1.00	\$980.40	100.00	\$0.00	Repair	Repair
6010005	BODY LH	A01001-CW561	PANEL,SIDE:L11,FOR MAN A22 BUS	1.00	\$1,092.50	100.00	\$0.00	Repair	Repair
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
<b>Total</b>					<b>\$3,378.30</b>		<b>\$0.00</b>		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									