





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/05/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB207G
Case Reference Number	BUS/03/20/5027
Registration Date	30/11/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Yang Dong
Type of Accident	Side Swipe
Accident Date and Time	27/3/2020 5:15 PM
Accident Reported Date and Time	27/3/2020 8:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106396
Special Instruction to ARC,if any	SMB207G-FRONT RIGHT PORTION SMK1255M (TP) INSURED WITH NTUC
Prepared Date and Time	31/3/2020 9:06 AM
Chassis Number	WMAA22ZZXB7001181
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$2,507.54	\$2,507.54
Total Other Cost	\$0.00	(\$229.20)
TOTAL COST	\$4,088.54	\$3,424.34
Lump Sum Total	\$0.00	\$3,400.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	steve chen
ARC / Surveyor Sign Off Date	31/03/2020 9:13 AM	31/03/2020 2:21 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/05/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00				\$530.00		
Total Labour			\$795.00				\$530.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$786.00				\$616.00		
Total Spray Painting & Panel Beating			\$786.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$229.20)		
Total Other Costs			\$0.00				(\$229.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010305	VE	81.25101-6540	HEADLAMP,RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010307	VE	81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace
Total					\$3,482.70		\$3,134.43		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									