

22/03/2020

ASS. REC. BY:

REF: CS/TMI20004761/Ftd3

Special Instruction:

Surveyor: RAM  
Menmen

ASSIGNMENT (Office)

From (Person): Dillen Genthilan

of TMI

Date/Time: 1/4/2020 12:14pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 3333 J

Insured:

SJC 5441T

at Workshop m/s

Comfort Delgro

Tel:

62148300

of

59 loyang Drive

Policy No: MT000878

Claim No: M2002246

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 31/03/2020

CA / REV / REP. / REV 24 HRS <sup>(up)</sup>

H.O.D. Endorsement:

Date/Time: 12:31pm 1/4/2020

Person Contacted:

jumani

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	SHC 3333 J - CC1/III.18016096/ Ngl/352	D.O.A: 1/4/2018
	SJC 5441T - X	

ASS. REC. BY: RAW

REF: CS/TMI 20004761/ P4D3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC3333J Yr Regn: 01/02/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai Ioniq C.C. 1580

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 171968 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCB8S1CVKUI34060

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DAWANG 1

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 8 mm

L/Bal. 7 mm L/Bal. 8 mm

D.O.A. 31/03/2020 D.O.I. 1/04/2020

Survey held at Comfortdelgro (Layang)

Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

TMI  
PIP

Date / Time	Action / Instruction
	NO Policy
	P/P: \$ 2662/= with 2 repair days
	confirm on 24/4/2020 with LKE

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format: \_\_\_\_\_

Lump Sum / L/S: (\$ \_\_\_\_\_)

Our Job Ref No 305391302

Date : 23.04.20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHC3333J CTPL

31.03.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJC5441T

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,611.00

(b) Labour Charges \$1,051.00

**Total for Part-By-Part Repair Cost** \$2,662.00

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost** \_\_\_\_\_


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM KWOK ENG

Name : RAM

Tel : 62148316

Date : 24/4/2020

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305391302  
 REGN NO : SHC3333J  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 01.02.2019  
 DATE/TIME IN : 31.03.2020 14:10  
 ACCIDENT DATE : 31.03.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1 L	588.80	20.00	471.04	BVC	
0002	04-01-0104-3913-G	IONIQ EMBLEM-BLUE DRIVE R	1 N	26.60	2.00-	26.60	nc	
0003	04-01-0104-2538-G	IONIQV2 MIRROR ASSY-OUTSI	1 L	1,391.70	20.00	1,113.36	Br	
							SUB-TOTAL	: 1,611.00

## JOB NATURE

0000	L	MERIMEN CHARGE				11.00		
0001	L	PANEL BEATING (repair frt WS pillar R				480.00		
0002	23-502	SPRAYPAINT ON AFFECTED AREA				480.00		
0003	17-01	CHECK ALL LIGHTING				30.00		
0004	20-00	TUFF COAT ON AFFECTED PARTS.				50.00		
							SUB-TOTAL	: 1,051.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	31/03/2020
Vehicle Reg. No.:	<b>SHC3333J</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/02/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU167569	Chassis No:	KMHC851CVKU134060
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	1,685.73
Miscellaneous Items	11.00
Labour	1,150.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$\$)</b>	<b>2,846.73</b>
<b>+ GST 7.00% (\$\$)</b>	<b>199.27</b>
<b>Nett Amount (\$\$)</b>	<b>3,046.00</b>

**This claim is handled by: LIM KWOK ENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 31 Mar 2020)**Parts:** 192    HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's    (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3333J/31/03/2020 17:43**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER RH <del>Blue</del> <i>Blue</i>	20.00	0.00	*588.80 FL
2	1		*FRT FENDER EMBLEM -BLUE DRIVE RH <i>nee</i>	0.00	0.00	*26.60 F
3	1		*RR VIEW MIRROR ASSY RH <i>Br</i>	20.00	0.00	*1,391.36 FL
4	1		*FRT DOOR COMFORTDELGRO LOGO RH <i>xwn</i>	0.00	0.00	*75.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,081.76</b>
<b>- List Item Discount on L Items (S\$)</b>	<b>396.03</b>
<b>Total Parts (S\$)</b>	<b>1,685.73</b>

ComfortDelGro Engineering Pte Ltd/SHC3333J/31/03/2020 17:43. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING ( repair frt WS pillar Rh )	New	\$480 500.00
2	SPRAY PAINTING CHARGE	New	\$480 550.00
3	WIRING CHARGE	New	\$30 50.00
4	TUFF KOTE	New	\$ 50.00
<b>Gross Labour Cost (S\$)</b>			<b>1,150.00</b>

ComfortDelGro Engineering Pte Ltd/SHC3333J/31/03/2020 17:43. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram (142)  
 1/04/2020 1200hrs  
 Parasuram@lkkauto.com  
 87622728  
 (P/P)  
 Bef paint photo  
~~and after repair photo~~  
 28 repair days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	31/03/2020 15:10
Date Of Accident	31/03/2020 11:00
Exact Location Of Accident	ALONG LOYANG AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC3333J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	LEE KIM ENG
NRIC No	SXXXX371Z
Date Of Birth	14/11/1970
Occupation	OUTDOOR
Date Of Driving Pass	12/04/1991
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97428155
Fax Number	
Contact Number	
EEmail Address	LEE_KIMENG@HOTMAIL.COM

Address	479 02-437 PASIR RIS DRIVE 4
Postcode	510479
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES N NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC5441T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOW YOONG PING
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

LEFT WING MIRRIR

No. Of Passenger (Including Driver)


**DETAILS OF INJURED PERSON 1**

Name	LEE KIM ENG
Approximate Age	50
Injuries Sustain	RIGHT WRIST AND SHOULDER PAIN
Injured person in which vehicle?	SHC3333J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

CLAMPINES

A = SAC 3333J

B = SJC 5441T  
(TOYOTA)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LOYANG AVE

Statement as per Police Report @

T1 20200331/2040

DECLARATION

We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 19229J21R

Olivia Wendy

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: 31 MAR 2020



**SINGAPORE  
POLICE FORCE**



T/20200331/2040

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

1 of 3

Report No. T/20200331/2040

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 31/03/2020 12:54		Vide Report No.:	Station Diary No.: 13
<b>Informant's Particulars</b>			
Name of Informant: LEE KIM ENG		Address: APT BLK 479 PASIR RIS DRIVE 4 #02-437 SINGAPORE 510479	
ID Type / ID No.: NRIC NO / S7041371Z		Contact No.:	Mobile: 97428155
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 49	Date of Birth: 14/11/1970	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class:	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 31/03/2020 11:00	Type of Location:
Location: Along Road 1 PASIR RIS DRIVE 1 LOYANG AVENUE Pasir ris dr 1 towards airport near Loyang avenue				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC3333J	Car					1
SJC5441T	Car					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20200331/2040

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

2 of 3

Report No. T/20200331/2040

## CONTINUATION OF REPORT

Driver			
Name	LEE KIM ENG	ID No.	S7041371Z
Related Vehicle	SHC3333J (Car)	Contact No.	97428155
Hospital/Clinic	ANSAR CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	31/03/2020	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	LOW YOONG PING	ID No.	S9603850Z
Related Vehicle	SJC5441T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned date, time and location I was driving my vehicle turning into Loyang ave from third lane of pasir ris dr 1 and while on Loyang avenue, the other vehicle from second lane attempt to enter into my lane and hit with the right of my vehicle causing damage to the front right bumper, side mirror and parts of the door. The said vehicle did not stop even I horned him, I followed him all the way to tampines ave 7 ESSO before he stopped, when I questioned him he said that he was stopping for me at this ESSO.



**SINGAPORE  
POLICE FORCE**



T/20200331/2040

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

3 of 3



Report No. T/20200331/2040





**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 2 GAN JIAN CAI, DARREN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 31/03/2020 12:54
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:  
Authentication Stamp NP168	



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

### Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

### Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

**Total Rebate Amount:**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Apr 2020

Company

821R

SHC3333J

No

02 Apr 2020

HYUNDAI

AE IONIQ HEV 1.6 DCT

Blue

2018

G4LEJU167569

KMHC851CVKU134060

103.6 kW (138 bhp)

\$25,131.00

01 Feb 2019

01 Feb 2019

0

\$12,184.00

Yes

31 Jan 2027

\$9,138.00

31 Jan 2027

A - Car up to 1600cc & 97kW (130bhp)

8

\$20,582.00

\$17,566.00

**\$26,704.00**

OK