15/5/2010

INS. CASE OWNER:

# CC3/FCI20004773/Kga3

LKK:

IDAC:

## ASSIGNMENT

Surveyor: KENNETH DOI: 31/03/2020 Date / Time : 31/03/2020

Registered in Merimen: —

**Pre-assign / CCU / FTE**

Insured Vehicle No. : SH 8037X Claim No. :

Name of Insured : COMFORT TRANSPORTATION PTE LTD Policy No. :

Insured Tel No. : HP: Make / Model :

**Excess Sec II :S$** D.O.A : 29/03/2020 21:50 Place of Accident : JALAN BESAR > DESKER ROAD

Is driver the owner? ( YES / NO ) Nature of Accident :

If **NO**, Driver Name / Age : OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO ) Insured Liability : % **Final ? Yes / No**

SHF 518Y → → →



INSRS:
WSP: TRANS-CAB
Tel : AUTO
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

INSRS:
WSP:
Tel :
Liability :
RMKS:

| Date/ Time | |
|---|---|
| | SHF 518Y - CC3/AXA14023438/Kwy3u2 ; 13/12/2014<br>CC3/FCI15014971/Kvbc2 ; 02/06/2015<br>CC3/FCI16011513/Kvbq2 ; 20/06/2016<br>CC3/III18020714/Kea3q2 ; 07/11/2018 |
| | SH 8037X - X |

| STAGE | DATE / PIC |
|---|---|
| Non-Reporting ltr (1st): | |
| Non-Reporting ltr (2nd): | |
| Non-Reporting ltr (Final): | |
| Notification ltr (if non-pickup): | |
| Call OI: | |
| After call ltr to OI: | |

| Documentation Check List: | Handler | Typist |
|---|---|---|
| Notification ltr (if non-pickup) | ☐ | ☐ |
| After call ltr to OI: | ☐ | ☐ |
| Authorisation To Act: | ☐ | ☐ |
| Release Voucher: | ☐ | ☐ |
| Final Repair Bill: | ☐ | ☐ |
| Car Rental Invoice: | ☐ | ☐ |
| Towing Invoice | ☐ | ☐ |
| LTA / GIA : | ☐ | ☐ |
| Medical Bill: | ☐ | ☐ |
| PIR: | ☐ | ☐ |
| Mandate/Reject Instruction: | ☐ | ☐ |
| LOD | ☐ | ☐ |
| Payment Breakdown Form: | | ☐ |
| Post-Repair Photos: | ☐ | ☐ |
| Others: | ☐ | ☐ |

| | | | |
|---|---|---|---|
| **PRELIMINARY ADVICE** | Date/Time: | Sent By: | |
| **FINALIZATION** | Date/Time: | Confirm with: | Confirm by: |
| Repair Cost: | S$ | ( days) Reduction: % | Email ☐ Call ☐ |
| **FINAL SETTLEMENT** | Date/Time: | Confirm with | Email ☐ Call ☐ |
| Final Liability: | % | (Agreed / Assessed) BOLA S/N No. : | If NO or B 28, Ass. Lia : |
| Repair Cost: | S$ | | |
| Loss of Rental (LOR): | S$ | ( days) | |
| Loss of Use (LOU): | S$ | ($ x days) | |
| Loss of Income (LOI): | S$ | ($ x days) | |
| LOR only ☐ LOU only ☐ | LOR + LOU ☐ | LOR + LOI ☐ [**Tick only one**] | |
| GIA/LTA Search | S$ | | |
| Medical: | S$ | | 1) Claim status: Normal/Reject/Private Settle |
| Disbursement: | S$ | (e.g. Tow/ Independent ) | 2) Report Format: |
| Legal Cost | S$ | | 3) Survey fee: |
| **Total:** | **S$** | **Global Sum S$:** | |
| **FINAL PAYMENT** | Date/Time: | Confirm with: | Email ☐ Call ☐ |
| Payee 1: | S$ | Name 1: | |
| Payee 2: (Strike if N.A.) | S$ | Name 2: | |
| Payee 3: (Strike if N.A.) | S$ | Name 3: | |

ASS. REC. BY: Kenneth | REF: FCZ1

# ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHH 5184 Yr Regn: 06/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or A

Make: Renault Latitude c.c 1995

Colour M.White/Red A/C: Insured / Std / NI / NA

Sp.Reading 509433 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 278263

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: Sailun 215/60R16

R: Goth

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 9 mm | R/Bal. | 7 mm |
| L/Bal. | 9 mm | L/Bal. | 7 mm |
| D.O.A. | 29/3/20 | D.O.I. | 31/3/2020 |

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rr

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| / | |
| | L/Sup @ 3700h |

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Report Format :

Lump Sum / I.B.I: ($ _____)

Survey Fee: _____

Transportation: _____ $ + RS. _____ SI

Parking _____

Others _____

TOTAL _____